

**REPORT OF CHANNEL CONDITIONS
100 TO 400 FEET WIDE
(ER 1130-2-520)**

PAGE 1 OF 1 PAGE(S)

DATE: **April 12, 2012**

TO:	FROM:
-----	-------

RIVER/HARBOR NAME AND STATE: Wareham Harbor, Wareham, Massachusetts Dwg. No. WM-H 14, Sheets 1-4 of 4, Dated 12 April 2012	MINIMUM DEPTHS IN CHANNEL ENTERING FROM SEAWARD
---	--

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH Nautical (miles)	MLLW DEPTH (feet)			
<u>CONDITION SURVEY</u>							
<u>9-Foot Channel</u>							
From about 430' seaward of Buoy RN-10, upstream about 7700' about 190' seaward of Buoy RN-20	3/09	125	1.27	9.0	(1) 8.8	9.0	9.0
Thence upstream 3400' to vicinity of Buoy RN-28	3/09	125 to 250 to 100	0.56	9.0	3.8	3.7	4.9
Thence upstream 1567' to The upstream limit of Federal Navigation Project.	3/09	100	0.26	9.0	8.7	6.2	5.3

GENERAL NOTE: The information shown on this sheet(s) represents the results of surveys made on the dates indicated and can only be considered as indicating the general conditions existing at that time.

FOOT NOTES:

(1). Except for shoaling to 6.7' within 5' of west channel limit.