QUALITY ASSURANCE REPORT (QAR)							REPORT NUMBER 499				Page 1 of 1				
DAILY LOG OF CONSTRUCTION								DATE 30 Apr 2020 - Thursday			v				
PROJECT Durbam Mea	dows Waterline	Remed	ial Desig	'n						CONTRAC		/IBER	,		
Durham Meadows Waterline Remedial Design CONTRACTOR							WEATHE	W912WJ19C0002							
Ludlow Constru	uction Co., Inc.									Tempe	rature N	ed Critical [/lin 47 °F M pitation 20 [/ax 56		
	PORTION OF S	CHEDU	LED DAY	SUITABLE	FOR OP	ERATIONS				Т	EMPE	RATURE			WIND
STRUCTURAL EXC	CA- BORROW E VATION	XCA-	EMBANK	MENT	CONCR	ETE	STRU	CTURE		MINIMUM		MAXIMUI	N		
	0 %	0 %		0 %		0 %			0 %		47 °F		56 °F		20 MPH
HAS ANYT	HING DEVELOPE		IE WORK	WHICH M	IGHT	XN	10					24 HOUR I			
	CHANGE ORDER					Π Y	′ES (Ex	plain)		INCHES		0.35		ENDING	Ν
	NUMP				OYEES					RIVER			RSTA	GE	
SUPERVISORY	OFFICE	LAYO		INSPECT		TOTAL		LABOR		FEET				TIME	
1	0		0		2		3		0			0.0			Ν
· · · ·		DR'S EM		;		NUMBE	-	HIFTS		<u> </u>	X			3	
SUPERVISORY	SKILLED	LABOR	RERS	TOTAL		FROM	Т	0	FF	ROM	TO	-	FROM	Л	TO
0	0		0		0	07	700	1530	м		м	M	1	М	N
	ch a list of the follo										ation of	contractor	personr	nel onsite.	
	TE: if the contracto	or's Quali	ty Control	Report (Q	CR) conta	ins the infor	mation	it need no	t be rep	eated.					
	Subcontractor &	& Area	of Respo	onsibility	for Wor	k:		Ur	nresolv	ed Issue: I	No	Shi	ft: 1		
Robert Chr															
	olves installing v	vater ma	ain from	a new Mic	ddletown	Water Ta	nk into	Durham	and ty	ing into ho	mes &	business	es:		
Subcontrac Subcontrac		t Traffic	Control	- 0		QC Jerry B	randor	1							
Work Perfor	med Today:							Ur	nresolv	ed Issue: I	No	Shi	ft: 1		
Billy's crew they were a will be insta	k Site and Acces continued to ins able to install 20 alled. Hoping to	stall the 6 feet. ⊺ get a pi	12" RCF The ran o pe delive	out of pipe ery tomorr	e, for the ow.	remainder	of the	day they	cleane	ed and mo	ved m	aterial clo	ser to v	where it	
Steve Wrig remainder Continued Contractor the excava	n Roads: 2 State ht for CT DOT n of the day this c installing the 16 encountered lec tor. ction testing was	nade the rew wor " Restra dge fron	e call to s rked in th ained wat n station	shut the c e yard or er from s 174+23 to	rew dow ganizing tation 17 o 174+43	n due to th and puttin 4+23 to 17 8 equaling	ne rain g fitting 74+43. 14.81	at 1000, gs togeth	by 115 er.	0 the crew	was o	off of the r	oad. F	or the	on
1 - Ludlow	employee contir	nued pre	essurizin	g the new	water m	nain.									
Pickett lane No other w No deliveri	ork was perform	ned toda	ay.												
2. Fire Hyd 3. Police - : 4. Illuminat 5. Sawcut 6. Sawcut 7. 16" Rest 8. 16" Non 9. 20 inch 10. 20 inch 11. Ledge 12. Trailer	rained Pipe - 0 Irant Assembly - 2 State Police ed Signs - yes Town Roads - 0 State Roads - 4 trained Pipe - 20 -Restrained Pipe oipe at access ro pipe Restrained Removal - Yes, cleaned - Not to Gate Valve - 0) Feet 0 Feet) Feet e - 0 Fee oad - 0 d - NA 14.81 C		ds											

14. Bank Run Gravel- 0 CY 15. Manual Drain Assembly - 0 16. 16x16x8 TEE - 0 17. 16x16x16 TEE - 0								
17. 16x16x16 TEE - 0 18. 16" Butterfly valve - 0 19. 1" Corporation - 0 20. 1" Curb stop - 0								
21. 1" Cooper pipe - 0								
Results of QA Inspections and Tests, Deficiencies Observed, Act	tions Taken: Unresolved Issue: No	Shift: 1						
Robert Christie Observed the installation of the 16" Restrained pipe. At approximate placed in the bottom of the excavation followed by 6" of 3/4" stone. installed the pipe and placed 12"of sand over the pipe. The rest of the lifts were bank run placed 4" of hot mix asphalt (HMA).	Then the stone was covered with fabric. They the	nen placed 3" of sand,						
Compaction Tests today - Not required today due to only installing 2	20 feet of pipe.							
No water was encountered today.								
	Drove by the storage yard twice during my shift. Observation made both times was no material was spilled on the ground and no damage to asphalt. The catch basin did have sediment control fabric in it and did not appear to be clogged.							
Observations made at the tank site location were of the installation slope of the pipe the contractor used a laser level.	of the 12" reinforced concrete pipe (RCP). To a	chieve the proper						
Verbal Instructions Given to Contractor:	Unresolved Issue: No	Shift: 1						
Robert Christie Spoke to SSHO - Rob to remind the crew working on state road 17 hard hat.	that when an operator gets out of the machine t	hey need to wear a						
Spoke to QC - Jerry about my concerns with moisture content from compaction tests. Also concerns with working on the state road with	h the rain.							
Miscellaneous Remarks and Visitors to Project:	Unresolved Issue: No	Shift: 1						
Robert Christie Jerry - QC Rob P - SSHO John Pio - Superintendent Mike Pio - onsite USACE - Kurt Mintell AECOM - Bill was onsite covering for Joel Mike Cunningham Steve - JTC Consulting Miscellaneous Remarks and Visitors to Project:	Unresolved Issue: No	Shift: 1						
Robert Christie Water encountered while excavating: No water was encountered today.								
PR Comments, encounters or issues: Contractor has agreed to move the piles of material away from the r	neighbors property to a different location here a	t the office/yard.						
CT DOT onsite or communication: No Safety:	Unresolved Issue: No	Shift: 1						
Robert Christie Noted portable hand wash station on back of tool truck, cleaning supplies nitrile gloves, face masks. Workers fill out daily forms indicating they are not demonstrating any symptoms of COVID 19 and turning into SSHO.								
Daily Safety Inspections: 1. Noted proper PPE while cutting Steel pipe with cut off saw. 2. Traffic Control: 2 State Police and cones on 17 - while installing the new water line 3. Discussed situational awareness while working around heavy equipment, and while allowing residents to use the shared driveway while under construction 4. Situational awareness not to work in close proximity to each other (COVID PREVENTION) 5. Trench box being used for all excavations while working in trench.								
QA DEFICIENCY (Describe QA Deficiency items issued, verify QA Deficiency items reported corrected by contractor) The following QA Deficiency items were issued today:								
QA Deficiency Item Location Description	3	Status						

QA-00003	Tank site	Observed a Ludlow employee working at the tank access road enter a catch basin which is a confined space. I told the foreman Billy to get the employee out. A few minutes later I witnessed the employee back in the catch basin. I then directed the employee out of the hole myself. UASCE Kurt then called the SSHO Rob to inform him of what had happened and told Rob to go over confined space with the crew. Both times the employee entered the catch basin it was witnessed by USACE Bob and Kurt that the employee's body was fully in the catch basin.	QA Concurs Corrected
QA-00004	Tank Site	The silt fence that was identified during the SWPP inspection with the SSHO/QC on 22 Apr 2020 as needing to be repaired hasn't been corrected.	QA Concurs Corrected

QA REPRESENTATIVE'S SIGNATURE	DATE	RE/PROJECT ENGR'S INITIALS	DATE