	QUALITY AS			REPORT NUMBE 653	ir ————	Page	e 1 of 0						
	DAILI L		71 OON	1311100	, 11014					DATE 01 Oct 2020 -	- Thursday		
PROJECT										CONTRACT NUM			
Durham Mea	adows Waterline I	Remed	lial Desig	jn						W912WJ19C	0002		
	ruction Co., Inc.									Weather Cause	/lin 48 °F Max 70) °F	
	PORTION OF SO	CHEDUI	LED DAY	SUITABLE	FOR OP	ERATIONS				TEMPER	RATURE		WIND
STRUCTURAL EXC VATION	CA- BORROW EX	CA-	EMBANK	MENT	CONCR	ETE	STRU	CTURE		MINIMUM	MAXIMUM		
	I	100 %		100 %		100 %		10	00 %	48 °F	70 °F		0 MPH
	HING DEVELOPED A CHANGE ORDER				GHT	X No	O ES (Exp	plain)		INCHES	24 HOUR PREC	ENDING	М
				MENT EMP							RIVER ST		
SUPERVISORY	OFFICE	LAYOU	JT	INSPECT	ION	TOTAL		LABOR		FEET		TIME	
1	0		0		1		2		0		0.0		М
NUMBER SUPERVISORY	R OF CONTRACTO	R'S EMI		TOTAL		NUMBER FROM	R OF S		T==	1 <u>X</u>	2	3 M I	ТО
		LABOI		IOTAL									
0 Δtts	0 ach a list of the follo	wing (a	0 Major ite	ems of equi	0 nment eith			1530 N		M description of	contractor person	M	М
NO ⁻	TE: if the contractor										Sommation person	inci onsite.	
QA NARRAT								Llove		ad Jaguar Na	Chiff, 1		
	med Today:							Unre	SOIVE	ed Issue: No	Shift: 1		
	ll Main Street Wate s today - no crew			k today									
	17: awcutting on 17 - lagger (ludlow)	noted I	Police or	nsite for tra	affic cont	trol.							
between th	- Installing prestr ne layout marks. I ns required in the	Last mi	inute noti	ification th	at DN Ta	ank would l							
KTR is doi issues. ITEMS: 114: 695.! 116: 228 S 117: 228 S 119: 10.64	t Paving on 17 - s ng the permanen 5 FEET OF STAT 6Q YARDS STA 1 6Q YARDS OF 3 5 Onsite for compa	t paving FE SAW 143 TO 143 TO SLIVEF	W CUT 0 146+30 0 146+30 R SLAB	t of Linos -	- noted a	ccess is be	əing m	aintained ir	า and	out of Linos with	n Steel road pla	ates. No	
Results of C	QA Inspections a	nd Tes	sts, Defic	ciencies (Observe	d, Actions	Taker	n: Unre	solve	ed Issue: No	Shift: 1		
													I
	with grass growin reseed these area					ed. The gra	ass is ı	not growing	g due	to drought cond	itions. Contrac	tor has	
tank contra methods to it did not no lack of cyli requiremen	e prestressed wire actor installed sho o save time. There eed to be tested onders. I will close ints. uctions Given to	otcrete e was r due to i the de	on the to no cylind it being t eficiency	op section lers taken the same r	of the ta from the mix that v	ink (over the one concr was used the	ne pres rete tru he oth	stressed wir lick that sho er day. I an blaced and	re ins owed n issu would	stalled)- this is the up. I discussed t uing a deficiency	e contractors mathis with QCM - for this placem	neans and - he told me	e
								01110	. 551 7 (10000. 140	Jimi. I		ŀ

Kurt Mintell

Items discussed today:

Jerry CQC & Jon Pio - storm drains must be covered when saw cutting is happening near the storm drain. Placing fabric over the top of the storm drain is not acceptable.

Directed Contractor to install sediment sock at STA 164+30 permanent paving. (Jon Pio)

With Rob Peddicord SSHO- better housekeeping ie, trash from cars at the tank site - please resolve ASAP.

Discussion with Ed to remove silt fence this season, relayed to Jerry (QCM) that removing it sooner would be better as the area has stabilized

Had conversation with Mike Cunningham:

- 1. Remove all construction components and construction related materials form the cul-de-sac at Talcott Ridge Road. At least put it near the tank site
- 2. Remove construction materials, equipment, pipe cut offs from Maple Ave or anywhere on the project.

This was reiterated to Jon Pio & Mike Pio

Noted fabric left at the intersection of Brick and Maiden

These items will remain open and discussed daily until completely resolved.

Miscellaneous Remarks and Visitors to Project:

Unresolved Issue: No

Shift: 1

Kurt Mintell

QA DEFICIENCY

Discussion with Mike Pio - there is a slow leak on the 8" main installed on Maple. the exact location is unknown right now.

QA Deficiency Item	Location	Description	Status
QA-00005	17	Ensure storm drains are properly protected from slurry from saw cutting and any type of material being excavated. Sediment socks must be installed under the catch basin grates to properly function as designed. This is critical to stay in compliance with EPA Regulations. It has been identified - storms drains left open at saw cut areas.	QA Concurs Corrected
QA-00006	Tank site	Shotcrete placed over the prestressed wire at the top of the tank (approx. 12 feet) There was no cylinders taken as required by the specification. This was a single truck - per section #13225-293.02 paragraph C& D Requires a set of 4 sets of test cylinders per 50 CY of concrete, or fraction thereof, placed in one day. 1 cylinders tested at 7 days 2 at 21 days one held as a spare	Not Reported Corrected

Shotcrete shall be tested per ACI-506 with test panels

(Describe QA Deficiency items issued, verify QA Deficiency items reported corrected by contractor)