

District Engineer

SECOND FIVE-YEAR REVIEW REPORT FOR WATERTOWN ARSENAL - D01MA0019 Project 02

MIDDLESEX COUNTY, MASSACHUSETTS

Prepared by ORPS OF The Corporation of the Corps Since 1775 Since 1775 Since 1775

U.S. Army Corps of Engineers New England District

Approved by:		
JOHN A. ATILANO II Colonel, Corps of Engineers	Date	_



EXECUTIVE SUMMARY

This is the Second Five-Year Review of Watertown Arsenal – Former General Services Administration (GSA) Property, Formerly Used Defense Site Project Number D01MA0019_02, located in Watertown, MA. The Decision Document's (DD) Remedial Action Objective is to reduce human health and ecological risks associated with exposure to polychlorinated biphenyls (PCBs), dioxin, and metals in the PCB Impacted Area. The site contains one Project.

The site achieved construction completion with the completion of the Remedial Action Closeout Report on September 30, 2014. The U.S Army Corps of Engineers (USACE) constructed the remedy in accordance with the 2012 DD requirements and the 2013 Remedial Action Work Plan which included the construction of a soil cap. Although the GSA property is 11.91 acres, the soil cap is approximately two acres. The five-year review trigger date was August 15, 2013. The First Five-Year Review Report was completed on August 3, 2018.

The Former GSA Property's remedy remains protective of human health and the environment. The remedy's elements that protect human health and the environment are:

- Excavated and transported offsite contaminated soil in the PCB Impacted Area greater than 50 mg/kg PCBs.
- Installed a soil cover and geotextile fabric (marker material) over residual PCB contamination less than 50 mg/kg.
- Completed a Grant of Environmental Restriction and Easement, which includes land use controls limiting onsite and intrusive activities.
- Conduct soil cover inspections and five-year reviews.

The Former GSA Property's soil cover remedy is functioning as designed by severing the soil exposure pathway. The DD's soil and surface water Applicable or Relevant and Appropriate Requirements have been met.



TABLE OF CONTENTS

EXECUTIVE SUMMARY	i
LIST OF FIGURES	iii
LIST OF TABLES	iii
LIST OF ABBREVIATIONS AND ACRONYMS	iv
1.0 INTRODUCTION	1
2.0 RESPONSE ACTION SUMMARY	6 6 8
3.0 PROGRESS SINCE THE LAST REVIEW	14
4.0 FIVE-YEAR REVIEW PROCESS 4.1 Community Notification, Involvement & Site Interviews 4.2 Data Review 4.3 Site Inspection	15 15
5.0 TECHNICAL ASSESSMENT	18
6.0 ISSUES AND RECOMMENDATIONS	
7.0 PROTECTIVENESS STATEMENT	21
8.0 NEXT REVIEW	21
9.0 REFERENCES	22
APPENDIX A – CHRONOLOGY OF SITE EVENTS	25
APPENDIX B – PUBLIC NOTICE	27
APPENDIX C – ARAR, RISK ASSESSMENT ASSUMPTIONS, AND TOXICITY REVIEW	<i>l</i> 30
APPENDIX D - FIVE-YEAR REVIEW INTERVIEWS	40
APPENDIX E – DATA ANALYSIS	44
APPENDIX F – MARCH 2023 FIVE-YEAR REVIEW SITE INSPECTION	46



APPENDIX G – MARCH 31, 2023 SITE VISIT PHOTOS62
LIST OF FIGURES
Figure 1. Former Watertown GSA Property Site Map (Maxar 2022, USGS 2021)2
Figure 2. Former Watertown GSA Property Site: Former and Current Wetlands (Maxar, 2022, USGS, 2021, USACE, 2017)4
Figure 3. Changes to the soil cover area from 2014 to 2021 (USDA NAIP 2014, Holmberg & Howe, 2014, Maxar, 2018, Maxar, 2020, Maxar, 2023, USGS, 2021)
Figure 4. Elevation change (delta) from 2014 to 2021 (Holmberg & Howe, 2014, USGS, 2021, Maxar, 2022). Positive values show potential Soil Cover settlement17
Figure F-1. March 2022 Site Visit Notes (Holmberg and Howe, 2018, Maxar, 2022)47
LIST OF TABLES
Table 1. Soil Risk Assessment Results and Remediation Goals (USACE, 2012)7
Table 2. Summary of Planned and/or Implemented Institutional Controls11
Table 3. Remedy Operations and Maintenance Summary (Charter, 2014a)12
Table 4. Protectiveness Determinations/Statements from the 2018 FYR (USACE, 2018)14
Table 5. Chronology of Site Events (Charter, 2014, 2013, USACE, 2012)26



LIST OF ABBREVIATIONS AND ACRONYMS

ARARs	Applicable or Relevant and Appropriate Requirements	MassDEP	Massachusetts Department of Environmental Protection
bgs	below ground surface	MCLs	Maximum Contaminant Levels
CERCLA	Comprehensive Environmental	MCP	Massachusetts Contingency Plan
	Response, Compensation, and	MDC	Metropolitan District Commission
	Liability Act	mg/kg	milligrams per kilogram
CFR	Code of Federal Regulations	MGL	Massachusetts General Law
CMR	Code of Massachusetts	NA	Not Applicable
	Regulations	NAIP	National Agricultural Imagery
COCs	Contaminants of Concern		Program (USDA)
DEM	Digital Elevation Model	NC	Non-carcinogenic
DERP	Defense Environmental	NCOC	Not a Chemical of Concern
	Restoration Program	NCP	National Oil and Hazardous
DU	Depleted Uranium		Substances Pollution Contingency
EPC	Exposure Point Concentration		Plan
ERA	Ecological Risk Assessment	NOAA	National Oceanographic and
FUDS	Formerly Used Defense Site		Atmospheric Administration
FYR	Five-Year Review	NOAEL	No Observed Adverse Effect Level
VOC	Volatile Organic Compounds	NPL	National Priorities List
SVOC	Semi-Volatile Organic Compounds	O&M	Operation and Maintenance
GE	Google Earth	PCB	Polychlorinated biphenyl
GERE	Grant of Environmental Restriction	PRG	Preliminary Remediation Goal
	and Easement	RA	Remedial Action
GSA	General Services Administration	RAO	Remedial Action Objective
HI	Hazard Index	RIFS	Remedial Investigation/Feasibility
IEUBK	Integrated Exposure Update		Study
	Biokinetic	TEQ	Toxicity Equivalence
LOAEL	Lowest Observed Adverse Effect	TSCA	Toxic Substances Control Act
	Level	USACE	U.S. Army Corps of Engineers
mg/kg	milligrams per kilogram	USDA	U.S. Dept. of Agriculture
LUCIP	Land Use Control Implementation	USEPA	United States Environmental
	Plan		Protection Agency
MassDCR	Department of Conservation and Recreation	USGS	United States Geological Survey



1.0 INTRODUCTION

The purpose of a Five-Year Review (FYR) is to evaluate the implementation and performance of a remedy in order to determine if the remedy is and will continue to be protective of human health and the environment. The methods, findings, and conclusions of reviews are documented in FYR reports such as this one. In addition, FYR reports identify issues found during the review, if any, and document recommendations to address them.

The U.S. Army Corps of Engineers (USACE) is preparing this FYR pursuant to the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) Section 121, consistent with the National Contingency Plan (NCP)(40 CFR Section 300.430(f)(4)(ii)) and considering Department of Defense, Formerly Used Defense Sites (FUDS), and U.S. Environmental Protection Agency (EPA) policy.

This is the second FYR for the Watertown Arsenal FUDS property. The triggering action for this statutory review is signing of the previous FYR on August 3, 2018 (USACE, 2018). The FYR has been prepared due to the fact that hazardous substances, pollutants, or contaminants remain at the Site above levels that allow for unlimited use and unrestricted exposure (UU/UE).

The Property (site)consists of one Project which will be addressed in this FYR. Project 02 (GSA Property) addresses the soil remedy.

The Watertown Arsenal FYR was led by Jeffrey Dvorak of USACE. Participants included hydrogeologist Drew Clemens, ecologist Cliff Opdyke, and geographic information systems specialist Sarah Wilkinson all of USACE. The review began on November 18, 2022.

1.1 Site Background

The site is located at 670 Arsenal Street, in the eastern portion of the town of Watertown in Middlesex County, Massachusetts (Figure 1) (USACE, 2012). It was part of the former U.S. Army Watertown Arsenal, and was referred to as the "Northeast Area" and the Federal Property Resources Center. The Site contains two parcels, the 11.91-acre GSA Property parcel, and the 1-acre, Metropolitan District Commission (MDC), now known as the MassDCR-owned, Property 20 parcel (Figure 1).

The site contains vacant land classified open space/conservancy by the City of Watertown with adjacent land considered industrial, mixed use, and residential (City of Watertown, 2022). The boundaries are heavily vegetated, and the interior contains an engineered, compensatory wetland and maintained soil cover (Figure 2). Structures related to former site operations were removed as part of the remedy, and there is no active use of the property. The nearest located water supply wells are over 1.4 miles north of the site in central Watertown, (MassMapper, 2023, USACE, 2012). The site is not within a current or a potential Drinking Water Source Area and is not within a surface water protection zone. Public access is restricted by a fence and locked gates constructed by Massachusetts Department of Conservation and Recreation (MassDCR). Historically, portions of the site were classified as both State and Federal wetlands. MassDCR and the City of Watertown plan to utilize this area as greenspace for passive recreation public access.






Figure 1. Former Watertown GSA Property Site Map (Maxar 2022, USGS 2021).



The MassDCR owned nearly 12-acre site is bounded on the west by residential properties and parkland, on the south by Arsenal Street and further south by MassDCR-owned parkland, on the east by Greenough Boulevard and parkland owned by MassDCR, and on the northwest by condominiums, apartments, and businesses. Upgradient properties contain light industrial and commercial uses, as well as two condominium complexes and a parking lot. The Arsenal Mall, the Watertown Mall, Arsenal Park, and MassDCR parkland occupy the land area to the south, southwest of the site. The area to the east and northeast of the site contains recreational pedestrian paths, open and wetland areas.

The property was filled to facilitate development during World War II and was subsequently used by the Army and by the GSA for storing and managing various materials and equipment. Prior to the Army's transfer of the property to GSA, the Nuclear Regulatory Commission (NRC) issued the U.S. Army a license in 1961 for processing

the depleted Uranium (DU) within an area at the site referred to as the former burn box area. The GSA also leased portions of the property to various parties, including automobile dealers and a television production company. One building was used as a police firing range and to store flammable materials (USACE, 2012).

1.2 History of Contamination

A 'burn area' was constructed in the northern portion of the property for scrap DU waste generated from machining operations at the former Watertown Arsenal (USACE, 2012). The Nuclear Regulatory Commission issued the U.S. Army a license in 1961 for processing the DU within an area at the site referred to as the former burn box area. The burn area vicinity was later classified as both State and Federal wetlands (Figure 2).

DU chips and turnings were coated with oil, placed in a drum, transferred to the site, and placed in a burn box located on a concrete pad surrounded by a chain link fence. The DU material was burned to convert the DU metal into a more chemically stable form. When the burn box container was full, it was welded shut and shipped off-site for appropriate disposal. A new burn box was then placed on the concrete pad.

Investigations conducted between 2007 and 2010 identified polychlorinated biphenyls (PCBs) and dioxin in site soil centered on the former burn box. It is suspected that the oil used to coat the DU chips may have contained PCBs. The dioxin may be a result of partially combusted, PCB-containing oil from the burning process. PCBs outside the burn pit may be a result of spillage during operations or oils used for dust suppression on roads.

During the 1940s, the GSA Property was filled as the U.S. Army expanded their operations toward the Charles River. The former Arsenal maintained large foundry, heat treating, sintering, and other metal working furnaces and equipment and probably generated debris such as offspec castings, sand, slag, and heat-treating furnace bricks. Fill materials observed during the field investigations at the site include metal castings, slag, metal cables, yellowish fire brick, concrete rubble, and a variety of glass, brick, and man-made fill materials.






Figure 2. Former Watertown GSA Property Site: Former and Current Wetlands (Maxar, 2022, USGS, 2021, USACE, 2017).



Given the nature of the fill materials, the fill is a reasonable source of metals contamination in soil at the site. Unlike PCBs and dioxins, metals are elements rather than compounds and therefore do not break-down. Metals can be soluble in water and under the certain conditions can be transported downgradient in surface water or groundwater flow. Groundwater was evaluated as part of 2004 Phase II CSA and is not impacted above MCP GW-3 standards. The 2004 Phase II CSA determined that the migration of metals in groundwater is not anticipated to be a significant migration pathway. Metals have low volatility and are unlikely to be transported in a gaseous phase. The mobility of metals at the site is therefore low (USACE, 2012).

The chronology of site events is shown in Appendix A, Table 5.

FIVE-YEAR REVIEW SUMMARY FORM

	FIVE-YEAR REVIEW SUMMARY FORM						
	SITE IDENTIFICATION						
Property Name: Wa	tertown Ars	senal					
FUDS Property No.:	D01MA001	19_02					
Region: 1	State: MA	Ą	City/County: Watertown, Middlesex				
		SIT	E STATUS				
NPL Status: Non-NPL	_						
Multiple OUs? No		Has the Yes	Site achieved construction completion?				
		REVI	IEW STATUS				
Lead agency: Other Federal Agency If "Other Federal Agency" was selected above, enter Agency name: United States Army Corps of Engineers (USACE)							
Author name (Federa	l or State I	Project M	lanager): Jeffrey Dvorak				
Author affiliation: US	SACE						
Review period: 11/18/2022- 8/3/2023							
Date of site inspection: 3/31/23							
Type of review: Statutory							
Review number: 2							
Triggering action date: 8/03/2018							
Due date (five years a	after trigge	ering acti	ion date): 08/03/23				



2.0 RESPONSE ACTION SUMMARY

2.1 Basis for Taking Action

PCBs, metals, and dioxin are the primary COCs at the site, and were identified in the PCB Impacted Area shown in Figure 2 as the soil cover Area. Potential exposures to PCBs, metals, and dioxin in soils in the vicinity of the burn box (PCB Impacted Area) posed the only documented site-related unacceptable risks to human health and the environment. Site data did not indicate the presence of a principal threat under the NCP as the contamination was reliably contained and presented a low risk below unacceptable levels in the event of exposure. As documented in the 2011 RI/FS, the PCBs do not readily volatilize or leach into the groundwater and the ability to install a soil cover to eliminate direct exposure to the contaminated soils has resulted in acceptable risk levels for the planned passive recreational use of the site.

2.2 Response Actions

The RAO for the site is to reduce human health and ecological risks associated with exposure to PCBs, dioxin, and metals in the PCB Impacted Area. From 1967 to 2003, several radiological surveys occurred at the site, resulting in 140 cubic yards of soil, fill material, DU debris, and two tanks, being removed (MacTec, 2011). The NRC released the site for unrestricted use for radiological concerns in November 2003. The Remediation Goals to meet this RAO are shown in Table 1. As indicated in the DD, USACE, with concurrence from MassDEP, selected the following major remedy components:

- Excavate contaminated soil in the PCB Impacted Area greater than 50 mg/kg PCBs,
- Install a soil cover and geotextile fabric over the PCB impacted area, and
- Grant of Environmental Restriction and Easement (GERE)

2.3 Status of Implementation

Charter Contracting Company, LLC (Charter) completed mobilization and pre-remedy construction tasks between December 2012 and August 2013. Clearing and grubbing, building demolition, utility, and monitor well abandonment were completed between January and April 2013. PCB Impacted Area delineation sampling was completed in late July 2013, and the Remedial Action soil removal began mid-August 2013. Approximately 960 tons of PCB contaminated soil greater than 50 mg/kg was excavated from 1 to 7 feet below grade in the PCB Impacted Area, and transported to the Wayne Disposal Landfill in Belleville, Michigan between August and December 2013 (Charter, 2014a). MassDEP approved using soil removed as part of the compensatory wetland construction, and about 600 tons of material excavated from the area around historical soil sample SS-104, to build the soil cover. The soil cover is approximately two acres.



Table 1. Soil Risk Assessment Results and Remediation Goals (USACE, 2012).

	Human Health Risk-E Remediation Goals (•	Ecological Risk-Based PRGs				Site		
Chemical	Impacted Area	Ç	ancer Risk		НІ		Rol	pin	Shr	ew	"Backgroun d Value" [e]	Remediation Goal [g]
of Concern	(mg/kg)	1E-06	1E-05	1E-04	1		NOAEL	LOAEL	NOAEL	LOAEL	(mg/kg)	(mg/kg)
PCBs	170	0.89	8.9	89	6.3	[b]					NA	1 [h]
Aroclor-1254	170						0.82	8.2	0.16	1.6	NA	1 [h]
Aroclor-1260	0.99						0.80	8.0	0.051	0.51	NA	1 [h]
Dioxin	0.00022	0.0000096	0.000096	0.00096	NA	[b]	0.000063	0.00063	0.0000016	0.000016	0.000208 [f]	0.00075 [i]
Antimony	414	NC	NC	NC	64	[c]	0.96	9.6	197	212	19.3	19.3
Cadmium	12.4	NCOC					7.2	27	6.0	23	2.18	N/A [j]
Chromium	264	NCOC					71	292	89	1305	25.2	N/A [j]
Copper	1000	NCOC					667	1333	1418	14185	66.2	N/A [j]
Lead	1031	984				[c, d]	100	176	165	5394	506	506
Nickel	17263	NC	NC	NC	1726	[c]	1213	1677	565	1129	22.3	565
Vanadium	74	NCOC					40	398	19	191	44.5	N/A [j]
Zinc	855	NCOC					232	2093	1158	3917	278	N/A [j]

[[]a] - For cancer-based values, calculated as: EPC x Target Risk /Risk for passive recreational visitor (sum of three populations) for non-cancer risk, calculated as: EPC/HI calculated for either young child subchronic scenario or young child chronic scenario (whichever is higher)

- [b] Based on young child chronic scenario
- [c] Based on young child subchronic scenario
- [d] Based on IEUBK modeling (AMEC, 2011)
- [e] Maximum concentration; Table 7-1 from Final Phase II CSA (MACTEC, 2004)
- [f] Concentration measured at reference location in southwest corner of site.
- [g] PRG is lowest value (rounded) of Human Health PRG, Ecological PRG or background if background is greater than Human Health and Ecological PRGs.
- [h] PRG based on TSCA PCB Site Revitalization Guidance Under the TSCA 2005in lieu of background concentration.
- [i] Concentration of Dioxin found at "Other Areas Around site"
- [j] Not applicable as metals associated with unregulated fill material found on site and not related to site activities.



The soil cover and filter fabric warning layer extended 10 feet beyond the 1 mg/kg PCB boundary except where retaining walls or the Greenough Boulevard fence limited workspace. The filter fabric is overlain by 18 inches of clean fill and 6 inches of clean topsoil, respectively. From September 2013 through June 2014, Charter constructed an approximately 2-acre compensatory wetland and adjacent upland meadow habitat at the site and in the process found and removed an underground storage tank (Charter, 2014a). The wetland replication area restores and replaces the functions and values of the wetland area impacted during soil removal and cover construction and replicated the incidental impacts to wetlands during remedy construction. A final inspection site walk with USACE, MassDEP, MassDCR, GSA, and the Watertown Conservation Commission to confirm completion of construction activities and site conditions occurred on July 16, 2014.

2.3.1 Soil Excavation

Spanning April 2013 through July 2014, remedial design, excavation, and confirmatory soil sampling were done in an iterative process to ensure material containing greater than 50 mg/kg PCBs was identified and removed for offsite disposal. Final confirmation sampling showed residual contamination levels were less than 50 mg/kg, and the 1 mg/kg remediation goal boundary is within the property boundary (purple polygon in Figure 2) (Charter, 2014b, USACE, 2012). Soil excavated as part of the compensatory wetland construction contained 1 to less than 50 mg/kg PCBs and was placed into the PCB Impacted Area excavations. The constructed soil cover encompasses the 1 mg/kg boundary except for a small portion on the eastern swale (Figure 2).

2.3.2 LUCIP Survey

The LUCIP and GERE review combined with the findings from the first FYR found the soil cover area correctly located (USACE, 2018). It was initially discovered in the first FYR the site plan's boundary data contained positional data documentation errors (Charter, 2014c, USACE, 2014). These errors were carried over from the as-built site survey and include the property boundaries and co-located fence (Holmberg & Howe, 2018). The corrected property boundary was used for all figures provided in this Second FYR. Site features assessed in this FYR were taken from satellite imagery and lidar derived digital elevation models (Maxar 2022, USGS 2021, USDA NAIP 2014, Maxar 2018, Maxar 2020, Maxar 2021).

2.4 Grant of Environmental Restriction and Easement

The Remedy's Land Use Control Implementation Plan (LUCIP) addresses the soil cover and non-soil cover areas through the GERE as outlined in the Decision Document. The covenants and restrictions in the GERE run with the land and are binding upon future owners of the property in perpetuity until otherwise released by the grantee. The GERE was established consistent with the provisions of M.G.L. c. 21E, sec. 6 and the applicable provisions of 310 CMR 40.1071, and otherwise is satisfactory to MassDEP as grantee (Table 2). The restrictions in the GERE include a description of prohibited and permitted uses and activities, including restrictions on soil disturbance within both the Soil Cover Area and the Non-Cover Area. The GERE was recorded immediately prior to the transfer of the GSA parcel from the Unites States. On Property 20, a Notice of Environmental Restriction and Easement was recorded, which is modeled on the GERE.



The soil cover Area is defined by a series of boulders and survey markers outlining its extent. No intrusive, active maintenance or recreational activities (school, gardening) are permitted on the soil cover. The non-soil cover area contains the rest of the site, including Parcel 20, and is marked by a MassDCR-installed chain link fence following the surveyed Site boundary (Figure 2). A retaining wall is located on the western site boundary and is not part of the site. Intrusive activities are permitted when done in accordance with the GERE's Soil Management Plan.

2.4.1 Permitted and Restricted Uses and Activities

Permitted Uses and Activities

The property owner has agreed to the following permitted uses and activities at the site:

- Pedestrian activity and other passive recreational uses, including sitting at and otherwise
 passively utilizing any meadow areas, viewing nodes, areas for nature study, park
 benches, shade structures and interpretive kiosks that may be located in the Non-Cover
 Area, and in each case in a manner that does not disturb the Soil Cover Area or NonCover Area, including the soil surface of the Soil Cover Area or Non-Cover Area, in a
 manner prohibited by the restricted use and activities (as defined below);
- Non-intrusive routine site maintenance, including cleaning drainage structures, mowing
 the shoulders along any trails and meadows, mowing the Soil Cover Area, leaf raking,
 and, on the paved or stabilized path or roadways that may be located in the Non-Cover
 Area, snow removal and ice treatment, provided, however, that such maintenance does
 not disturb the Soil Cover Area or Non-Cover Area, including the soil surface of such
 Areas, in a manner prohibited by the restricted use and activities (as defined below); and
- Excavation, drilling or otherwise disturbing soil, loam, peat, gravel, sand, rock or other mineral or natural resource in, below or on the Non-Cover Area in accordance with the Soil Management Plan (Exhibit C of the GERE).

Restricted Uses and Activities

Restricted uses and activities are not permitted at the site. Restricted uses and activities include the following:

Soil Cover Area

- Residential, daycare, school activities, gardening, or active recreational activities.
- Excavating, drilling, or otherwise disturbing any soil, loam, peat, gravel, sand, rock or
 other mineral or natural resource in, below or on the Soil Cover Area, including any
 disturbance or breaching of the permeable soil cover in the Soil Cover Area in any way,
 including by digging, drilling, plowing, planting, cultivating, or by constructing buildings or
 other structures.
- Reduction in the grade below the ground surface grade of the Soil Cover Area.
- Using or otherwise bringing motorized vehicles, including cars, trucks, snowmobiles, and all-terrain vehicles on or over the Soil Cover Area, or using bicycles, skis, or sleds in, on or over the Soil Cover Area, but excluding motorized vehicles with ground pressure of 15 psi or less; and
- Any other use or activity in the Soil Cover Area which would interfere with, or would be
 reasonably likely to interfere with, the implementation, effectiveness, integrity, operation,
 or maintenance of the Selected Remedy, including but not limited to (a) interference with
 the Benchmarks, or (b) interference with any systems used to monitor groundwater,
 surface water, soils, or sediments.

Non-Cover Area

Residential, daycare, school activities, gardening, or active recreational activities.



- Excavation, drilling or otherwise disturbing any soil, loam, peat, gravel, sand, rock or other mineral or natural resource in, below or on the Non-Cover Area, except in accordance with the Soil Management Plan (Exhibit C of the GERE).
- Using motorized vehicles by the public, including cars, trucks, snowmobiles, dirt bikes and all-terrain vehicles on or over the Non-Cover Area except in paved areas designated for parking.
- Using bicycles, skis, snowboards, or sleds on or over the Non-Cover Area except on paved ways; and
- Using or otherwise bringing motorized vehicles, including cars, trucks, snowmobiles and
 all-terrain vehicles on or over the Non-Cover Area, or using bicycles, skis or sleds in, on
 or over the Non-Cover Area, but excluding (a) any such use of motorized vehicles,
 bicycles, skis or sleds that is conducted on a paved or stabilized path or roadway in
 good repair, and (b) motorized vehicles or equipment used by public employees in
 carrying out their lawful duties, provided, however, that such motorized vehicles and
 equipment do not disturb the Non-Cover Area;
- Any other use or activity in the Non-Cover Area which would interfere with, or would be
 reasonably likely to interfere with, the implementation, effectiveness, integrity, operation,
 or maintenance of the Selected Remedy, including but not limited to (a) interference with
 the Benchmarks, or (b) interference with any systems used to monitor groundwater,
 surface water, soils, or sediments (Charter, 2014b).

2.4.2 Compilation and finalization of the GERE

The GERE comprises the following (Charter, 2014b, USACE, 2012):

- A prepared map indicating the soil cover Area and Non-Cover Area boundary areas over which the LUCs will apply.
- A survey plan showing the property boundaries, soil cover Area and Non-Cover Area, prepared by a professional land surveyor registered by the Commonwealth of Massachusetts agency for the limited purpose of providing public notice of the environmental conditions of and limitations on the use of property (copies will be provided to MassDEP).
- A title certification consistent with Massachusetts title certification standards, showing no encumbrances inconsistent with the GERE.
- LUC monitoring to verify the LUCs are being properly implemented and that the LUC objectives are being met on an annual basis unless the frequency is reduced by agreement with MassDEP. The LUC monitoring results are included in a separate report and provided to MassDEP.
- Reporting and notification requirements include the following:
 - Notification to MassDEP no longer than ten days after discovery of any activity that is inconsistent with the LUC objectives or use restrictions, or any other action that may interfere with the effectiveness of the LUCs.
 - The United States, acting through GSA, shall provide a copy of executed lease of transfer documents to MassDEP.
 - USACE shall submit annual LUC monitoring reports to MassDEP no later than 30 days after the inspection. If the United States has transferred the land to another entity, the annual evaluation will address whether the LUCs were communicated in the GERE, whether the owners and state and local agencies were notified of



- the use restrictions and controls affecting the property, and whether use of the property has conformed to such restrictions and controls.
- USACE shall notify MassDEP and MassDCR at least 7 days before any LUC compliance inspection so that either party will have the opportunity to participate in the LUC inspection if it so chooses.
- Obtain MassDEP concurrence prior to modifying or terminating the LUCs or implementation actions.
- Evaluate the effectiveness of the LUCs as part of each Five-Year Review.

As indicated in Table 2 below, the GERE was finalized on October 21, 2014, and amended on January 28, 2021, to reference a plan with corrected coordinate data.

Table 2. Summary of Planned and/or Implemented Institutional Controls

Media, engineered controls, and areas that do not support UU/UE based on current conditions	ICs Needed	ICs Called for in the Decision Documents	Impacted Parcel(s)	IC Objective	Title of IC Instrument Implemented and Date (or planned)
Soil	Yes	Yes	Property A: 670 Arsenal Street Book 4363 Page 281	GERE filed with the Massachusetts Registry of Deeds to assure changes in land use are evaluated in accordance with state and local requirements. The objectives are to prevent exposure to soil containing PCBs, Dioxin, and metals by preventing disturbance of the soil, maintaining the integrity of the remedial action (soil cover) and assure access to the site.	Grant of Environmental Restriction and Easement (GERE) – October 21, 2014 and revised January 28, 2021

2.5 System Operation/Operation and Maintenance, and Monitoring

Long term monitoring and maintenance of the soil cover began in 2014 to ensure soil cover integrity. USACE and MassDCR, in coordination with MassDEP, conduct inspections of the soil cover and compensatory wetlands (Table 3) using the approved scheme based on the signed Decision Document and the resulting O&M Plan (Charter 2014a, b, 2013, USACE, 2012).



Table 3. Remedy Operations and Maintenance Summary (Charter, 2014a).

Activity	Performing Agency	Frequency/Duration
Inspect vegetative (soil) cover (includes surface elevation or settlement monitoring)	USACE in coordination with MassDCR and MassDEP	Annually
Mow vegetative (soil) cover, including swales; remove deep-rooted vegetation; clean drainage swales, check dams, and the catch basin	MassDCR	Once per year for mowing; Once per year or more often as needed for other activities.
Maintenance of remedy, including vegetative cover not delegated to MassDCR; repair of vegetative cover; and the correction of design flaws in the vegetative cover	USACE	As identified during inspections
Maintenance and inspection of compensatory wetlands	MassDCR	Semi-Annual After 15 August 2018
Compensatory wetlands monitoring and reporting	MassDCR	Annually After 15 August 2018
Soil cover reports	USACE	Annual after initial 5 years
Five-year review reports	USACE	Every 5 Years

2.5.1 Annual Soil Cover Monitoring and Maintenance

Soil cover inspections transitioned to annual events starting in 2018 through 2022 as indicated in Table 3 due to PCBs remaining at the site between 1 and 50 mg/kg concentration (USACE, 2016, Charter, 2014a). Annual Monitoring and maintenance activities include annual mowing of the soil cover and non-soil cover areas by MassDCR. MassDCR also clears the drainage swale and catch basin adjacent to the soil cover area. USACE then performs an inspection to determine whether the land use controls are still being fully implemented. Over the previous five years, notable observations and maintained activities have included:

- In 2018, several animal burrows on the soil over area. USACE contracted a landscaper to fill the burrows and replant the disrupted area as no damage was observed to the liner.
- In 2019, USACE observed the site's drainage swale was filled with standing water and the swale was ironed-stained.
 - The presence of iron-staining and standing water are not new site condition and has been observed since long term monitoring and maintenance began in 2014 (USACE, 2018b). The staining likely reflects the natural precipitation of iron from solution in groundwater when exposed to air at the surface.
 - The surface water accumulation was noted after a significant rain event.
 USACE representatives observed that the catch basin was completely blocked by vegetation and no flow/drainage from the site was occurring.
 MassDCR cleared the catch-basin allowing the surface water to drain from the drainage swale.
- Field observations were not located on the checklist's accompanying imagery in accordance with the requirements of the O&M Plan checklist for four of the last five annual inspections, preventing problem analysis over time and across the site for many



findings identified in the inspection reports (First FYR review maps used for all USACE 2018-2022 inspections) (USACE, 2018 - 2022).

2.5.2 Eastern Swale

The soil cover extends about 50 ft to the northeast into a wetland, which drained southeast toward the boundary fence along Greenough Boulevard before entering one of two catch basins discharging into the Charles River (MacTec, 2011). The eastern swale riprap or channel armor parallel to Greenough Boulevard has been iron-stained since at least September 2014 and retains water after major storm events. The ponded water in the eastern swale may be due to clogged check dams and catch-basin (maintained by MassDCR) or ground water break out. The swale and its catch basin occupy a pre-1951 drainage ditch and wetland (Harding ESE, 2004, ABB Environmental, 1993) (Figure 1). The wetland described in this section was ultimately filled as a result of the cap installation.

2.5.3 Compensatory Wetlands

USACE conducted inspections every two to four weeks starting May 2014, and continued through September 2014 (Charter, 2014b Lucas Environmental, 2014). Frequency was reduced to 3-to-4-month intervals through 2016 in accordance with the Operations and Maintenance Plan (Charter, 2014a). USACE began semi-annual inspections in 2017 through August 2018, when MassDCR took over the program for the entirety of this second five-year period (2018-2023) (USACE, 2017c, Charter, 2014a).



3.0 PROGRESS SINCE THE LAST REVIEW

This section includes the protectiveness determinations and statements from the **last** five-year review as well as the recommendations from the **last** five-year review and the current status of those recommendations.

Table 4. Protectiveness Determinations/Statements from the 2018 FYR (USACE, 2018).

Project #	Protectiveness Determination	Protectiveness Statement
02	Protective	The former GSA Property's remedy is protective of human health and the environment.

As indicated in Table 4, no issues were identified during the first five-year review (USACE, 2018).



4.0 FIVE-YEAR REVIEW PROCESS

4.1 Community Notification, Involvement & Site Interviews

A public notice was made available by newspaper posting titled "Public Notice for Start of Second Five-Year Review for the Watertown Arsenal, Former GSA Property, Watertown, Massachusetts" in The Boston Globe on November 18, 2022, both in the newspaper and on their website (see Appendix B). The posting stated that there was a five-year review and inviting the public to submit any comments to USACE. The results of the review and the report will be made available at the site information repository located at the Watertown Free Public Library, 123 Main Street, Watertown MA, 02472. It will also be posted on the public USACE website for the site. The results of the review and the report will be made available on the USACE website:

https://www.nae.usace.army.mil/Missions/Projects-Topics/Watertown-Arsenal-FUDS/

4.1.1 Interviews

During the FYR process, interviews were conducted to document any perceived problems or successes with the remedy that has been implemented to date. The results of these interviews are summarized below. A request for interview with representatives of the City of Watertown, MassDEP, and MassDCR was sent in an email dated September 30, 2022. Joanne Dearden of MassDEP participated in an interview on April 13, 2023, and the interview summary is included for record in Appendix D. Ms. Dearden indicated on the overall status of the project and site, she thought the Remedy is performing as expected; one of the areas that regularly requires attention is the maintenance of the drainage swale. She stated USACE has been responsive to fixing observed minor disturbances to the soil cover including burrows & run-off channeling. No other stakeholders participated in interviews as part of the second FYR.

4.2 Data Review

No data was collected as part of the remedy over the last five years, however, the 5YR used lidar survey data to evaluate soil cover settlement over time.

4.2.1 Soil Cover Area

A review of as-built contours of the soil cover area (Holmberg & Howe, 2014) and digital elevation model derived from 2021 lidar (ground points only, DEM generated at 1.6 ft cell size) (USGS, 2021) (Appendix E) showed settlement areas less than 1 ft deep over areas no bigger than 6 feet (Figure 4).

Observations from the Second FYR Site Inspection are included in Section 4.3.





16

Figure 3. Changes to the soil cover area from 2014 to 2021 (USDA NAIP 2014, Holmberg & Howe, 2014, Maxar, 2018, Maxar, 2020, Maxar, 2023, USGS, 2021)

July-2023





Figure 4. Elevation change (delta) from 2014 to 2021 (Holmberg & Howe, 2014, USGS, 2021, Maxar, 2022). Positive values show potential Soil Cover settlement.



4.3 Site Inspection

The inspection of the site was conducted on 3/31/2023. In attendance were Jeff Dvorak and Drew Clemens from USACE, Joanne Dearden (MassDEP), Muhammad Chowdhury (MassDCR), Katie Swan (City of Watertown), and Samantha Velluti-Fry (Tighe & Bond, City of Watertown-retained Consultant) accompanied the USACE team. The purpose of the inspection was to assess the protectiveness of the remedy.

The soil cover integrity has not been compromised, but several depressions noted in the DEM analysis were found during the inspection (Appendix E). Soil cover inspections show no indication that the filter fabric warning layer has been penetrated by burrowing rodents or any other potential intrusive threats and no active or abandoned animal burrows were noted during the 31 March 2023 FYR site walk.

Sod cover was thin on the southern part of the cap, and some spots on the north-facing slope. More than half of the original disk pins locating the edge of the membrane appear to be missing, and the boulders on the northern portion appear to have been moved from the boundary of the cap. Exposed tree roots penetrate the soil cover in one location but are outside the 1 mg/kg PCB boundary. The location of the inlet and outfall pipes utilized in the first FYR was found to be off from the location observed during the site inspection (USACE, 2018). This has been corrected and updated in all figures associated with the Second FYR.

Leaf litter in the swale continues to limit flow and clog the inlet grate. The offsite outfall appears to be functioning. A depression within the Eastern Drainage Swale appears to create local standing water. There has been no change in iron staining extent first documented on September 27, 2014 (Google Earth, 2017). MassDCR maintains the six check dams, catch basin and associated outfall across Greenough Boulevard following inspections. Below grade sediment and debris conditions are not known.

Locations of site observations are shown in Appendix F; Figure F-1. A photograph log of the site inspection is included as Appendix G.

Phragmites clumps are present in the northern swale's edges. Plant debris clogs the six check dams, and some have been lowered to facilitate flow. While onsite, USACE personnel unclogged the catch basin grate of vegetation debris. The eastern swale's riprap channel armor is iron stained.

None of the observations made during the site visit indicated a potential for current or future impact protectiveness of the Remedy.

5.0 TECHNICAL ASSESSMENT

Question A: Is the remedy functioning as intended by the decision documents?

Yes. Original confirmation sampling showed soil exceeding 50 mg/kg of PCBs were successfully excavated and transported to regulated landfill offsite. Remaining soils contaminated with less than 50 mg/kg of PCBs were consolidated onsite, covered with a filter fabric warning layer, and clean soil as designed. The soil cover successfully prevents receptor access to the underlying contaminated materials. Soil cover inspections show no indication that the filter fabric warning layer has been penetrated by burrowing rodents or any other potential intrusive threats. The temporal topography comparison between post construction survey and



2021 lidar does not indicate any major settlements or alterations to the soil cover therefore indicating the cap is in similar condition to post construction condition, and the remedy is still in place. The soil cover is maintained in accordance with the O&M plan. As there has been no major settlements, alterations to the soil cover, and the liner has not daylighted during any of the site inspection activities, contaminated soil will have stayed below the cap, cutting the pathway of direct contact.

As indicated in Section 2.4, the Remedy's LUCIP addresses the soil cover and non-soil cover areas through the GERE as outlined in the Decision Document. The GERE is in place and functioning as intended as it has been effective in preventing exposure through covenants and restrictions, annual maintenance, monitoring and reporting.

Question B: Are the exposure assumptions, toxicity data, cleanup levels, and remedial action objectives (RAOs) used at the time of remedy selection still valid?

Yes. The remedy's exposure assumptions remain valid, however several of the values have changed since the RI was written and those are detailed in Appendix C. There have not been any changes in the physical site conditions that could affect the protectiveness of the remedy. Appendix C summarizes exposure pathways and routes evaluated in the human health and ecological risk assessments.

No toxicity factors or exposure assumptions for COCs have changed since the completion of the Decision Document, so cleanup levels and RAOs used at the time of the remedy remain valid. The only two COCs with Remediation Goals (RGs) based on risk were nickel (No Observed Adverse Effect Level for the Shrew) and PCBs (2005 EPA Guidance). The remedial action is complete and has achieved its RAOs.

Question C: Has any other information come to light that could call into question the protectiveness of the remedy?

No.

6.0 ISSUES AND RECOMMENDATIONS

Issues/Recommendations Project(s) without Issues/Recommendations Identified in the Five-Year Review: 02

No issues or recommendations affecting current and or future protectiveness were identified in the five-year review.

6.1 Other Findings

In addition, the following are recommendations that were identified during the FYR and (may reduce costs, improve management of O&M, and conserve energy), but do not affect current and/or future protectiveness:



- Operations & Maintenance Plan Execution Inspection findings should be georeferenced and tracked over time in accordance with the O&M Plan (e.g., tree roots).
 - Observed potential disturbances such as the tree roots should be removed and noted during annual inspection and maintenance activities.
- Six Swale Check Dams The drainage swale's check dams retain water for several days after precipitation events and should be cleaned. During regular mowing activities and swale maintenance completed by MassDCR, the check dams and receiving catch basin should be inspected and serviced if needed, including camera inspection of the pipe under Greenough Blvd.
- Elevation Verification Complete a site survey by a MA licensed surveyor to better quantify low spots in the swale and to confirm the soil cover perimeter. At the time of the survey, survey markers should be replaced where necessary.
- Site Assessment Utilize drone-based assessment methods for inspections.



7.0 PROTECTIVENESS STATEMENT

Protectiveness Statement(s)				
Project: 02	Protectiveness Determination: Protective	Planned Addendum Completion Date: Not Applicable		
Protectiveness S health and the er	Statement: The remedy at Project 02 (GSA Pronvironment.	operty) is protective of human		

The following actions are affectively reducing the exposure risk to PCBs, dioxin, and metals:

- Excavated and transported offsite contaminated soil in the PCB Impacted Area greater than 50 mg/kg PCBs.
- Installed a soil cover and geotextile fabric (marker material) over residual PCB contamination less than 50 mg/kg.
- Completed a GERE, which includes land use controls limiting site and intrusive activities.
 - LUCs (covenants and restrictions, annual maintenance, monitoring and reporting) are effectively limiting site and intrusive activities.
- Conduct soil cover inspections.

8.0 NEXT REVIEW

The next five-year review report for the Watertown Arsenal – Former GSA Property is required five years from the completion date of this review.



9.0 REFERENCES

- ABB Environmental Services Inc (ABB Environmental, Inc), 1993. Former Watertown Arsenal Preliminary Assessment, Watertown Massachusetts. U.S Army Corps of Engineers New England Division Waltham Massachusetts, 321 p.
- Charter Environmental, Inc., 2013. Remedial Action Work Plan GSA Property D01MA001902, Watertown MA. Prepared for the US Army Corps of Engineers under Contract W912WJ-11-D-0009/0003 and submitted 17 May 2013, 143 p.
- Charter Environmental, Inc., 2014a. Draft Final Operations and Maintenance Plan GSA Property D01MA001902, Watertown MA. Prepared for the US Army Corps of Engineers under Contract W912WJ-11-D-0009/0003, 38 p.
- Charter Environmental, Inc., 2014b. Final Land Use Control Plan GSA Property D01MA001902, Watertown MA. Prepared for the US Army Corps of Engineers under Contract W912WJ-11-D-0009/0003, 81 p.
- Charter Environmental, Inc., 2014c. Final Remedial Action Closeout Report– GSA Property D01MA001902, Watertown MA. Prepared for the US Army Corps of Engineers under Contract W912WJ-11-D-0009/0003, 506 p.
- Chute, N.E., 1959. Glacial Geology of the Mystic Lakes-Fresh Pond area, Massachusetts. US Geological Survey Bulletin 1061-F, 38 p.
- City of Watertown, 2022. Watertown Planning and Zoning Dept. Zoning Map dated 12 May 2022. Accessed from: https://www.watertown-ma.gov/218/Planning-Zoning, Watertown Zoning Map (PDF) Accessed 14 April 2022.
- Google Earth, 2017. Imagery collected on 14 April 2017 over the Watertown MA area.
- Harding ESE, 2004. Draft Response Action Outcome Statement, GSA Site, Watertown Massachusetts, Release Tracking Number 3-02722. Prepared for USACE New England District under Contract No DACA33-97-C-0023, January 2004, 109 p.
- Holmberg & Howe, 2014. As-Built Site Plan, Remedial Action at the GSA Property (D01MA001902), Watertown MA. Date: 9/29/14. Prepared for Charter Environmental (Plan #6). Found in page 130 of Final RACR.
- Holmberg & Howe, 2018. Plan of Land, Remedial Action at the GSA Property (D01MA001902), Watertown MA. Date: 10/04/2013, Revised 04/17/2018. Prepared for Charter Environmental (Plan #1).
- Lucas Environmental, 2014. GSA Property DOMA001902 670 Arsenal Street, Watertown, Massachusetts. Prepared for Charter Environmental 28 Oct 2014, 22 p.
- MacTec, 2011. Remedial Investigation/Feasibility Study (RI/FS), GSA Property, Watertown, Massachusetts. Formerly Used Defense Sites Project Number D01MA001902, DEP CASE NO. 3-02722. Prepared for USACE New England District by MacTec and Woods Hole Group under Contract Number W912WJ-09-D0001, 249 p.



- MassMapper, 2023. MassGIS Data: Public Water Supplies, https://maps.massgis.digital.mass.gov/MassMapper/MassMapper.html, accessed on 17 April 2023.
- Maxar 2018 Pan Sharpened Natural Color Imagery. Collected 5 May 2018. File: 2018_05_05_R2C4. Downloaded from G-EGD https://evwhs.digitalglobe.com/myDigitalGlobe/ March 2023.
- Maxar, 2020. Pan Sharpened Natural Color Imagery. Collected 14 June 2020. File: 2020_06_14_R1C3. Downloaded from G-EGD https://evwhs.digitalglobe.com/myDigitalGlobe/ March 2023.
- Maxar 2023. Pan Sharpened Natural Color Imagery. Collected 5 March 2023. File: 2023_03_05_R1C2 and 2023_03_05_R1C1. Downloaded from G-EGD https://evwhs.digitalglobe.com/myDigitalGlobe/ March 2023.
- United States Army Corps of Engineers (USACE), 2007. Wetland Delineation Report, Former Watertown Arsenal, GSA Property, Watertown, Massachusetts. Prepared By: Department Of Army New England District, Corps of Engineers, Engineering/Planning Division, Evaluation Branch, Environmental Resources Section, 128 p.
- USACE, 2012. Decision Document GSA Property Formerly Used Defense Site # D01MA001902 Watertown, Massachusetts D01MA001902, signed 20 June 2012. Prepared by: Woods Hole Group, Inc. 81 Technology Park Drive East Falmouth, Massachusetts and AMEC Environment & Infrastructure, Inc. 107 Audubon Road Wakefield, Massachusetts Contract Number: W912WJ-09-D0001, 97 p.
- USACE, 2014. Grant of Environmental Restriction and Easement. Prepared by USACE New England District notarized 21 October 2014 and submitted to MassDEP.
- USACE, 2016. Compensatory Wetland and Soil Cover Monitoring and Maintenance Report, April 2015, GSA Property DOMA001902, 670 Arsenal Street, Watertown, Massachusetts, prepared 16 Feb 2016, 31 p.
- USACE, 2018. Five-Year Review Report, First Five-Year Review for Watertown Arsenal Former GSA Property, Formerly Used Defense Site Project Number D01MA0019_02, Town of Watertown, Middlesex County, Massachusetts.
- USACE, 2019. Soil Cover Monitoring and Maintenance Summary Report, GSA Property DOMA001902, 670 Arsenal Street, Watertown, Massachusetts, prepared September 2020, 33 p.
- USACE, 2020. Soil Cover Monitoring and Maintenance Summary Report, GSA Property DOMA001902, 670 Arsenal Street, Watertown, Massachusetts, prepared September 2020, 25 p.
- USACE, 2021. Soil Cover Monitoring and Maintenance Summary Report, GSA Property DOMA001902, 670 Arsenal Street, Watertown, Massachusetts, prepared September 2021, 25 p.



- USACE, 2022. Soil Cover Monitoring and Maintenance Summary Report, GSA Property DOMA001902, 670 Arsenal Street, Watertown, Massachusetts, prepared September 2022, 27 p.
- United States Department of Agricultures (USDA) National Agriculture Imagery Program (NAIP), 2014. NAIP Imagery Entity ID M_4207147_NE_19_1_20140712. Project Name 201407_MASSACHUSETTS_NAIP_1X0000M_UTM_CNIR. Collection Date: 12 June 2014. Downloaded from https://earthexplorer.usgs.gov/ 22 March 2023.
- USEPA, 2005. PCB Site Revitalization Guidance Under the Toxic Substances Control Act
- USEPA, 2011. OSWER Directive 9355.7-18 Recommended Evaluation of Institutional Controls: Supplemental to the Comprehensive Five-Year Review Process, 28 p.
- USEPA, 2012. OSWER Directive 9200.2-111 Clarifying the Use of Protectiveness Determinations for Comprehensive Environmental Response, Compensation, and Liability Act Five-Year Reviews, 5 p.
- USEPA, 2015. OSWER Publication 9200.2-154 OSWER Technical Guide for Assessing and Mitigating the Vapor Intrusion Pathway from Subsurface Vapor Sources To Indoor Air. Published by the U.S. Environmental Protection Agency, Office of Solid Waste and Emergency Response, June 2015, 267 p, available at https://www.epa.gov/vaporintrusion/technical-guide-assessing-and-mitigating-vapor-intrusion-pathway-subsurface-vapor.
- U.S. Geological Survey (USGS), 2015. USGS Lidar Point Cloud MA Sndy-CMPG 2013 19TCG225920 LAS 2015: U.S. Geological Survey 20150528. Collected: 16 November 2013 11-16 to 31 December 2014-12-31. Metadata available at: https://www.sciencebase.gov/catalog/item/5a868722e4b00f54eb371b9a.
- USGS 2021. USGS Lidar Point Cloud MA_CentralEastern_2021_B2119TCG322692: U.S. Geological Survey 20221013. Collected: 20 March 2021 to 24 April 2021. Metadata available at https://www.sciencebase.gov/catalog/item/634b44cad34e47431c14b1c9. Accessed Feb 2023 from https://apps.nationalmap.gov/downloader/.



APPENDIX A – CHRONOLOGY OF SITE EVENTS



Table 5. Chronology of Site Events (Charter, 2014, 2013, USACE, 2012).

Event	Date
US Army acquires the GSA property from the Commonwealth of	4000
Massachusetts	1920
US Army used the property for landfilling, outdoor vehicle, and	4040a through
material storage	1940s through early 1950s
US Army treated depleted uranium (DU) scrap by coating with oil	1061 1067
and burning in a burn box	1961-1967
US Army transferred the property to GSA	1967
Radiological surveys and soil removal actions	1967, 1973, 1988
Comprehensive Site Assessment	1990
Interim Remedial Measure removing 130 cubic yards of soil, fill	1989-1993
material, debris, and an underground tank	1909-1993
Preliminary Assessment	1992-1993
Radiation Characterization Survey	1993-1996
Historical Site Assessment and Report	2000-2001
Focused Uranium Tailings Investigation and Report	2002-2003
Phase II Comprehensive Site Assessment	1994-2003
MassDEP and the Massachusetts Department of Public Health	
concurred with the Nuclear Regulatory Commission's	November 2003
recommendation releasing the Site for unrestricted use	
Draft Response Action Outcome and Activity and Use Limitation	January 2004
Tank Removal	August 2004
USACE Wetland Delineation	2007
Massachusetts Department of Conservation and Recreation	2007
(MassDCR) Due Diligence Investigation	
Supplemental Field Investigation	2008
Governing program changed from the MCP to the DERP-FUDS Program in accordance with CERCLA	2009-2010
Supplemental Field Investigation	2010
Remedial Investigation/Feasibility Study (RI/FS) completed, documenting polychlorinated biphenyls (PCBs) and dioxin	September 2011
Proposed Plan Approved	November 2011
Decision Document	May 23, 2012
Remedial Action Work Plan, initial clearing, demolition, and soil	July 2013
sampling completed.	,
Soil cover construction begins with off-site disposal of areas with PCB contamination equal to/or than great than 50 mg/kg	August 15, 2013
Operations and Maintenance Plan approved by USACE and MassDEP	April 16, 2014
Remedial Action removed PCB-contaminated soil, constructed the	September 30, 2014
soil cover and compensatory wetland.	September 30, 2014
Semi-annual and Annual Monitoring	2014 to 2018
First Five-Year Review Report Completed	August 3, 2018
Annual Monitoring	2018 to present



APPENDIX B - PUBLIC NOTICE



11/18/22, 8:37 AM

https://www.masspublicnotices.org/(S(fnnbpzh0msqblcngg2lsa4k0))/DetailsPrint.aspx?SID=fnnbpzh0msqblcngg2lsa4k0&ID=377...

Boston Globe, The

Publication Name: Boston Globe, The

Publication URL: www.boston.com/

Publication City and State:

Boston, MA

Publication County:

Suffolk

Notice Popular Keyword Category:

Notice Keywords: former GSA property

Notice Authentication Number: 202211180736534137178 2361534520

Notice URL:

Back

Notice File:

Notice Publish Date:

707185 VI B0 CBW GLegal Notice 2 Col SLN2C11182022.PDF Friday, November 18, 2022

Notice Content

PLEASE NOTE: The following text was electronically converted from the PDF document above, and may not be 100% accurate. Because of this, please view the PDF for

Public Notice for Start of Second Five-Year Review for the Watertown Arsenal, Former GSA Property, Watertown, Massachusetts The U.S. Army Corps of Engineers (USACE) is conducting the second Five-Year Review (FYR) of the selected rem- edy at the Watertown Arsenal, Former General Services Administration (GSA) Property Formerly Used Defense Site (FUDS) located 670 Arsenal Street, Watertown, Middlesex County, Massachusetts (the Site). The FYR will be conduct- ed in accordance with the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) and the National Oil and Hazardous Substances Pollution Con- tingency Plan (NCP) under the Defense Environmental Res- toration Program (DERP). FYRs provide an opportunity to evaluate the implementation and performance of a rem- edy to determine whether it remains protective of human health and the environment. Generally, reviews take place five years following the start of a CERCLA r

Web display limited to 1,000 characters. Please view the PDF for the complete Public Notice.



Public Notice for Start of Second Five-Year Review for the Watertown Arsenal, Former GSA Property, Watertown, Massachusetts

Watertown Arsenal, Former GSA Property, Watertown, Massachusetts

The US Army Corps of Engineers (USACE) is conducting the second Five-Year Review (FYR) of the selected remedy at the Watertown Arsenal, Former General Services Administration (GSA) Property Formerly Used Defense Site (FUDS) located 670 Arsenal Street, Watertown, Middlesex County, Massachusetts (the Site). The FYR will be conducted in accordance with the Comprehensive Environmental Response, Compensation, and Liability Act (CERCLA) and the National Oil and Hazardous Substances Pollution Contingency Plan (NCP) under the Defense Environmental Restoration Program (DERP). FYRs provide an opportunity to evaluate the implementation and performance of a remedy to determine whether it remains protective of human health and the environment, Generally, reviews take place five years following the start of a CERCLA response action and are repeated every succeeding five years so long as future uses remain restricted. The selected remedy included excavation and removal of PCB contaminated soils, installation of soil and geotextile fabric cover over residual PCB contaminated soils, Land Use Control annual notification, and annual inspections.

If the review identifies issues that affect protectiveness, the Five-Year Review report will recommend improvements. USACE plans to issue the final Five-Year Review in August 2023.

The public is invited to provide any information regarding this site that it deems relevant to the review process and is requested to postmark comments no later than December 31, 2022. Public input should be directed to the U.S. Army's point of contact listed below. Upon completion of the FYR, the report will be placed in the Information Repository, and another public notice will be review.

Information Repository Watertown Free Public Library 123 Main Street Watertown MA 02472

Administrative Record
The Administrative Record can be found at:
USACE-New England District Office
696 Virginia Road
Concord, MA 01742
The Administrative Record can also be found through the
USACE-New England District website for the Watertown
GSA F UDs. https://www.nae.usace.army.mil/Missions/Projects-Topics/Watertown-Arsenal-FUDS/

For more information, or to send comments, please contact:

Jeffrey A. Dvorak USACE New England District 696 Virginia Road, Concord, MA 01742 (978) 318-8464 jeffrey a dvorak@usace army mil



APPENDIX C - ARAR	. RISK ASSESSMENT	ASSUMPTIONS.	, AND TOXICITY REVIEW
-------------------	-------------------	--------------	-----------------------



1.0 REVIEW OF ARARS

Applicable or Relevant and Appropriate Requirements (ARARs) for the site were identified in the Decision Document (USACE, 2012) are shown in Table C-1 and include the following:

- Massachusetts Surface Water Quality Standards (chemical specific)
- Federal Toxic Substance & Control Act (TSCA) on Storage and Disposal (action specific)
- Federal TSCA regulations on Decontamination (action specific)
- Federal Compensatory Mitigation for Losses of Aquatic Resources (Federal location specific)

No "To-Be Considered" criteria were identified in the Decision Document.

The Federal TSCA ARARs are action specific and do not apply to operation and maintenance. The Decision Document highlighted the Massachusetts Surface Water Quality Standards chemical specific criteria as ARARs. The remedial action is complete and has achieved those standards as applicable.

2.0 HUMAN HEALTH TOXICITY AND CHEMICAL CHARACTERISTICS

Examination of the EPA's Integrated Risk Information System (www.epa.gov/iris) indicates no change to the toxicity values assigned to COCs identified in the 2012 Decision Document, so the cleanup goals remain protective.

3.0 HUMAN HEALTH EXPOSURE ASSESSMENT

The following exposure pathways were evaluated in the 2011 Human Health Risk Assessment:

- Park Visitors (adults and children) by incidental ingestion of, dermal contact with, and inhalation of particulates entrained from soil.
- Occupational Workers by incidental ingestion of, dermal contact with, and inhalation of particulates entrained from soil.
- Construction Worker by incidental ingestion of, dermal contact with, and inhalation of particulates from total soil during excavation activities.

Several of the exposure factors used in the derivation of the risk in 2011 have been updated and changed since. Table C-2 below compares the original exposure factors used with the updated exposure factors. As the variables in the exposure equations are directly related to changes in the resulting risk values, the intake equation ouputs were also updated in Table C-3 to show how the risks would be altered using updated exposure values. Ratios displayed in Table C-3 that are less than unity exhibit how the resulting risk characterization would be lowered if recalculated, conversely, ratios greater than one would exhibit greater risks. Future construction worker and occupation worker intakes (and also resulting calculated risks) would decrease with the new exposure factors while the future adult recreator intakes both increased and decreased and the future child recreator's intakes were mostly increased in value which would result in overall greater risk. In all exposure pathways however, the risk assumes that the receptors can encounter site soils, however, the cap remains in place and therefore there is no



complete exposure pathway and no concomitant risk, regardless of changes in exposure values.



Table C-1. Applicable or Relevant and Appropriate Requirements (USACE, 2012).

REGULATORY AUTHORITY	AREA	CHEMICAL, ACTIVITY, OR LOCATION SPECIFIC	REQUIREMENT	STATUS	REQUIREMENT SYNOPSIS	ACTION TO BE TAKEN TO ATTAIN REQUIREMENT
State	Surface Water	Chemical Specific	Massachusetts Surface Water Quality Standards [314 CMR 4.04 (1) and (7)4.]	Applicable	Protection of Existing Uses. In all cases existing uses and the level of water quality necessary to protect the existing uses shall be maintained and protected.	Cleanup actions will be designed, implemented, and monitored to attain Massachusetts Surface Water Quality Standards if site surface water is generated (e.g., construction dewatering).
Federal	TSCA	Action Specific	TSCA [40 CFR Part 761.61b Subpart D] Storage and Disposal	Relevant and Appropriate	Performance-based disposal. Disposing of non- liquid PCB remediation waste by a chemical waste landfill has been approved.	These requirements were incorporated into a remedial action that results in the excavation, transport, and disposal of PCB impacted soils.
Federal	TSCA	Action Specific	TSCA regulations on Decontamination [40 CFR 761.79 (b), I, (g)]	Applicable	This regulation applies to concentrations of PCBs >50 ppm and establishes decontamination standards and procedures for removing PCBs from water, organic liquids, and various types of surfaces including equipment used in excavation or other handling of PCB containing materials.	These requirements would be attained through the proper use of decontamination procedures.
Federal	Wetlands	Location Specific	40 CFR Part 230.93 (f), (1) Compensatory Mitigation for Losses of Aquatic Resources	Relevant and Appropriate	Requires a compensation ratio of at least one-to- one by acreage or linear foot for lost aquatic resources.	These requirements were incorporated into remedial actions that result in the loss of wetlands.



Table C-2. Updated Exposure Values - Comparison.

	Future Occupational Worker (OLD)	Future Occupational Worker (NEW)	Future Construction Worker (OLD)	Future Construction Worker (NEW)
Exposure Value				
soil ingestion rate ¹	50 mg/day	50 mg/day	110 mg/day	100 mg/day
skin surface area ¹	3473 cm ²	3473 cm ²	3473 cm ²	5653 cm ²
adherence factor ¹	0.03 mg/cm ²	0.03 mg/cm ²	0.29 mg/cm ²	.19 mg/cm ²
body weight ²	61.1 kg	80 kg	58 kg	80 kg
exposure duration	27 yr *	27 yr *	1 yr ¹	1 yr ¹

Exposure Value	Future Child Recreator - Subchronic (OLD)	Future Child Recreator - Subchronic (NEW)	Future Young Child Visitor (OLD)	Future Young Child Visitor (NEW)	Future Older Child Visitor (OLD)	Future Older Child Visitor (NEW)
soil ingestion rate ¹	100 mg/day	100 mg/kg	100 mg/day	100 mg/day	50 mg/day	50 mg/day
skin surface area	1670 cm ²	1840 cm ²	2431 cm ²	2431 cm ²	4427 cm ²	4427 cm ²
adherence factor	0.35 mg/cm ²	.35 mg/cm ²	0.35 mg/cm ²	.35 mg/cm ²	0.14 mg/cm ²	.14 mg/cm ²
body weight ²	10.7 kg	10.7 kg	17 kg	18.6 kg	39.9 kg	56.8 kg
exposure duration	1 yr ¹	1 yr 1	7 yr *	7 yr *	7 yr ³	6 yr ³



Table C-2. Updated Exposure Values - Comparison. (Continued)

Exposure Value	Future Adult Recreator (OLD)	Future Adult Recreator (NEW)
soil ingestion rate ¹	50 mg/day	50 mg/day
skin surface area ¹	5653 cm ²	5653 cm ²
adherence factor ¹	0.13 mg/cm ²	0.13 mg/cm ²
body weight ²	58.7 kg	80 kg
exposure duration	16 yr ³	26 yr ³

Sources:

1. Massachusetts Department of Environmental Protection (MADEP).

Occupational and Construction workers: MCP Numerical Standards Development Spreadsheets. Values for S-2 Soil (Occupational Worker) and S-3 (Construction Workers). OLD values are from 2009 edition; NEW values are from 2014 edition. (https://www.mass.gov/lists/risk-assessment-information).

Parameter values for Park Visitor Short Form (Adult and Child). OLD values are from 2007 edition; NEW values are from 2012 edition. (https://www.mass.gov/lists/risk-assessment-information).

- 2. United States Environmental Protection Agency (USEPA). Exposure Factors Handbook, October 2011. Chapter 8: Body Weight Studies.
- 3. USEPA. Regional Screening Levels (RSLs) Equations, May 2023. Recreator for Soil/Sediment, Adult and Child.
- * = assumption made in RI/FS report from 2011



Table C-3. Intake Equation Differences based on Updated Exposure Values.

Intake Equation	Future Occupational Worker (OLD)	Future Occupational Worker (NEW)	Ratio (new/old)
nc intake-ingestion = (IR x ED x CF1)/(BW x AT x CF2)	2.242E-09	1.71233E-09	0.76
nc intake-dermal = (SA x AF x ED x CF1)/(BW x AT x CF2)	4.67188E-09	3.56815E-09	0.76
c intake-ingestion = (IR x ED x CF1)/(BW x AT x CF2)	8.64772E-10	6.6047E-10	0.76
c intake-dermal = (SA x AF x ED x CF1)/(BW x AT x CF2)	1.80201E-09	1.37629E-09	0.76

Intake Equation	Future Construction Worker (OLD)	Future Construction Worker (NEW)	Ratio (new/old)
nc intake-ingestion = (IR x ED x CF1)/(BW x AT x CF2)	1.03921E-08	6.84932E-09	0.66
nc intake-dermal = (SA x AF x ED x CF1)/(BW x AT x CF2)	9.51507E-08	7.35664E-08	0.77



Table C-3. Intake Equation Differences based on Updated Exposure Values.

Intake Equation	Future Construction Worker (OLD)	Future Construction Worker (NEW)	Ratio (new/old)
c intake-ingestion = (IR x ED x CF1)/(BW x AT x CF2)	7.4229E-11	4.89237E-11	0.66
c intake-dermal = (SA x AF x ED x CF1)/(BW x AT x CF2)	6.79648E-10	5.25475E-10	0.77

Intake Equation	Future Adult Recreator (OLD)	Future Adult Recreator (NEW)	Ratio (new/old)
nc intake-ingestion = (IR x	2.33367E-09	1.71233E-09	0.73
ED x CF1)/(BW x AT x CF2)			
nc intake-dermal = (SA x AF x ED x CF1)/(BW x AT x CF2)	2.14374E-09	9.67979E-10	0.45
c intake-ingestion = (IR x ED x CF1)/(BW x AT x CF2)	5.3341E-10	6.36008E-10	1.19
c intake-dermal = (SA x AF x ED x CF1)/(BW x AT x CF2)	4.89997E-10	3.59535E-10	0.73



Table C-3. Intake Equation Differences based on Updated Exposure Values. (Continued)

Intake Equation	Future Child Recreator - Subchronic (OLD)	Future Child Recreator - Subchronic (NEW)	Ratio (new/old)
nc intake-ingestion = (IR x ED x CF1)/(BW x AT x CF2)	4.41464E-08	4.41464E-08	1.00
nc intake-dermal = (SA x AF x ED x CF1)/(BW x AT x CF2)	2.58036E-07	2.84303E-07	1.10
c intake-ingestion = (IR x ED x CF1)/(BW x AT x CF2)	3.65785E-10	3.65785E-10	1.00
c intake-dermal = (SA x AF x ED x CF1)/(BW x AT x CF2)	2.13801E-09	2.35565E-09	1.10



4.0 HUMAN HEALTH RISK RESULTS

Risks above target action levels (i.e., Excess Lifetime Cancer Risk > 1E10⁻⁴ and/or Hazard Index >1) were found for the future park visitors for the following areas and media:

- The PCB Impacted Area (Figure 1) could pose risks to human health that exceed NCP risk management criteria based on presumed exposure to PCBs, antimony, lead, and nickel in soil (0 to 3 ft below ground surface [bgs]).
- Surface soil (soil 0 to 3 ft bgs) Area Outside of the PCB Impacted Area would not pose risks to human health in excess of the NCP risk management criteria.
- Subsurface soil throughout the site at 3 to 15 ft bgs would not pose risks to human health in excess of NCP risk management criteria if the public was fully exposed to these soils (e.g., ground surface).

It should be noted there have not been any changes in the physical site conditions that could affect the protectiveness of the remedy.

5.0 ECOLOGICAL RISK ASSESSMENT RESULTS

The Ecological Risk Assessment (ERA) evaluated the following:

- Robin: ingestion of soil, ingestion of invertebrates and plants that have accumulated COPCs from soil;
- Shrew: ingestion of soil, ingestion of invertebrates, plants, and other small mammals that have accumulated COPCs from soil; and
- Raccoon: ingestion of soil and invertebrates that have accumulated COPCs from soil.

The ERA of the PCB Impacted Area concluded:

- HQs for individual contaminants, as indicators of the potential for hazard, were greater than 1 indicating the potential for hazards at the site may be greater than at background areas for robins and shrews at the PCB Impacted Area.
- HQs for individual contaminants were less than 1 for raccoons at the PCB Impacted Area.
- Site-related COCs were identified as PCB Aroclors, dioxin TEQ, antimony, lead and nickel based on incremental hazard No Observed Adverse Effect Level (NOAEL) and Lowest Observed Adverse Effect Level (LOAEL) HQs greater than 1.
- When the PCB Impacted Area is excluded, the site poses no significant hazard to environmental receptors.

6.0 BASIS FOR REMEDIATION GOALS

The only two COCs with Site Remediation Goals (RGs) based on risk were nickel (No Observed Adverse Effect Level for the Shrew) and PCBs (2005 EPA guidance). Antimony and lead RGs were based on background, and the dioxin RG was based on "other areas around the site."



APPENDIX D - FIVE-YEAR REVIEW INTERVIEWS



INTERVIEW DOCUMENTATION FORM The following is a list of individuals interviewed for this five-year review. See the attached contact record(s) for a detailed summary of the interviews. Project Manager, Federal Facilities Joanne Dearden Program MassDEP 4/13/2023 Title/Position Name Organization Date Title/Position Organization Name Date Name Title/Position Organization Date Organization Title/Position Name Date Title/Position Organization Name Date Title/Position Organization Name Date



INTERVIEW RECORD						
Site Name: Former GSA Property	, FUDS #D01MA0	01902	EPA ID No.: N/A	A		
Subject: Five-Year review for: For Year Review	rmer GSA Propert	y, Second Five-	Time: 10:00	Date:4/13/2023		
Type: ■ Telephone □ Visit □ Other Location of Visit: Web Based interview			☐ Incoming	□ Outgoing		
	Contact	Made By:				
Name: Jeffrey Dvorak	Name: Jeffrey Dvorak Title: Lead Author			Organization: USACE North Atlantic Division		
	Individual	Contacted:				
Name: Joanne Dearden	Title: Project Ma Facilities Progra		Organization: Nof Waste Site Cl	MassDEP Bureau eanup		
Telephone No: (781) 407-1595		Street Address	100 Cambridge	Street, Suite 900		
Fax No: N/A E-Mail Address: joanne.dearden(@state.ma.us	City, State, Zip:	Boston, MA 021	14		
Summary Of Conversation						
Q1: What is your overall impression of the project and site? A1: The project appears to be going well and stakeholders historically have been happy with the outcome. The Remedy is performing as expected; one of the sticking points is the maintenance of the drainage swale. USACE has been responsive to fixing observed minor disturbances to the soil cover including burrows & run-off channeling.						

soil cover including burrows & run-off channeling.

Q2: Are you aware of any issues the five-year review should focus on?

A2: No. Timely maintenance and cleaning of the drainage swale is important and although not a current issue, the chances it becomes an issue are greatly reduced by continuing with the annual inspections, O&M, and keeping the lines of communication among stakeholders open.

Q3: Who should USACE speak to in the community to solicit local input?

A3: in the past 5 years, I haven't received any interest from the public, but historical contact regarding the project has been from the former RAB group, the adjacent property owners, the condominium association, and the City of Watertown.

Q4: Is the remedy functioning as expected?

A4: Yes. Note - as long interaction of stakeholders and the O&M is being followed.

Q5: Is the Town actively involved in the site or do they show an active interest?

A5: Yes, the city is, but public has had limited interest since the remedial action was completed.

Q6: Have there been any changes in the site or surrounding property in the last 5 years, or are changes planned?



INTERVIEW RECORD

Site Name: Former GSA Property, FUDS #D01MA001902 EPA ID No.: N/A

A6: There has been none onsite since the remedial action was completed. MassDCR will address future plans for the site. Surrounding the site there appears to be much more commercial and retail development since the completion of the remedial action. The City of Watertown would have more information on property/ usage changes.

Q7: Does MassDEP have any questions about the previous five years or the project in general?

Ā7: No current questions/issues. As far as future use, any future development would need to be in accordance with the Decision Document, O&M Plan and GERE.



APPENDIX E - DATA ANALYSIS



1.0 DEM ANALYSIS

To determine possible change in the soil cap condition over time, the most recent elevation data were compared to post-construction elevation data (as-built survey). The first FYR utilized lidar data cited as being from 2015; however, the date of collection of this data was actually 2013 to 2014 (USGS, 2015). This 2013-2014 lidar was collected over the span of over 1 year and the project area was flown prior to the construction of the soil cap (cover area) being completed, resulting in irregular surface with drop-off on the southern side of the cap (instead of smooth mound surface).

The contours utilized as post-construction survey elevations in the first FYR were found to be design contours. For this FYR, as-built contours were utilized from Holmberg and Howe 2014 (page 130 of Final RACR) which were in NAVD 88 feet. To make a smooth surface from these contours, half-foot contours were created mid-way between each 1-foot contour. In addition, contours were created to capture high points on the south end of the soil cap that fell slightly below 1-foot contour (e.g., 13.96 ft). A raster surface was created from these contours (Feature to Raster) which was then smoothed (Focal Statistics). This created surface retained more characteristics of the original contours than prior effort (Topo to Raster) which eliminated high points of the cap.

There was only one available lidar data set collected post construction of the soil cap, collected March-April 2021 (USGS, 2021). This dataset met American Society for Photogrammetry and Remote Sensing (ASPRS) standards with a non-vegetated vertical accuracy (95% confidence level) of 19.6 cm. Ground point spacing was 0.5 m and the vertical datum was NAVD 88 meters. From this dataset, classified ground points were selected, and a DEM was created with a 0.5 m (1.64 ft) cell size. Elevation was converted from meters to feet. The created 2021 surface was subtracted from the 2014 surface to produce an estimated difference or delta/change surface between the present and when soil cap was constructed. This delta surface (Figure 4) is an approximation due to the 2014 contour surface being modeled. A more accurate difference was added to Figure 4 (purple numbers) using the exact measurements called out on the 2014 asbuilt survey (e.g., specific points where surveyor added exact elevation like 13.25 ft) along with points on the contour lines where were assumed to be the value of that contour (e.g., point on 8 ft contour line = 8 ft). The value at these exact points on the 2021 DEM were subtracted from the 2014 points.

The 2014 to 2021 differenced or delta surface shows a range of 1.7 ft to –1.3 feet where positive values show areas where the 2014 elevation is higher and negative values show areas where the 2021 elevation is higher. However, the range in difference at exact points was 0.55 to –0.32 ft indicating a much smaller deviation. Potential reasons for the 2014 elevation being higher could be soil cover settling or sod depletion. This was confirmed by March 2023 site visit where the top of the south end of the mound appeared to have a depression and sod disturbance (Figure F-1). Reasons for the 2021 elevation being higher (negative numbers) on the perimeter of the soil cover area could be 2014 boundary boulders moved during 2022 or armor stone bank stabilization placement over time.



APPENDIX F - MARCH 2023 FIVE-YEAR REVIEW SITE INSPECTION






Figure F-1. March 2022 Site Visit Notes (Holmberg and Howe, 2018, Maxar, 2022).



I. SITE INFORMATION					
Site Name: Former GSA Property	Date of inspection: March 31, 2023				
Location and Region: Watertown MA, Region I	EPA ID: Not on the NPL				
Agency, office, or company leading the five- year review: USACE New England District	Weather/temperature: Sunny, 40-44°F, winds <10 mph				
Remedy Includes: (Check all that apply) Landfill cover/containment Monitored natural attenuation Access controls Groundwater containment Institutional controls Vertical barrier walls Groundwater pump and treatment Surface water collection and treatment Other storm water runoff ditches and drain					
Attachments: ■ Inspection team roster attached	■ Site map attached Check all that apply)				
-					
Name Interviewed □ at site □ at office □ by phone Pl Problems, suggestions; □ Report attached This site does not have an onsite O&M Site Management of the problems.	Title Date				
2. O&M staffName	Title Date				
Interviewed at site at office by phone Phone no. Problems, suggestions; Report attached This site does not have an onsite O&M staff. The USACE FYR geotechnical and ecology team members conducted annual soil cover and compensatory wetlands inspections since the last review.					
Inspection Team:					
Jeff Dvorak	Lead Author				
Drew Clemens	Hydrogeologist				



respons	al regulatory authorities and response office, police department, office of per of deeds, or other city and county office	ublic health or envir	onmental health,				
	Agency <u>MassDCR</u>						
	Contact Muhammad Chowdhury Assis. Dir. Boston Region 31 March 2023 (857)-270-8697						
	Name	Title	Date	Phone no.			
	Problems; suggestions; □ Report attac Leaves block ditch drain and check da		OCR will be addr	essing this year.			
	Agency MassDEP						
		Manager, Facilities Program Title Ched	March 31, 2023 Date	(781) 407-1595 Phone no.			
	Agency <u>City of Watertown</u> Contact <u>Katie Swan</u> <u>Environmer</u> Name (857) 303-9427 Phone no. Problems; suggestions; Report attack	ntal Planner/ Conser Title ched	vation Agent <u>I</u>	March 31, 2023 Date			
	Agency Contact Name Problems; suggestions; □ Report attack	Title ched	Date	Phone no.			
4	Other internal control of the contro	attacks d					
4.	Other interviews (optional) Report	. апаспеа.					



	III. ON-SITE DOCUMENTS & RE	CORDS VERIFIED (Che	eck all that app	ly)
1.	O&M Documents ■ O&M manual ■ As-built drawings □ Maintenance logs Remarks <u>Drawing files have no layer dinspection Google Earth Maps do not logack scale bars & north arrows.</u>			
2.	Site-Specific Health and Safety Plan Contingency plan/emergency response Remarks_Site Safety and Health Plan was Prevention Plan & Activity Hazard Analysis	se plan □ Readily availa	able □ Up to	o date ■ N/A
3.	O&M and OSHA Training Records Remarks		■ Up to date	□ N/A
4.	Permits and Service Agreements Air discharge permit Effluent discharge Waste disposal, POTW Other permits Remarks	□ Readily available □ Readily available □ Readily available □ Readily available	□ Up to date □ Up to date □ Up to date □ Up to date	■ N/A ■ N/A ■ N/A ■ N/A
5.	Gas Generation Records Remarks	□ Readily available	□ Up to date	■ N/A
6.	Settlement Monument Records Remarks No settlement monuments we	□ Readily available ere installed as part of the	•	■ N/A
7.	Groundwater Monitoring Records Remarks_	□ Readily available	□ Up to date	■ N/A
8.	Leachate Extraction Records Remarks	□ Readily available	□ Up to date	■ N/A
9.	Discharge Compliance Records □ Air □ Water (effluent) Remarks	□ Readily available □ Readily available	□ Up to date □ Up to date	■ N/A ■ N/A
10.	Daily Access/Security Logs Remarks	□ Readily available	□ Up to date	■ N/A



		IV. O&M COSTS	
1.	O&M Organization ■ State in-house □ PRP in-house □ Federal Facility in-house □ Other	☐ Contractor for State ☐ Contractor for PRP ☐ Contractor for Federal Fac	sility
2.	■ Funding mechanism/agreem Original O&M cost estimate <u>\$5</u>		
	From 1 OCT 18 To 30 SEP 1 Date Date From 1 OCT 19 To 30 SEP 1 Date Date From 1 OCT 20 To 30 SEP 2 Date Date From 1 OCT 21 To 30 SEP 2 Date Date From 1 OCT 22 To 30 SEP 2 Date Date Date Date Date	8 \$55,000 Total cost 9 \$21,000 Total cost 20 \$14,000 Total cost 21 \$26,000 Total cost	 □ Breakdown attached
3.	Unanticipated or Unusually In Describe costs and reasons: none	High O&M Costs During Rev	iew Period

Breakdown of USACE operations, maintenance, and monitoring costs by fiscal year. MassDCR are not included.

Fiscal Year	Soil Cover	Compensatory Wetlands	Project Management	Total	Notes
FY19 Actuals	\$20,000	\$0	\$35,000	\$55,000	
FY20 Actuals	\$12,000	\$0	\$7,000	\$21,000	
FY21 Actuals	\$8,000	\$0	\$6,000	\$14,000	
FY22 Actuals	\$16,000	\$0	\$10,000	\$26,000	
FY23 Projected	\$50,000	\$0	\$40,000	\$90,000	Second Five-Year Review



	V. ACCESS AND INSTITUTIONAL CONTROLS ■ Applicable □ N/A
Α.	Fencing
1.	Fencing damaged □ Location shown on site map ■ Gates secured □ N/A Remarks Fence and gates are in good condition.
В.	Other Access Restrictions
1.	Signs and other security measures □ Location shown on site map □ N/A Remarks Posted signs on access gate and fence are secured and legible, most of the compensatory wetlands' signs are missing.
C.	Institutional Controls (ICs)
1.	Implementation and enforcement Site conditions imply ICs not properly implemented Site conditions imply ICs not being fully enforced Yes No N/A
2.	Adequacy ■ ICs are adequate □ ICs are inadequate □ N/A Remarks Soil cover is in good condition with minor ruts from lawn mower, minor settlement observed at the site and in the DEM comparison (none holding water). No animal burrows were found. Boulders marking end of cap material on the north side were pushed to the mowing perimeter. Tree roots daylight at one spot on the cap's western margin.
υ.	General
1.	Vandalism/trespassing □ Location shown on site map ■ No vandalism evident Remarks
2.	Land use changes on site □ N/A Remarks No change in land use since construction completed.
3.	Land use changes off site □ N/A Remarks No change in land use since construction completed.

VI. GENERAL SITE CONDITIONS



_	
A.	Roads ■ Applicable □ N/A
1.	Roads damaged □ Location shown on site map ■ Roads adequate □ N/A Remarks Access road is in good condition.
В.	Other Site Conditions
	Remarks Overall site is in good condition. Vegetation in the drainage swales has been cut down and awaiting herbicide treatment for root removal. Debris covering the catch basin was pulled back, but leaves surrounding the basin and on upstream sides of check dams needs to be removed. Check dams should be regularly maintained during annual cap and swale maintenance activities.
_	VII. LANDFILL COVERS ■ Applicable □ N/A
	Landfill Surface
1.	Settlement (Low spots) ■ Location shown on site map □ Settlement not evident Areal extent Most is located on the SW portion of the cover (see map) □ Depth_< 1 ft Remarks: Settlement is assessed by quantitatively comparing most recent bare earth digital elevation model (DEM) with historic DEMs and estimated post construction survey data model (contours developed from several spot elevations). About half of the original 34 metal pin disks marking the geotextile boundary are missing (unclear if the result of vandalism or cap mowing).
2.	Cracks □ Location shown on site map ■ Cracking not evident Lengths Widths Depths Remarks
3.	Erosion □ Location shown on site map ■ Erosion not evident Areal extent □ Depth □ Remarks □ □ Location shown on site map ■ Erosion not evident
4.	Holes □ Location shown on site map ■ Holes not evident Areal extent Depth Remarks Rodent holes noted in 2022 annual inspection appear filled in with topsoil.
5.	Vegetative Cover ■ Grass ■ Cover properly established ■ No signs of stress □ Trees/Shrubs (indicate size and locations on a diagram) Remarks Sod cover on the southern and northern portions is thin.
6.	Alternative Cover (armored rock, concrete, etc.) Remarks
7.	Bulges □ Location shown on site map ■ Bulges not evident Areal extent □ Height □ Remarks □ □ Location shown on site map ■ Bulges not evident
I	



8.	Wet Areas/Water Damage Use Wet areas Soft subgrade Remarks	■ Wet areas/water damage not evident □ Location shown on site map Areal extent □ Location shown on site map Areal extent □ Location shown on site map Areal extent □ Location shown on site map Areal extent
9.	Slope Instability Slide Areal extent Remarks	s □ Location shown on site map ■ No evidence of slope instability
B. Bei		nds of earth placed across a steep landfill side slope to interrupt n the velocity of surface runoff and intercept and convey the
1.	Flows Bypass Bench Remarks	□ Location shown on site map □ N/A or okay
2.	Bench Breached Remarks	□ Location shown on site map □ N/A or okay
3.	Bench Overtopped Remarks_	□ Location shown on site map □ N/A or okay
C. Let		ntrol mats, riprap, grout bags, or gabions that descend the steep I allow the runoff water collected by the benches to move off of
1.	Areal extent	ation shown on site map □ No evidence of settlement Depth
2.	Material Degradation □ Loc Material type Remarks	
3.	Erosion □ Loc Areal extent Remarks	
4.	Undercutting □ Loc Areal extent Remarks	



5.	Obstructions Type
6.	Excessive Vegetative Growth No evidence of excessive growth Vegetation in channels does not obstruct flow Location shown on site map Remarks
D. Co	ver Penetrations □ Applicable ■ N/A
1.	Gas Vents
2.	Gas Monitoring Probes □ Properly secured/locked □ Functioning □ Routinely sampled □ Good condition □ Evidence of leakage at penetration □ Needs Maintenance □ N/A Remarks
3.	Monitoring Wells (within surface area of landfill) □ Properly secured/locked □ Functioning □ Routinely sampled □ Good condition □ Evidence of leakage at penetration □ Needs Maintenance □ N/A Remarks
4.	Leachate Extraction Wells □ Properly secured/locked □ Functioning □ Routinely sampled □ Good condition □ Evidence of leakage at penetration □ Needs Maintenance □ N/A Remarks
5.	Settlement Monuments



E.	Gas Collection and Treatment □ Applicable ■ N/A
1.	Gas Treatment Facilities Flaring
2.	Gas Collection Wells, Manifolds and Piping Good condition Needs Maintenance Remarks
3.	Gas Monitoring Facilities (e.g., gas monitoring of adjacent homes or buildings) □ Good condition □ Needs Maintenance □ N/A Remarks
F.	Cover Drainage Layer □ Applicable ■ N/A
1.	Outlet Pipes Inspected □ Functioning □ N/A Remarks
2.	Outlet Rock Inspected □ Functioning □ N/A Remarks
G.	Detention/Sedimentation Ponds □ Applicable ■ N/A
1.	Siltation Areal extent Depth □ N/A □ Siltation not evident Remarks
2.	Erosion Areal extentDepth □ Erosion not evident Remarks
3.	Outlet Works □ Functioning □ N/A Remarks
4.	Dam □ Functioning □ N/A Remarks



H. Ret	taining Walls □ Applicable ■ N/A
1.	Deformations □ Location shown on site map □ Deformation not evident Horizontal displacement Vertical displacement Rotational displacement Remarks
2.	Degradation □ Location shown on site map □ Degradation not evident Remarks □
I. Peri	meter Ditches/Off-Site Discharge ■ Applicable □ N/A
1.	Siltation □ Location shown on site map ■ Siltation not evident Areal extent □ Depth □ Remarks □ □
2.	Vegetative Growth □ Location shown on site map □ N/A ■ Vegetation does not impede flow Areal extent ~5000 sq feet □ Type Reeds and cat tails Remarks Vegetation was trimmed to near ground surface in late 2022 and is awaiting herbicide treatment by MassDCR to remove remaining stalks and roots. A few Spring 2022 growth patches remain in the northern ditch. Potential settlement in the drainage ditch is restricting flow on the northeast corner of the cap. Staining similar to iron oxidation is present on the southeastern part of the ditch system, with high water marks indicating seasonal and/or storm-related ponding occurs. Ponding is exacerbated by leaf debris clogging the drainage grate and the six check dams.
3.	Erosion □ Location shown on site map ■ Erosion not evident Areal extent □ Depth □ Remarks □
4.	Inlet/Discharge Structure ■ Functioning □ N/A Remarks Catch basin grate originally obstructed by leaf litter from late 2022 vegetation trimming. Once leaf litter was cleared from the grate by the inspection team, ponded surface water began to discharge into the catch basin. Discharge pipe was submerged by about 4 inches of standing water, but flow was observed from the pipe after removing debris from inlet grate. The inspection team noted the location of the catch basin and associated discharge pipe across Greenough Boulevard. differs from construction drawings by approximately 24 meters. This has since been corrected in all figures associated with the FYR.



	VIII. VERTICAL BARRIER WALLS □ Applicable ■ N/A
1.	Settlement
2.	Performance Monitoring □ Performance not monitored Frequency Head differential Remarks
	IX. GROUNDWATER/SURFACE WATER REMEDIES □ Applicable ■ N/A
A. Gro	oundwater Extraction Wells, Pumps, and Pipelines □ Applicable □ N/A
1.	Pumps, Wellhead Plumbing, and Electrical □ Good condition □ All required wells properly operating □ Needs Maintenance □ N/A Remarks
2.	Extraction System Pipelines, Valves, Valve Boxes, and Other Appurtenances Good condition Remarks
3.	Spare Parts and Equipment □ Readily available □ Good condition □ Requires upgrade □ Needs to be provided Remarks
B. Sui	rface Water Collection Structures, Pumps, and Pipelines □ Applicable □ N/A
1.	Collection Structures, Pumps, and Electrical Good condition Needs Maintenance Remarks
2.	Surface Water Collection System Pipelines, Valves, Valve Boxes, and Other Appurtenances Good condition Remarks
3.	Spare Parts and Equipment □ Readily available □ Good condition □ Requires upgrade □ Needs to be provided Remarks



C.	Treatment System □ Applicable □ N/A
1.	Treatment Train (Check components that apply) Metals removal
2.	Electrical Enclosures and Panels (properly rated and functional) N/A Good condition Needs Maintenance Remarks
3.	Tanks, Vaults, Storage Vessels □ N/A □ Good condition □ Proper secondary containment □ Needs Maintenance Remarks
4.	Discharge Structure and Appurtenances □ N/A □ Good condition □ Needs Maintenance Remarks
5.	Treatment Building(s) □ N/A □ Good condition (esp. roof and doorways) □ Needs repair □ Chemicals and equipment properly stored Remarks
6.	Monitoring Wells (pump and treatment remedy) □ Properly secured/locked □ Functioning □ Routinely sampled □ Good condition □ All required wells located □ Needs Maintenance □ N/A Remarks



D. Mo	nitoring Data
1.	Monitoring Data
	□ Is routinely submitted on time □ Is of acceptable quality
2.	Monitoring data suggests:
	□ Groundwater plume is effectively contained □ Contaminant concentrations are declining
E. Mo	onitored Natural Attenuation
1.	Monitoring Wells (natural attenuation remedy) □ Properly secured/locked □ Functioning □ Routinely sampled □ Good condition □ All required wells located □ Needs Maintenance □ N/A Remarks
	X. OTHER REMEDIES
If there are remedies applied at the site which are not covered above, attach an inspection sheet describing the physical nature and condition of any facility associated with the remedy. An example would be soil vapor extraction. No other remedies are implemented at this Site.	

XI. OVERALL OBSERVATIONS

A. Implementation of the Remedy

Describe issues and observations relating to whether the remedy is effective and functioning as designed. Begin with a brief statement of what the remedy is to accomplish (i.e., to contain contaminant plume, minimize infiltration and gas emission, etc.).

The Remedial Action Objectives for the site are to reduce human health and ecological risks associated with exposure to polychlorinated biphenyls, dioxins, and metals in the PCB impacted area. The soil cover does show signs of settlement in the southwest portion, but it is unknown if this occurred soon after construction or since the last FYR. The filter fabric does not appear to be penetrated by burrowing rodents, for the filled burrow spoils contain no filter fabric debris and the burrow depths are less than the designed filter fabric depth. Trees and brush are not present on the soil cover, but tree roots are exposed in one location. See Figure F-1 for location of observations.

B. Adequacy of O&M

Describe issues and observations related to the implementation and scope of O&M procedures. In particular, discuss their relationship to the current and long-term protectiveness of the remedy.

The Operation and Maintenance Plan inspection requirements adequately address all facets of soil cover and compensatory wetlands maintenance and monitoring. Identified issues (e.g., burrows, invasive plant species, need for replacement plantings, drainage swale vegetation removal), were or are being addressed by MassDCR and USACE.

<u>Soil cover perimeter survey markers (survey disks and boulders) may need to be replaced or pushed back in their original location.</u>

Wetland signage may need to be replaced and annual inspection reports need to be routinely completed.

C. Early Indicators of Potential Remedy Problems



XI. OVERALL OBSERVATIONS

Describe issues and observations such as unexpected changes in the cost or scope of O&M or a high frequency of unscheduled repairs that suggest that the protectiveness of the remedy may be compromised in the future.

Excluding the first FYR year, and this projected second FYR year, and the year USACE project management changed project managers, USACE OM&M costs have not exceeded the estimated \$50,000/year cost presented in the decision document. This will be reviewed in the future with concern of inflation and the cost of completing the work.

Armor stone in the drainage swale parallel to Greenough Boulevard contains an iron oxidation coating not present in any other part of the swale system. The oxidation's color is most intense on the swale system's northeast corner and suggests groundwater from underneath the soil cover may seasonally be entering the swale system.

The eastern drainage swale may have a depression preventing water leaving the site.

D. Opportunities for Optimization

Describe possible opportunities for optimization in monitoring tasks or the operation of the remedy.

Continue to evaluate Soil Cover settlement areas comparing post 2022 DEMs to historic DEMs Employ a cellphone-based site assessment app to map annual inspection findings for trend analyses over time.

Complete an annual site survey by a MA licensed surveyor to better quantify low spots in the swale and to confirm the soil cover perimeter.

Conduct a camera inspection of the drainage pipe under Greenough Blvd, repair if needed, and add results to next FYR.

Utilize drone-based methods for annual inspections or next FYR.

Remove leaf litter during dry periods, improving flow through the check dams

Continue to monitor tree roots encroaching the soil cover area.



APPENDIX G - MARCH 31, 2023 SITE VISIT PHOTOS



PHOTOLOG INDEX

Photo 1. Compensatory Wetlands looking northeast, showing one of the few remaining plastic wetland boundary signs64
Photo 2. Compensatory Wetlands looking southwest, showing one of the few remaining plastic wetland boundary signs64
Photo 3. Soil cover looking southwest toward the Compensatory Wetlands, showing good sod cover
Photo 4. Daylighting Tree Roots. Uncertain if these are under or outside the membrane65
Photo 5. Potential former animal burrow surrounded by thin sod cover65
Photo 6. Disk marking soil cover extent. Over half of the original disks appear to be missing
Photo 7. Boulder marking soil cover extent moved into brush line since last review66
Photo 8. Possible depression in Eastern Drainage Swale at the northeast gate, limiting surface water discharge. No inlet grate or off-site discharge pipe present. Sheen in center foreground appears to be organic material, not petroleum67
Photo 9. Leaf litter-clogged Check Dams within the Eastern Drainage Swale; some check dams appear to have had stone material removed from their centers to expedite surface water discharge
Photo 10. Eastern Drainage Swale Inlet Grate with leaf litter blocking grate partially removed
Photo 11. Eastern Drainage Swale Inlet Grate at the end of the site inspection. Triangle shows material removed from the upstream check dam, looking northeast68
Photo 12. Southwestern portion of the soil cover showing minor depressions less than 0.9 feet deep. View is looking east
Photo 13. GSA stormwater discharge pipe (submerged) southeast of Greenough Boulevard70
Photo 14. Disconnected power pole with transformer next to access gate70





Photo 1. Compensatory Wetlands looking northeast, showing one of the few remaining plastic wetland boundary signs.



Photo 2. Compensatory Wetlands looking southwest, showing one of the few remaining plastic wetland boundary signs.



Photo 3. Soil cover looking southwest toward the Compensatory Wetlands, showing good sod cover.





Photo 4. Daylighting Tree Roots. Uncertain if these are under or outside the membrane.

Photo 5. Potential former animal burrow surrounded by thin sod cover; grate hook used for scale.





Photo 6. Disk marking soil cover extent. Over half of the original disks appear to be missing.



Photo 7. Boulder marking soil cover extent moved into brush line since last review.





Photo 8. Possible depression in Eastern Drainage Swale at the northeast gate, limiting surface water discharge. No inlet grate or off-site discharge pipe present. Sheen in center foreground appears to be organic material, not petroleum.



Photo 9. Leaf litter-clogged Check Dams within the Eastern Drainage Swale; some check dams appear to have had stone material removed from their centers to expedite surface water discharge.





Photo 10. Eastern Drainage Swale Inlet Grate with leaf litter blocking grate partially removed.



Photo 11. Eastern Drainage Swale Inlet Grate at the end of the site inspection. Triangle shows material removed from the upstream check dam, looking northeast.





Photo 12. Southwestern portion of the soil cover showing minor depressions less than 0.9 feet deep. View is looking east.

69





Photo 13. GSA stormwater discharge pipe (submerged) southeast of Greenough Boulevard.

Photo 14. Disconnected power pole with transformer next to access gate. (*Removed from site as of April 28, 2023 per MassDCR)

Five-Year Review Report – Second Five-Year Review for Former GSA Property Watertown, Middlesex County, Massachusetts 70 July-2023



THIS PAGE INTENTIONALLY LEFT BLANK