

**REPORT OF CHANNEL CONDITIONS
100 TO 400 FEET WIDE
(ER 1130-2-520)**

PAGE 1 OF 1 PAGES

DATE: **April 18, 2016**

TO: NAVIGATION INTEREST

FROM:

RIVER/HARBOR NAME AND STATE: Bridgeport Harbor, Bridgeport,
Connecticut Dwg. No. BRH-541, Sheet 1 of 1, Dated April 18, 2016

MINIMUM DEPTHS IN
CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (nautical miles)	MLLW DEPTH (feet)			
<p><u>CONDITION SURVEY</u></p> <p><u>Johnsons River</u> <u>15-Foot Channel</u></p> <p>From about 230' upstream of Buoy RN-2 upstream 3,200' to upstream end of channel</p>	2/16	200 to 250 to 100	.53	15.0	(1) 13.8	6.0	(2) 6.9
<p><u>9-Foot Channel</u></p> <p>Thence upstream about 415' to upstream end of channel</p>	2/16	100	.07	9.0	9.0	9.0	8.7

GENERAL NOTE: The information shown on this sheet(s) represents the results of surveys made on the dates indicated and can only be considered as indicating the general conditions existing at that time.

FOOT NOTES:

- (1). Except for shoaling to 11.3' within 15' of limit and shoaling to 9.9' within the last 600' of reach.
- (2). Except for shoaling to 4.0' within 10' of limit.