

**REPORT OF CHANNEL CONDITIONS
LESS THAN 100 FEET WIDE
(ER 1130-2-520)**

DATE: **Mar 15, 2012**

TO:	FROM:
-----	-------

RIVER/HARBOR NAME AND STATE: Stonington Harbor, Stonington, Connecticut Dwg. No. SHC-585, Sheet 1 of 1, Dated 15 March 2012	MINIMUM DEPTHS IN CHANNEL ENTERING FROM SEAWARD
--------------------------------------------------------------------------------------------------------------------------------	-------------------------------------------------

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			DEPTH AVAILABLE
		WIDTH (feet)	LENGTH Nautical (miles)	MLLW DEPTH (feet)	
<u>CONDITION SURVEY</u>					
<u>10-Foot Anchorage</u>	1/12		22.2 acres	10.0	(1) 9.9
<u>12-Foot Anchorage</u>	1/12		17.3 acres	12.0	(2) 11.8

GENERAL NOTE: The information shown on this sheet(s) represents the results of surveys made on the dates indicated and can only be considered as indicating the general conditions existing at that time.

FOOT NOTES:
 (1). Isolated shoaling to 9.9' located in southeastern quadrant within about 130' of southeast anchorage limit; otherwise 10.0' available elsewhere.
 (2). Isolated shoaling to 11.8' located within about 50' of northwest limit; 12.0' available elsewhere.