

**REPORT OF CHANNEL CONDITIONS
LESS THAN 100 FEET WIDE
(ER 1130-2-520)**

DATE: **October 16, 2013**

T0:	FROM:
-----	-------

RIVER/HARBOR NAME AND STATE: Andrews River, Harwich, Massachusetts Dwg. No. AND-61, Sheet(s)1-2 of 2, Dated 16 October 2013	MINIMUM DEPTHS IN CHANNEL ENTERING FROM SEAWARD
--	---

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			DEPTH AVAILABLE
		WIDTH (feet)	LENGTH Nautical (miles)	MLLW DEPTH (feet)	
<u>CONDITION SURVEY</u>					
<u>6-Foot Channel</u>					
From about 260' seaward of Buoy GC-1 upstream 2,750' to the East Jetty Light	08/13	75	0.45	6.0	(1) 4.9
Thence upstream 1,500' to beginning of 6-foot anchorage	08/13	75	0.25	6.0	(2) 5.5
<u>6-FOOT ANCHORAGE</u>	08/13		3.2 acres	6.0	(3) 4.3

GENERAL NOTE: The information shown on this sheet(s) represents the results of surveys made on the dates indicated and can only be considered as indicating the general conditions existing at that time.

FOOT NOTES:

- (1). Shoaling located from 50' seaward of Buoy GC-3 to 170' upstream of Buoy GC-3; 6.0' available elsewhere.
- (2). Except for shoaling to 3.8' within 10' along channel limits.
- (3). Except for shoaling to 1.9' within 20' of south and east limits and shoaling to 2.2' within 20' of west limit; encroachment by floats, docks and piles of Saquatucket Harbor Marina on the west portion of anchorage .