

**REPORT OF CHANNEL CONDITIONS
100 TO 400 FEET WIDE
(ER 1130-2-520)**

DATE: **February 18, 2016**

TO: NAVIGATION INTEREST	FROM:
-----------------------------------	-------

RIVER/HARBOR NAME AND STATE: Duxbury Harbor, Duxbury, Massachusetts Dwg. No. DUX-63, Sheets 1-2 of 2, Dated 18 February 2016	MINIMUM DEPTHS IN CHANNEL ENTERING FROM SEAWARD
---	--

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (nautical miles)	MLLW DEPTH (feet)			
<p><u>CONDITION SURVEY</u></p> <p><u>8-Foot Channel</u></p> <p>From about 85' seaward of Buoy RN-12 upstream 5,047' (about 50' seaward of Buoy GC-21)</p>	1-2/16	225 to 100 to 135 to 100	.83	8.0	(1) 8.0	8.0	(2) 8.0
<p><u>8-Foot Anchorage</u></p> <p>From about 50' seaward of Buoy GC-21 to vicinity of Duxbury Yacht Club</p> <p><u>South Half</u></p> <p><u>North Half</u></p>	1-2/16		21.0 acres	8.0		8.0 (3) 8.0	

GENERAL NOTE: The information shown on this sheet(s) represents the results of surveys made on the dates indicated and can only be considered as indicating the general conditions existing at that time.

FOOT NOTES:

- (1). Except for shoaling to 7.9' within 5' of limit.
- (2). Except for shoaling to 7.8' within 5' of limit.
- (3). Except for shoaling to 6.1' within 10' along northern upstream limit.

