

**REPORT OF CHANNEL CONDITIONS
100 TO 400 FEET WIDE
(ER 1130-2-520)**

PAGE 1 OF 1 PAGE

DATE: **November 20, 2015**

<p>TO:</p> <p align="center">NAVIGATION INTEREST</p>	<p>FROM:</p>
--	---------------------

RIVER/HARBOR NAME AND STATE: Edgartown Harbor, Edgartown, Massachusetts
Dwg. No. EDG-143, Sheet 1 of 1, Dated 20 November 2015

MINIMUM DEPTHS IN
CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (nautical miles)	MLLW DEPTH (feet)			
<u>CONDITION SURVEY</u>							
<u>17-Foot Channel</u>							
From about 680' seaward of Buoy RN-8 upstream 930'	9/15	150	.15	17.0	17.0	17.0	17.0
Thence upstream 1,920'	9/15	150	.32	17.0	15.1	15.0	15.5
Thence upstream 920' to the end of the 17-Foot Channel and start of the 12-Foot Anchorage	9/15	150 to 200 to 150	.15	17.0	17.0	17.0	17.0
<u>12-Foot Anchorage</u>							
Thence upstream 2,870' to upstream end of the Federal Navigation Project	9/15		36 acres	12.0		(1) 9.8	

GENERAL NOTE: The information shown on this sheet(s) represents the results of surveys made on the dates indicated and can only be considered as indicating the general conditions existing at that time.

FOOT NOTES:

(1). Except for shoaling to 6.0' within 100' of east limit from about 25' to about 750' seaward of Buoy GC-9.