

**REPORT OF CHANNEL CONDITIONS  
LESS THAN 100 FEET WIDE  
(ER 1130-2-520)**

DATE: **July 18, 2013**

TO:	FROM:
-----	-------

RIVER/HARBOR NAME AND STATE: Rockport Harbor, Rockport, Massachusetts Dwg. No. RKM-32, Sheet(s)1 of 1, Dated 18 July 2013	MINIMUM DEPTHS IN CHANNEL ENTERING FROM SEAWARD
--	--

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			DEPTH AVAILABLE
		WIDTH (feet)	LENGTH Nautical (miles)	MLLW DEPTH (feet)	
<b><u>CONDITION SURVEY</u></b>					
<b><u>10-Foot Channel</u></b>					
From about 32' seaward of Buoy RN for about 1,088' (approximately 50' seaward of end of T-Wharf)	4/13	80	.18	10.0	8.8 <sup>(1)</sup>
150' Access Channel to the 8-Foot South Basin	4/13	40	.02	10.0	10.0
<b><u>8-Foot North Outer Anchorage</u></b>					
From about 210' upstream of Buoy RN for about 770' upstream	4/13	3.5 acres		8.0	7.2 <sup>(2)</sup>
<b><u>8-Foot South Outer Anchorage</u></b>					
From about 230' upstream of Buoy RN for about 750'	4/13	2.4 acres		8.0	7.4 <sup>(3)</sup>

**GENERAL NOTE:** The information shown on this sheet(s) represents the results of surveys made on the dates indicated and can only be considered as indicating the general conditions existing at that time.

**FOOT NOTES:**

- (1). Shoaling is located within 10' of southern limit from about 35' to about 200' upstream of Buoy RN; 9.8' available elsewhere.
- (2). Except for shoaling to 3.5' within 20' along anchorage limits.
- (3). Except for shoaling to 7.0' within 10' along anchorage limits.