

**REPORT OF CHANNEL CONDITIONS
100 TO 400 FEET WIDE
(ER 1130-2-520)**

PAGE 1 OF 1 PAGE

DATE: **November 20, 2015**

TO: NAVIGATION INTEREST

FROM:

RIVER/HARBOR NAME AND STATE: Scituate Harbor, Scituate, Massachusetts
Dwg. No. SCI-194, Sheet 1 of 1, Dated 20 November 2015

MINIMUM DEPTHS IN
CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (nautical miles)	MLLW DEPTH (feet)			
<u>CONDITION SURVEY</u>							
<u>12-Foot Entrance Channel</u> From about 1,400' seaward of South Breakwater upstream 1,530' to end of 12-Foot Channel	10/15	200	.25	12.0	10.0	11.4	(1) 12.0
<u>10-Foot Harbor Channel</u> Thence upstream 3,340' (590' upstream of the Scituate Wharf)	10/15	200 to 150	.55	10.0	(2) 8.6	8.8	8.8
<u>10-Foot Inner Anchorage</u>	10/15		8.1 acres	10.0		(3) Not Available	
<u>10-Foot Anchorage</u>	10/15		15.2 acres	10.0		(4) 8.4	
<u>8-Foot Anchorage</u>	10/15		12.9 acres	8.0		(5) 6.2	

GENERAL NOTE: The information shown on this sheet(s) represents the results of surveys made on the dates indicated and can only be considered as indicating the general conditions existing at that time.

FOOT NOTES:

- (1). Except for shoaling to 11.2' within 15' of limit.
- (2). Except for shoaling to 4.1' within 10' of limit.
- (3). Incomplete coverage due to boats in area at time of survey.
- (4). Except for shoaling to 3.7' within 75' of north limit.
- (5). Except for shoaling to 3.2' within 50' of north limit; Encroachment of a float of Scituate Harbor Yacht Club.