

**REPORT OF CHANNEL CONDITIONS  
100 TO 400 FEET WIDE  
(ER 1130-2-520)**

DATE: **August 1, 2014**

<p><b>T0:</b></p> <p align="center"><b>NAVIGATION INTEREST</b></p>	<p><b>FROM:</b></p>
--	---------------------

RIVER/HARBOR NAME AND STATE: Sesuit Harbor, Dennis, MA Dwg. No. SES-34, Sheet 1 of 1, Dated 1 August 2014	MINIMUM DEPTHS IN CHANNEL ENTERING FROM SEAWARD
--	--

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (Nautical miles)	MLLW DEPTH (feet)			
<b><u>AFTER DREDGE SURVEY</u></b>							
<b><u>6-Foot Channel</u></b>							
From about 210' seaward of Buoy GC-3A upstream 1500' to Buoy GC-3B	06/14	100	0.25	6.0	6.0	5.9	(1) 3.6
Thence upstream 420' to about 40' upstream of Buoy RN-2	06/14	100	0.07	6.0	6.0	5.3	5.1
Thence upstream 1,075' to termination of Federal Channel (vicinity of Northside Marina)	06/14	100 to 80	.18	6.0	5.4	5.7	(2) 5.2

**GENERAL NOTE:** The information shown on this sheet(s) represents the results of surveys made on the dates indicated and can only be considered as indicating the general conditions existing at that time.

**FOOT NOTES:**

- (1). Shoaling located from 140' upstream from Buoy FI R-2A to 35' seaward from Buoy FI-2B; 5.6' available elsewhere.
- (2). Except for shoaling to 4.3' within 5' of limit, located about 220' to 280' upstream of Buoy RN-4.