

**REPORT OF CHANNEL CONDITIONS  
LESS THAN 100 FEET WIDE  
(ER 1130-2-520)**

DATE: **August 15, 2013**

TO:	FROM:
-----	-------

RIVER/HARBOR NAME AND STATE: Winthrop Harbor, Winthrop, Massachusetts Dwg. No. WTH-1906, Sheet(s) 1-2 of 2, Dated 15 August 2013	MINIMUM DEPTHS IN CHANNEL ENTERING FROM SEAWARD
---	--

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			DEPTH AVAILABLE
		WIDTH (feet)	LENGTH Nautical (miles)	MLLW DEPTH (feet)	
<p><b><u>CONDITION SURVEY</u></b></p> <p><b><u>6-Foot Channel</u></b></p> <p>From about 300' seaward of the Winthrop Light upstream 4035' to end of Federal Navigation Project</p>	7/13	150 to 50	0.66	6.0	(1) 6.0

GENERAL NOTE: The information shown on this sheet(s) represents the results of surveys made on the dates indicated and can only be considered as indicating the general conditions existing at that time.

FOOT NOTES:

(1). Except for shoaling to 1.6' within 25' of west channel limit from 50' seaward to about 340' upstream of Buoy RN-2; encroachment by docks along east limit for last 310' of Federal project.