

**REPORT OF CHANNEL CONDITIONS
100 TO 400 FEET WIDE
(ER 1130-2-520)**

PAGE 1 OF 1 PAGE(S)

DATE: **May 21, 2012**

T0:

FROM:

RIVER/HARBOR NAME AND STATE: Belfast Harbor, Belfast, Maine
Dwg. No. 2699, Sheet 1 of 1, Dated 21 May 2012

MINIMUM DEPTHS IN
CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH Nautical (miles)	MLLW DEPTH (feet)			
<u>CONDITION SURVEY</u>							
<u>15-Foot Channel</u>							
From about 310' seaward of Buoy RN-4 upstream about 3,790' (about 20' upstream of Buoy RN-6)	5-6/11	490 to 220	.63	15.0	15.0	15.0	15.0
<u>13-Foot Anchorage</u>	5-6/11	45.6 acres		13.0		(1) 10.0	
<u>8-Foot Anchorage</u>	5-6/11	19.3 acres		8.0		(2) 7.8	

GENERAL NOTE: The information shown on this sheet(s) represents the results of surveys made on the dates indicated and can only be considered as indicating the general conditions existing at that time.

FOOT NOTES:

- (1). Except for shoaling to 7.9' located about 950' to about 1,300' seaward of Buoy RN-6; 10.0' available at half portion of east limit and except for shoaling to 4.9' within 15' of limit.
- (2). Except for shoaling to 2.7' within 20' of limit; obstruction noted on sheet.