

**REPORT OF CHANNEL CONDITIONS
100 TO 400 FEET WIDE
(ER 1130-2-520)**

PAGE 1 OF 1 PAGES

DATE: **June 15, 2012**

T0:

FROM:

RIVER/HARBOR NAME AND STATE: Jonesport Harbor, Jonesport, Maine
Dwg. No. JON-2712, Sheet 1 of 1, Dated 15 June 2012

MINIMUM DEPTHS IN
CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH Nautical (miles)	MLLW DEPTH (feet)			
<u>CONDITION SURVEY</u>							
<u>8-Foot Channel</u>							
From about 300' downstream from cellular steel sheet pile breakwater to about 240' upstream of Town Pier	1/12	100	0.17	8.0	7.4	7.3	6.8
<u>8-Foot Anchorage</u>	1/12		6.8 acres	8.0		6.8	
<u>6-Foot Anchorage</u>	1/12		9.1 acres	6.0		(1) 5.2	

GENERAL NOTE: The information shown on this sheet(s) represents the results of surveys made on the dates indicated and can only be considered as indicating the general conditions existing at that time.

FOOT NOTES:

(1). Except for shoaling to 4.8' within 60' of west anchorage limit.