

**REPORT OF CHANNEL CONDITIONS
FOR CHANNELS LESS THAN 100 FEET WIDE
(ER 1130-2-520)**

DATE: **September 4, 2014**

TO:
NAVIGATION INTEREST

FROM:



**US Army Corps
of Engineers**
New England District

Digitally signed by
PRESTON.JEFFREY.W.1228574348
DN: c=US, o=U.S. Government, ou=DoD, ou=PKI,
ou=USA, cn=PRESTON.JEFFREY.W.1228574348
Date: 2014.09.04 11:14:54 -04'00'

RIVER/HARBOR NAME AND STATE: **Josias River, Ogunquit, Maine**
Dwg. No. **JOS-2746, Sheet 1 of 1, Dated 4 September 2014**

MINIMUM DEPTHS IN
CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			DEPTH AVAILABLE
		WIDTH (feet)	LENGTH (Nautical miles)	MLLW DEPTH (feet)	
<u>CONDITION SURVEY</u>					
<u>7-Foot Channel</u>					
From about 925' seaward of southernmost face of the Ogunquit South Town Dock upstream 560'	7/14	40	.09	7.0	7.0
Thence upstream 665' to end of channel (about 100' upstream from north face of bascule footbridge)	7/14	40 to 45	.11	7.0	(1) 5.7
<u>7-Foot Anchorage</u>					
	7/14		2.13 acres	7.0	(2) 5.7
<u>5-Foot Anchorage</u>					
Western area	7/14		1.30 acre	5.0	(3) 4.8
Southern area	7/14		0.22 acre	5.0	4.0
Eastern area	7/14		0.04 acre	5.0	5.0

GENERAL NOTE: The information shown on this sheet(s) represents the results of surveys made on the dates indicated and can only be considered as indicating the general conditions existing at that time.

FOOT NOTES:

- (1). Except for shoaling to 3.8' within 5' of south channel limit.
- (2). Except for shoaling to 4.7' within 30' of northwest corner of anchorage: Encroachment of a float along north limit.
- (3). Except for shoaling to 2.9' within 10' of northwesterly limit, and shoaling to 3.8' within 10' of south limit.