

**REPORT OF CHANNEL CONDITIONS
100 TO 400 FEET WIDE
(ER 1130-2-316)**

DATE: **December 5, 2011**

TO:	FROM:
-----	-------

RIVER/HARBOR NAME AND STATE: Rockport Harbor, Rockport, Maine Dwg. No. 2694, Sheet 1 of 1, Dated 5 December 2011	MINIMUM DEPTHS IN CHANNEL ENTERING FROM SEAWARD
---	--

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH Nautical (miles)	MLLW DEPTH (feet)			
<p><u>CONDITION SURVEY</u></p> <p><u>12-Foot Area</u> <u>(Maintained to 9.0-Feet)</u></p>	05/10		5.5 acres	12.0		9.0 Available (1)	

GENERAL NOTE: The information shown on this sheet(s) represents the results of surveys made on the dates indicated and can only be considered as indicating the general conditions existing at that time.

FOOT NOTES:

(1). Except for shoaling to 8.3' within 110' of northwest corner and shoaling to 8.5' within 50' along west limits; encroachment by floats and dock on north limit.