

**FURNACE REPLACEMENT
U.S. ARMY CORPS OF ENGINEERS
NORTH HARTLAND LAKE
NORTH HARTLAND, VERMONT
Statement of Work**

Informational Photos



Informational Photo 1: Furnace location showing duct work

**FURNACE REPLACEMENT
U.S. ARMY CORPS OF ENGINEERS
NORTH HARTLAND LAKE
NORTH HARTLAND, VERMONT
Statement of Work**

Informational Photos



Informational Photo 2: Furnace location showing duct work

**FURNACE REPLACEMENT
U.S. ARMY CORPS OF ENGINEERS
NORTH HARTLAND LAKE
NORTH HARTLAND, VERMONT
Statement of Work**

Informational Photos



Informational Photo 3: Duct work to be replaced

**FURNACE REPLACEMENT
U.S. ARMY CORPS OF ENGINEERS
NORTH HARTLAND LAKE
NORTH HARTLAND, VERMONT
Statement of Work**

Informational Photos



Informational Photo 4: Air exchange unit on third floor. Not replacing.

**FURNACE REPLACEMENT
U.S. ARMY CORPS OF ENGINEERS
NORTH HARTLAND LAKE
NORTH HARTLAND, VERMONT
Statement of Work**


Informational Photos



Informational Photo 5: Access to gatehouse via 5 ton limit bridge

**FURNACE REPLACEMENT
 U.S. ARMY CORPS OF ENGINEERS
 NORTH HARTLAND LAKE
 NORTH HARTLAND, VERMONT
 Statement of Work**

Informational Plans



Informational Photo 6: Plan of existing system.