


REPORT OF CHANNEL CONDITIONS LESS THAN 100 FEET WIDE (ER 1130-2-520)					PAGE 1 OF 1 PAGE
T0:			FROM:  US Army Corps of Engineers® New England District		DATE: January 23, 2017 <small>Digitally signed by WALKER.WILLIAM.H.1228577908 DN: c=US, o=U.S. Government, ou=DoD, ou=PKI, ou=USA, cn=WALKER.WILLIAM.H.1228577908 Date: 2017.01.24 09:20:26 -05'00'</small>
RIVER/HARBOR NAME AND STATE: Winthrop Harbor, Winthrop, Massachusetts Dwg. No. WTH-1907, Sheets 1-2 of 2, Dated 23 January 2017				MINIMUM DEPTHS IN CHANNEL ENTERING FROM SEAWARD	
NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			DEPTH AVAILABLE
		WIDTH (feet)	LENGTH (nautical miles)	MLLW DEPTH (feet)	
<u>CONDITION SURVEY</u> <u>6-Foot Channel</u> From about 185' seaward of the Winthrop Light upstream 4,035' to upstream end of Federal Navigation Project	11-12/16	150 to 50	.66	6.0	(1) 4.2
<p>GENERAL NOTE: The information shown on this sheet(s) represents the results of surveys made on the dates indicated and can only be considered as indicating the general conditions existing at that time.</p> <p>FOOT NOTES: (1). Except for shoaling to 0.8' within 5' along west channel limit located in the vicinity of Buoy GC-1A; Encroachment of floats of Crystal Cove Marina.</p>					
NOAA Chart 13272					