



GENERAL NOTES:

1. Soundings are in feet and tenths and refer to the plane of Mean Lower Low Water (MLLW) 1983-2001 Tidal Epoch.
2. Topography shown is from previous surveys and/or NOAA Chart No. 13313. All topography, including shoreline, bridges, piers, etc., is located approximate unless otherwise noted and should be used as a general reference only.
3. Bench Mark Data: Tides were recorded using RTK GPS. The MLLW to NAVD88 correction for this project is 5.52 feet. This correction is referenced from NOAA's V-Datum Model in the vicinity of Frenchboro Harbor, Frenchboro, Long Island, Maine. No tide gauges were used on this project.
4. Coordinates shown are based on the Transverse Mercator Grid System for the State of Maine (East Zone 1801) and NAD 1983.
5. Survey was performed using an Odom MK2 echotrac echosounder. Horizontal positioning and vertical depths were recorded utilizing a Leica I200 GPS System. The RTK Base Station was set up on TBM Fog (2007).
6. The sounding information shown on this map represents the SHOALEST soundings of those obtained from hydrographic surveys conducted during September 2013.
7. The sounding information depicted on this map should NOT be used to determine volumes. Volumes are determined from more sounding information than shown. Additional sounding information is available upon request.
8. The information depicted on this map represents the results of surveys made on the dates indicated, and can only be considered as indicating the general conditions existing at that time.
9. Field Book: R&H 4092

10-Foot depth contour shown thus:

6-Foot depth contour shown thus:

Surveyed by: Paul K. O'Brien and crew
Refer to Survey No. 13-1291

U.S. Army Corps of Engineers
CONCORD, MASSACHUSETTS
www.nae.usace.army.mil

DATE: 10/23/2013
DRAWN BY: [Signature]
CHECKED BY: [Signature]
SUBMITTED BY: [Signature]
DATE: 10/23/2013
DRAWING CODE: FRES2103N
FILE NUMBER: FRES2103N
SCALE: 1" = 100'
ANSI: FRES2103N

FRENCHBORO HARBOR
FRENCHBORO LONG ISLAND, MAINE
CONDITION SURVEY
6-FOOT CHANNEL
AND 10-FOOT ANCHORAGES

SHEET IDENTIFICATION
V-101
SHEET 1 OF 1

