

**REPORT OF CHANNEL CONDITIONS
FOR CHANNELS LESS THAN 100 FEET WIDE
(ER 1130-2-316)**

DATE: **November 22, 2013**

TO:	FROM:
-----	-------

RIVER/HARBOR NAME AND STATE: Frenchboro Harbor, Frenchboro, Long Is, Maine Dwg. No. FRE-2739, Sheet 1 of 1, Dated 22 November 2013	MINIMUM DEPTHS IN CHANNEL ENTERING FROM SEAWARD
---	--

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			DEPTH AVAILABLE
		WIDTH (feet)	LENGTH Nautical (miles)	MLLW DEPTH (feet)	
<u>CONDITION SURVEY</u>					
<u>10-Foot Anchorage</u>					
From about 50' seaward of Frenchboro Ferry Dock upstream 850' to end of 10-Foot anchorage	9/13	Varies 75 to 400	5.7 acres	10.0	(1) 7.5
<u>6-Foot Channel</u>					
Thence upstream 475' from end of 10-Foot anchorage	9/13	75	.08	6.0	(2) 6.0
<u>6-Foot Anchorage</u>					
Thence upstream 350' to the upstream end of the Federal Navigation Project	9/13	Varies 75 to 310	2.0 acres	6.0	(3) 4.8

GENERAL NOTE: The information shown on this sheet(s) represents the results of surveys made on the dates indicated and can only be considered as indicating the general conditions existing at that time.

FOOT NOTES:

- (1). Shoaling located at upstream end of anchorage in the vicinity of 6' channel; Encroachment of dolphins in the vicinity of Frenchboro Ferry Dock.
- (2). Except for shoaling to 5.1' within 10' of west limit and to 5.7' within 5' of east limit.
- (3). Except for shoaling to +0.4' within last 50' of anchorage, and shoaling to 1.1' within 20' of east limit; Encroachment of floats and gangways along west and south limits.