REPORT NUMBER Page 1 of 3 584 CONTRACTORS QUALITY CONTROL REPORT (QCR) DAILY LOG OF CONSTRUCTION DATE 24 Jul 2020 - Friday PROJECT CONTRACT NUMBER W912WJ19C0002 Durham Meadows Waterline Remedial Design CONTRACTOR WEATHER Ludlow Construction Co., Inc. Weather Caused No Delay Temperature Min 69 °F Max 85 °F No Precipitation 0.53 MPH Wind **QC NARRATIVES** JOB SAFETY SAFETY: Crews arrived at 7:00am, Departed at 3:00-3:30pm *SSHO Rob Peddicord: *Monitored 2 main crews production activities; Foremen Jonathon Pio and Billy DaCRuz, *Monitored DN Tanks activities at the Water Tank; Foreman Al Kendall *Jonathon Pio's crew: Cleaned up Pickett Lane, Continued set-up for Streamcrossing #3 at Maple Ave *Billy DaCruz crew at Rt 17, Shimmed/paved low spots in the A.M., installed Water Service in the P.M. *2 CTC flaggers for traffic control (Certs on record) *Borrow/Dump Yard: 1 Operator loading dumps with trench backfill material; maintaining waste piles *1 Laborer saw cutting laterals on Rt 17 *1 Laborer pressure testing pipe *Performed daily checklist inspections on Daily Report; Crews wearing all required PPE, Following Trench Safety, Crews alert of surroundings. Safety in compliance with EM 385-1-1. COVID-19 precautions being followed. (SEE Attached Ludlow SSHO Daily PDF Report) *Checked dumptruck haul roads for debris. *Checked silt fencing for SWPP; no ruptures. *Office work: The SSHO continued collecting and filing crew paperwork for Lift Plans, AHAs, and Daily Equipment Inspections (See Lift Plan PDFs attached to RMS). *Received daily reports from DN Tanks; COVID self cert, SSHO Daily Report. TESTS REQUIRED BY SPECIFICATIONS, PERFORMED, AND THE RESULTS Pressure Testing Water Lines on Pickett Lane and Maiden Lane at STA 426+00 to STA 512+00/ STA 426+00 to STA 530+71 Tested for two hours at 150 PSI. Test Results Good. WORK PERFORMED TODAY WORK PERFORMED TODAY Onsite 7:00 AM ; Offsite 3:00 PM PERSONAL: Project Manager 1 Superintendent 5 Operators 5 Labors 10 **Truck Drivers 3** VISITERS: SUBCONTRACTORS ON SITE: Cert Flaggers = 2 WORK COMPLETED; JON'S Crew: Cleaned up Pickett Lane. Placed top soil around the two Streams and seeded. Equipment was moved to Maple Lane for the next Stream Crossing. Pressure Test was done on Pickett Lane Water Line and Maiden Lane at STA 426+00 to STA 512+00/ STA 426+00 to STA 530+71. Tested at 150 PSI for two hours. Test Good.

BILLY's Crew: Water Service 1" Corp; Water Service 1" Curb Stop; 1 - 1 Inch Curb Stops was installed at STA 176+00 Water Service 1" Copper Line; 42 Feet of Copper Line was Installed. Water Service Soil Piercing: 8.0 Feet under sidewalk

			REPORT NUMBER			
CONTRA		LITY CONTROL REPORT (QCR) OF CONSTRUCTION	584	Page 2 of 3		
CONTRA			DATE			
			24 Jul 2020 - Friday			
PROJECT			CONTRACT NUMBER	ау		
	dows Waterline	e Remedial Design	W912WJ19C0002)		
	Feet of Saw Cut in	-	1012101000002	-		
Shimming: STA STA STA STA	A 136+46 to STA 1 A 156+35 to STA 1 A 160+80 to STA 1 A 162+70 to STA 1 t Middlefield Road.	38+00/ 60+20/ 61+45/ 64+95				
Water Tank Ins Making Forms Rebar was cap	and Setting forms	around tank area.				
QA/QC:						
	SON COORDINAT	FOR:				
PREP/INITIAL D	ATES	(Preparatory and initial dates held and adv	vance notice)			
	ections held today					
No preparator	y inspections h	eld today				
Initial Inspections						
•	ections held too	day				
ACTIVITY STAR	T/FINISH					
Activity No	Description					
	vere started or f	iinished today				
	ENTS					
Requirement No		Description		Results		
CT-00187	QC Test	Pressure Testing on Maiden Lane and F 512+00/ STA 426+00 to STA 530+71	Pickett Lane: STA 426+00 to S	TA Awaiting	Results	
SSUED QA/QC	DEFICIENCY	(Describe QA and QC Deficiency item	is issued)			
Item No	Location	Description	,			
	Location					
		Description				
No QC Deficie	ncy items were					
	ency items were	issued today	corrected)			
CORRECTED Q	A/QC DEFICIEN	issued today ICY (Report QC and QA Deficiency items	corrected)			
	,	issued today	graph 3.11.1 (Resident Engine wide trailer with an indoor lava with the contractor that the batl be vented improperly. This is a	tory. USÁCE on mul nroom has a bad odo	tiple or	
CORRECTED Q Item No QA-00005	A/QC DEFICIEN Location Office	ICY (Report QC and QA Deficiency items Description Section 01 50 00 Page 10 parage responsible to provide a double occasions has raised the issue coming from it and it appears to	graph 3.11.1 (Resident Engine wide trailer with an indoor lava with the contractor that the bat be vented improperly. This is a sed into the trailer.	tory. USÁCE on mul nroom has a bad odo	tiple or	
CORRECTED Q Item No QA-00005	A/QC DEFICIEN Location Office	ICY (Report QC and QA Deficiency items Description Section 01 50 00 Page 10 parage responsible to provide a double occasions has raised the issue coming from it and it appears to toxic sewer gasses being releas	graph 3.11.1 (Resident Engine wide trailer with an indoor lava with the contractor that the bat be vented improperly. This is a sed into the trailer.	tory. USÁCE on mul nroom has a bad odo	tiple or	
CORRECTED Q Item No QA-00005 CONTRACTORS Name	A/QC DEFICIEN Location Office	ICY (Report QC and QA Deficiency items Description Section 01 50 00 Page 10 parage responsible to provide a double occasions has raised the issue coming from it and it appears to toxic sewer gasses being releas (Report first and/or last day contractors we	graph 3.11.1 (Resident Engine wide trailer with an indoor lava with the contractor that the bath be vented improperly. This is a sed into the trailer. ere on site)	tory. USÁCE on mul nroom has a bad odc a safety issue of poss	tiple or	
CORRECTED Q Item No QA-00005 CONTRACTORS Name No Contractor	A/QC DEFICIEN Location Office S ON SITE rs had their first	ICY (Report QC and QA Deficiency items Description Section 01 50 00 Page 10 parage responsible to provide a double occasions has raised the issue coming from it and it appears to toxic sewer gasses being releas	graph 3.11.1 (Resident Engine wide trailer with an indoor lava with the contractor that the bath be vented improperly. This is a sed into the trailer. ere on site)	tory. USÁCE on mul nroom has a bad odc a safety issue of poss	tiple or	
CORRECTED Q Item No QA-00005 CONTRACTORS Name No Contractor LABOR HOURS	A/QC DEFICIEN Location Office S ON SITE rs had their first	ICY (Report QC and QA Deficiency items Description Section 01 50 00 Page 10 parage responsible to provide a double occasions has raised the issue coming from it and it appears to toxic sewer gasses being releas (Report first and/or last day contractors we t or last day on the site	graph 3.11.1 (Resident Engine wide trailer with an indoor lava with the contractor that the bath be vented improperly. This is a sed into the trailer. ere on site)	tory. USACE on mul nroom has a bad odc a safety issue of poss Last Day Number of	tiple or sible Hours	
CORRECTED Q Item No QA-00005 CONTRACTORS Name No Contractor ABOR HOURS Employer	A/QC DEFICIEN Location Office S ON SITE rs had their first	issued today (Report QC and QA Deficiency items Description Section 01 50 00 Page 10 parageresponsible to provide a double occasions has raised the issuer coming from it and it appears to toxic sewer gasses being releas (Report first and/or last day contractors we t or last day on the site Labor Classification	graph 3.11.1 (Resident Engine wide trailer with an indoor lava with the contractor that the bath be vented improperly. This is a sed into the trailer. ere on site)	tory. USACE on mul nroom has a bad odd a safety issue of poss Last Day Number of Employees	tiple or sible Hours Worked	
CORRECTED Q Item No QA-00005 CONTRACTORS Name No Contractor ABOR HOURS Employer Ludlow Construct	A/QC DEFICIEN Location Office S ON SITE rs had their first	issued today (Report QC and QA Deficiency items Description Section 01 50 00 Page 10 parage responsible to provide a double occasions has raised the issue coming from it and it appears to toxic sewer gasses being release (Report first and/or last day contractors we t or last day on the site Labor Classification TRUCK DRIVER, GROUP 1	graph 3.11.1 (Resident Engine wide trailer with an indoor lava with the contractor that the bath be vented improperly. This is a sed into the trailer. ere on site)	tory. USACE on mult proom has a bad odd a safety issue of poss Last Day Number of Employees 3.0	tiple or sible Hours Worked 24.0	
CORRECTED Q Item No QA-00005 CONTRACTORS Name No Contractor ABOR HOURS Employer Ludlow Construc Ludlow Construc	A/QC DEFICIEN Location Office S ON SITE Ts had their first tion Co., Inc. tion Co., Inc.	issued today (Report QC and QA Deficiency items Description Section 01 50 00 Page 10 parageresponsible to provide a double occasions has raised the issuer coming from it and it appears to toxic sewer gasses being release (Report first and/or last day contractors we t or last day on the site Labor Classification TRUCK DRIVER, GROUP 1 LABORER, GROUP 1	graph 3.11.1 (Resident Engine wide trailer with an indoor lava with the contractor that the bath be vented improperly. This is a sed into the trailer. ere on site)	tory. USACE on mult proom has a bad odd a safety issue of poss Last Day Number of Employees 3.0 9.0	tiple or sible Hours Worked 24.0 72.0	
CORRECTED Q Item No QA-00005 CONTRACTORS Name No Contractor ABOR HOURS Employer Ludlow Construc Ludlow Construc	A/QC DEFICIEN Location Office S ON SITE S had their first tion Co., Inc. tion Co., Inc.	Pissued today NCY (Report QC and QA Deficiency items Description Section 01 50 00 Page 10 paragoresponsible to provide a double occasions has raised the issue to coming from it and it appears to toxic sewer gasses being release (Report first and/or last day contractors were to classification TRUCK DRIVER, GROUP 1 LABORER, GROUP 1 CIRCULAR SAW OPERATOR	graph 3.11.1 (Resident Engine wide trailer with an indoor lava with the contractor that the bath be vented improperly. This is a sed into the trailer. ere on site)	tory. USACE on mult proom has a bad odd a safety issue of poss Last Day Number of Employees 3.0 9.0 1.0	tiple or sible Hours Worked 24.0 72.0 8.0	
CORRECTED Q Item No QA-00005 CONTRACTORS Name No Contractor ABOR HOURS Employer Ludlow Construc Ludlow Construc Ludlow Construc Ludlow Construc	A/QC DEFICIEN Location Office S ON SITE S on SITE stion Co., Inc. tion Co., Inc. tion Co., Inc.	issued today (Report QC and QA Deficiency items Description Section 01 50 00 Page 10 paragers responsible to provide a double occasions has raised the issue to coming from it and it appears to toxic sewer gasses being release (Report first and/or last day contractors were to relast day on the site Labor Classification TRUCK DRIVER, GROUP 1 LABORER, GROUP 1 CIRCULAR SAW OPERATOR PROJECT MANAGER	graph 3.11.1 (Resident Engine wide trailer with an indoor lava with the contractor that the bath be vented improperly. This is a sed into the trailer. ere on site)	tory. USACE on mult proom has a bad odd a safety issue of poss Last Day Number of Employees 3.0 9.0 1.0 0.0	tiple or sible Hours Worked 24.0 72.0 8.0 0.0	
CORRECTED Q Item No QA-00005 CONTRACTORS Name No Contractor LABOR HOURS Employer Ludlow Construc Ludlow Construc Ludlow Construc Ludlow Construc Ludlow Construc Ludlow Construc	A/QC DEFICIEN Location Office S ON SITE S on SITE s had their first tion Co., Inc. tion Co., Inc. tion Co., Inc. tion Co., Inc.	issued today ICY (Report QC and QA Deficiency items Description Section 01 50 00 Page 10 paragersponsible to provide a double occasions has raised the issue ocming from it and it appears to toxic sewer gasses being released (Report first and/or last day contractors were) (Report first and/or last day contractors were) t or last day on the site Labor Classification TRUCK DRIVER, GROUP 1 LABORER, GROUP 1 CIRCULAR SAW OPERATOR PROJECT MANAGER OPERATOR HEAVY EQUIPMENT 1	graph 3.11.1 (Resident Engine wide trailer with an indoor lava with the contractor that the bath be vented improperly. This is a sed into the trailer. ere on site)	tory. USACE on multiproom has a bad odd a safety issue of poss Last Day Number of Employees 3.0 9.0 1.0 0.0 5.0	Hours Worked 24.0 72.0 8.0 0.0 40.0	
CORRECTED Q Item No QA-00005 CONTRACTORS Name No Contractor LABOR HOURS Employer Ludlow Construc Ludlow Construc Ludlow Construc Ludlow Construc Ludlow Construc Ludlow Construc Ludlow Construc	A/QC DEFICIEN Location Office S ON SITE S ON SITE stion Co., Inc. tion Co., Inc. tion Co., Inc. tion Co., Inc. tion Co., Inc. tion Co., Inc.	issued today NCY (Report QC and QA Deficiency items Description Section 01 50 00 Page 10 paragores Section 01 50 00 Page 10 paragores Section 01 50 00 Page 10 paragores responsible to provide a double occasions has raised the issue occasions has raised the issue coming from it and it appears to toxic sewer gasses being release (Report first and/or last day contractors were) t or last day on the site Labor Classification TRUCK DRIVER, GROUP 1 LABORER, GROUP 1 LABORER, GROUP 1 CIRCULAR SAW OPERATOR PROJECT MANAGER OPERATOR HEAVY EQUIPMENT 1 SSHO SSHO	graph 3.11.1 (Resident Engine wide trailer with an indoor lava with the contractor that the bath be vented improperly. This is a sed into the trailer. ere on site)	tory. USACE on multaroom has a bad odd a safety issue of poss Last Day Number of Employees 3.0 9.0 1.0 0.0 5.0 1.0	tiple or sible Hours Worked 24.0 72.0 8.0 0.0 40.0 8.0	
CORRECTED Q Item No QA-00005 CONTRACTORS Name No Contractor LABOR HOURS Employer Ludlow Construc Ludlow Construc Ludlow Construc Ludlow Construc Ludlow Construc	A/QC DEFICIEN Location Office S ON SITE S ON SITE S had their first stion Co., Inc. tion Co., Inc. tion Co., Inc. tion Co., Inc. tion Co., Inc. tion Co., Inc. tion Co., Inc.	issued today ICY (Report QC and QA Deficiency items Description Section 01 50 00 Page 10 paragersponsible to provide a double occasions has raised the issue ocming from it and it appears to toxic sewer gasses being released (Report first and/or last day contractors were) (Report first and/or last day contractors were) t or last day on the site Labor Classification TRUCK DRIVER, GROUP 1 LABORER, GROUP 1 CIRCULAR SAW OPERATOR PROJECT MANAGER OPERATOR HEAVY EQUIPMENT 1	graph 3.11.1 (Resident Engine wide trailer with an indoor lava with the contractor that the bath be vented improperly. This is a sed into the trailer. ere on site)	tory. USACE on multiproom has a bad odd a safety issue of poss Last Day Number of Employees 3.0 9.0 1.0 0.0 5.0	Hours Worked 24.0 72.0 8.0 0.0 40.0	

CONTRACTORS Q DAILY L	UALITY CONTRO OG OF CONSTRU	REPORT 584 DATE	NUMBER	Page 3 of 3		
		24 Ju	24 Jul 2020 - Friday			
ROJECT				CT NUMBER		
Durham Meadows Wate	erline Remedial De	W912	W912WJ19C0002			
Total hrs worked to date:	23,000.5	Hrs worked MTD:	2,584.0	Total:	20.0	160.0
QUIPMENT HOURS					Idle	Operating
Serial Number	Description				Hours	Hours
L-20	L-20 Kumatsu Fror	,			4.0	4.0
TE-6 Ex	TE-6 Volvo	Jon			6.0	2.0
E-4 0336FCRAB	E-4 Cat 336 Track				4.0	4.0
T-36	Dump Truck T-36	Jon			8.0	0.0
B-5	Sweeper B-5	Billy			6.0	2.0
E-20 ECR145DL,	E-20 Volvo Excava				4.0	4.0
T-41	Ludlow Pressure T				0.0	8.0
T-50	T-50 PU	Jon			4.0	4.0
T-77 PU	T-77 PU	Billy			4.0	4.0
E-9 Track Hoe	E-9 336 Track Ho	e Billy			8.0	0.0
T-64	Dump Truck T-64				8.0	0.0
B-5 Sweeper	B-5 Sweeper	Jon			4.0	4.0
R-4 Roller Billy	Roller Compacter	Billy			4.0	4.0
TE 15 Excavator	TE-15 Track Hoe	Billy			4.0	4.0
T-84 PU	T-84 PU	Billy			0.0	8.0
T-78 PU	T-78 PU	Jon			6.0	2.0
L-18 950	L-18 Loader	Jon			4.0	4.0
R-18 Roller	R-18 Compactor	JON			4.0	4.0
D1 Cat	D-1 Cat D-5 Doze	5			8.0	0.0
T-86	T-86 Dump Truck	,			0.0	8.0
T-21 Dump	T-21 Dump	Jon			8.0	0.0
R-17 Roller	R-17 Roller	Billy			8.0	0.0
T-59 Dump	T-59 Dump	Billy			8.0	0.0
TE-13 Excavator	TE-13 EX 19,187.5 Idle I	Billy	or hrs MTD:	1,328.0	8.0	0.0
Total operating hrs to date:	,	· · · ·	DI HIS MID.	1,320.0	Total: 122.0	70.0
	(Describe mi					
ISHAP REPORTING No mishaps reported too		snaps)				