Daily Report

Location: Maple Avenue, Main Street, and the Shared Access Driveway Day	of Week:	
	OI WEEK.	Monday
Project #: AECOM: 6061487 Re	eport No:	128
Contractor: Ludlow Construction	Page:	1 of 17

		Weather C	onditi	ons				
Conditions:	Daylight l	nours. Sunny.						
Temperature (°F):	High	100°F Low 77°F					_	
Con	tractors & Sub	contractors Workforce			Equipment in Use		_	
Trade	# x hrs	Trade	# :	k hrs	Туре	#	х	1
USACE		Ludlow Construction			Concrete/Asphalt Road Saw	1	х	
-ield Engineer	2 x 8	Superintendent	0	x 8	Dump truck	5	х	
		Safety Officer	1	ĸ 8	Excavator – Large	3	х	
		Foreman	2	ĸ 8	Excavator - Mid-Size	1	х	
		Dump truck Operator	4	ĸ 8	Excavator - Rubber Wheeled – Rock	0	х	
		Excavator Operator	4	ĸ 8	Skid Steer / Bucket Loader	1	х	
		Skid Steer/Bucket Loader	1	ĸ 8	Rolling Compactor	1	х	
		Laborers	6	κ 8	Plate Compactor	1	х	
		Note that some persons			Jumping Jack Compactor	1	х	
		Multiple pieces equipment.			Street Sweeper (Broce Broom)	1	х	
					Material Hopper	1	х	
		Sub-contractor	2	κ 8	Pipe saw	1	х	
		Municipal Police Detail	0	X 8	Light Tower	0	х	
		State Police Detail	0	κ 8				

Visitors: Army Core of Engineers (Kurt and Bob)

Pipe Connections, Installations, and Other Work

Ludlow placed piping in the Allyn Brook stream bed to divert flow.

Ludlow installed curb stops on the west side of Main Street at Stations 176+50, 178+50, & 180.

DN Tanks continued to construct forms for the water tank. Four (4) yards of concrete was poured at the tank site.

Compaction Testing

Soil compaction testing was not performed today. Compaction test data for the project can be found here:

https://www.nae.usace.army.mil/Portals/74/docs/Topics/DurhamMeadowsWaterline/CompactionTests/

Res. Representative:

D. Kielbania

Date: 7/27/20

Daily Report

Durham Meadows Pipeline Installation	Date:	July 27, 2020
Maple Avenue, Main Street, and the Shared Access Driveway	Day of Week:	Monday
AECOM: 6061487	Report No:	128
Ludlow Construction	Page:	2 of 17
	Maple Avenue, Main Street, and the Shared Access Driveway AECOM: 6061487	Maple Avenue, Main Street, and the Shared Access DrivewayDay of Week:AECOM: 6061487Report No:

In addition, soil compaction data is presented in the Contractor Daily Quality Control Reports located here:

https://www.nae.usace.army.mil/Missions/Projects-Topics/Durham-Meadows-Water-Lines-Project/

Daily Activities – Stream Crossing, Maple Avenue

Ludlow began work on the Allyn Brook stream crossing at Maple avenue at Station ~905+00.

0716: Ludlow began to remove brush from the stream bed and load it into a dump truck.

0740: Ludlow began to place large sandbags and sheets of poly in the stream bed.

0800: Ludlow began to place two sections of corrugated pipe parallel with the stream bed to divert the flow.

1055: Ludlow created to sumps in the stream bed and began to pump water into a large frac tank.

1223: Ludlow is continuing to pump water into the frac tank.

1340: SAA

Daily Activities – Installation of Curb Stop(s), Main Street, Durham

Ludlow installed (3) curb stop(s) on Main Street at Station(s) 176+50, 178+50, & 180

0830: Ludlow began to rock hammer in front of the house on 318 Main Street (176+50). The trench line was dug for the service line and the curb stop. The curb stop is approximately 27' off the curb. An 8*4*4 piece of sidewalk was removed due to ledge.

1028: Ludlow began to install curb stop at the property on 308 Main Street (178+50). The curb stop is approximately 50' from the curb.

1145: Ludlow began to backfill and compact trenches for 318 and 308 Main Street. They then began to dig the trench line for 289 Main Street (180).

1316: Ludlow installed the curb stop at 289 Main Street. The curb stop is approximately 37' from the curb.

1400: Ludlow began to backfill and compact the trench at 289 Main Street.

Daily Activities – DN Tanks Mobilization, Shared Access Driveway, Middletown

DN Tanks spent the morning prepping for a small concrete pour (4 yards). They spent the remainder of the day building the

Res. Representative:

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	July 27, 2020
Location:	Maple Avenue, Main Street, and the Shared Access Driveway	Day of Week:	Monday
Project #:	AECOM: 6061487	Report No:	128
Contractor:	Ludlow Construction	Page:	3 of 17

concrete form for the frost wall.

0818: DN tanks and Ludlow prepping for concrete pour.

0930: Concrete mixer onsite to begin concrete pour. JTC and ACE onsite to see pour and conduct testing on the concrete.

1123: DN Tanks building forms for the tank wall.

1250: SAA

1420: SAA

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	July 27, 2020
Location:	Maple Avenue, Main Street, and the Shared Access Driveway	Day of Week:	Monday
Project #:	AECOM: 6061487	Report No:	128
Contractor:	Ludlow Construction	Page:	4 of 17



Picture 1: Ludlow construction removing brush, Maple Avenue, Station 905. View to the south.

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	July 27, 2020
Location:	Maple Avenue, Main Street, and the Shared Access Driveway	Day of Week:	Monday
Project #:	AECOM: 6061487	Report No:	128
Contractor:	Ludlow Construction	Page:	5 of 17
Contractor:	Ludlow Construction	Page:	



Picture 2: Ludlow construction removing brush, Maple Avenue, Station 905. View to the south.

Daily Report

Location:Maple Avenue, Main Street, and the Shared Access DrivewayDay of Week:Project #:AECOM: 6061487Report No:	27, 2020
	Monday
	128
Contractor: Ludlow Construction Page:	6 of 17



Picture 3: Ludlow construction installing sandbags and corrugated piping in the stream bed, Maple Avenue, Station 905. View to the west.

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	July 27, 2020
Location:	Maple Avenue, Main Street, and the Shared Access Driveway	Day of Week:	Monday
Project #:	AECOM: 6061487	Report No:	128
Contractor:	Ludlow Construction	Page:	7 of 17



Picture 4: Ludlow construction installing sandbags and corrugated piping in the stream bed, Maple Avenue, Station 905. View to the west.

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	July 27, 2020
Location:	Maple Avenue, Main Street, and the Shared Access Driveway	Day of Week:	Monday
Project #:	AECOM: 6061487	Report No:	128
Contractor:	Ludlow Construction	Page:	8 of 17



Picture 5: Ludlow construction installing sandbags and corrugated piping in the stream bed, Maple Avenue, Station 905. View to the west.

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	July 27, 2020
Location:	Maple Avenue, Main Street, and the Shared Access Driveway	Day of Week:	Monday
Project #:	AECOM: 6061487	Report No:	128
Contractor:	Ludlow Construction	Page:	9 of 17



Picture 6: DN Tanks placing concrete around a pipe for the water tank, Shared Access Driveway. View to the west.

Res. Representative:

Daily Report

	, ,		
Project:	Durham Meadows Pipeline Installation	Date:	July 27, 2020
Location:	Maple Avenue, Main Street, and the Shared Access Driveway	Day of Week:	Monday
Project #:	AECOM: 6061487	Report No:	128
Contractor:	Ludlow Construction	Page:	10 of 17



Picture 7: DN Tanks placing concrete around a pipe for the water tank, Shared Access Driveway. View to the west.

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	July 27, 2020
Location:	Maple Avenue, Main Street, and the Shared Access Driveway	Day of Week:	Monday
Project #:	AECOM: 6061487	Report No:	128
Contractor:	Ludlow Construction	Page:	11 of 17



Picture 8: JTC testing the concrete being placed, Shared Access Driveway. View to the east.

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	July 27, 2020
Location:	Maple Avenue, Main Street, and the Shared Access Driveway	Day of Week:	Monday
Project #:	AECOM: 6061487	Report No:	128
Contractor:	Ludlow Construction	Page:	12 of 17



Picture 9: Concrete air entrainment indicator reading 1.4, Water Tank, Shared access driveway.

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	July 27, 2020
Location:	Maple Avenue, Main Street, and the Shared Access Driveway	Day of Week:	Monday
Project #:	AECOM: 6061487	Report No:	128
Contractor:	Ludlow Construction	Page:	13 of 17



Picture 10: Ludlow construction installing curb stop, 308 Main Street, Station 178+50. View to the south.

Res. Representative:

D. Kielbania

Date: 7/27/20

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	July 27, 2020
Location:	Maple Avenue, Main Street, and the Shared Access Driveway	Day of Week:	Monday
Project #:	AECOM: 6061487	Report No:	128
Contractor:	Ludlow Construction	Page:	14 of 17



Picture 11: Water being pumped from sumps into frac tank, Maple Avenue, Station 905. View to the west.

Daily Report

	· · · · · · · · · · · · · · · · · · ·		
Project:	Durham Meadows Pipeline Installation	Date:	July 27, 2020
Location:	Maple Avenue, Main Street, and the Shared Access Driveway	Day of Week:	Monday
Project #:	AECOM: 6061487	Report No:	128
Contractor:	Ludlow Construction	Page:	15 of 17
		-	



Picture 12: DN Tanks constructing concrete forms for water tank side panels, Shared access driveway. View to the east.

Res. Representative:

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	July 27, 2020
Location:	Maple Avenue, Main Street, and the Shared Access Driveway	Day of Week:	Monday
Project #:	AECOM: 6061487	Report No:	128
Contractor:	Ludlow Construction	Page:	16 of 17



Picture 13: Ludlow construction installing curb stop, 289 Main Street, Station 180+00. View to the south.

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	July 27, 2020
Location:	Maple Avenue, Main Street, and the Shared Access Driveway	Day of Week:	Monday
Project #:	AECOM: 6061487	Report No:	128
Contractor:	Ludlow Construction	Page:	17 of 17



Picture 14: Ludlow construction installing curb stop, 318 Main Street, Station 178+50. View to the east.

Res. Representative: