Daily Report	Daily	/ Re	port
--------------	-------	------	------

Project:	Durham Mea	dow	s Pipeline Installation	-			Date: Septem	ber 14, 2021
Location:	Wallingford F	Road	and Maple Avenue, Durham	ı			Day of Week:	Tuesday
	•						Deve evit Nev	222
Project #:	AECOM: 606	1487					Report No:	322
Contractor:	Ludlow Cons		ion				Page:	1 of 16
Contractor:	Luciow Cons	ruci	1011					
			Weather (Cond	litio	ns		
Conditions:	Daylig	ht h	ours: Sunny. Winds variable	0-2	mpl	n.		
Temperature (°F):	High	7	9°F Low 59°F					
						1		
			ontractors Workforce		1	1.	Equipment in Use	
Trade	# x h	S	Trade	#	Х	hrs	Туре	# x Hrs
USACE			Ludlow Construction				Concrete/Asphalt Road Saw	0 x 8
Field Engineer	1 x 8	;	Superintendent	1	Х	8	Dump truck	1 x 8
			Safety Officer	1	Х	8	Excavator – Large	0 x 8
			Foreman	1	Х	8	Excavator - Mid-Size	1 x 8
			Dump truck Operator	1	Х	8	Excavator - Rubber Wheeled	1 x 8
			Excavator Operator	1	Х	8	Skid Steer / Bucket Loader	1 x 8
			Skid Steer/Bucket Loader	1	Х	8	Rolling Compactor	1 x 8
			Laborers	4	Х	8	Plate Compactor	0 x 8
United Concrete	0 X 8	;	Note that some persons				Jumping Jack Compactor	1 x 8
Fazzino Plumbing	2 x 8		operate multiple pieces				Street Sweeper (Broce Broom)	1 x 8
A&R Electrical	0 x 8		of equipment.				Material Hopper	0 x 8
CT Traffic Control	1 x 8	;	Sub-contractor	3	Х	8	cutoff saw	1 x 8
DN Tanks	0 x 8		Municipal Police Detail	0	Х	8	Light Tower	0 x 8
			State Police Detail	0	Х	8		
Visitors:								

Pipe Connections, Installations, and Other Work

Ludlow finished repairing the lawn at 22 Wallingford Road, Durham, after they installed a 1.5" copper water service line and installed a 1" copper water service line at the 148 Maple Avenue residence. Fazzino Plumbing installed final water service components at residences located at 133, 146, and 148 Maple Avenue in Durham.

Daily Activities - Installation of water lines, Wallingford Road and Maple Avenue, Durham

Ludlow finished repairing the lawn at 22 Wallingford Road, Durham, after they installed a 1.5" copper water service line and installed a 1" copper water service line at the 148 Maple Avenue residence.

0700: Ludlow returns to the 22 Wallingford Road, Durham, property to continue restoration activities on the portions of the property that were disturbed during the installation of a 1.5" copper water service line. Ludlow is also assessing how they plan to repair the meter pit that they damaged yesterday at the 22 Wallingford Road property.

0816: Ludlow begins excavating on the east side of the 148 Maple Avenue residence for the installation of a 1" copper water service line.

Res. Representative:

J. Meunier

Date: 09/14/21

Daily Report

, , ,		
Durham Meadows Pipeline Installation	Date:	September 14, 2021
Wallingford Road and Maple Avenue, Durham	Day of Week:	Tuesday
AECOM: 6061487	Report No:	322
Ludlow Construction	Page:	2 of 16
	Wallingford Road and Maple Avenue, Durham AECOM: 6061487	Wallingford Road and Maple Avenue, DurhamDay of Week:AECOM: 6061487Report No: Page:

0846: Ludlow continues excavating at the 148 Maple Avenue property for the installation of a 1" copper waterline. Ludlow has daylighted the poured concrete foundation on the east side of the residence.

0918: Ludlow continues to spread and grade loam at the 22 Wallingford Road property to restore those areas of the lawn that were disturbed during installation of a 1.5" copper water service line.

0931: Ludlow continues to excavate on the east side of the 148 Maple Avenue residence forte installation of a 1" copper water service line. Ludlow is currently jackhammering rock they have encountered at the bottom of the trench, located approximately 25' west of the curb stop.

0946: Ludlow continues to jackhammer rock in the trench they are excavating on the east side of 148 Maple Avenue residence.

0959: Ludlow continues to spread and rake out loam at the 22 Wallingford Road property.

1046: Ludlow has drilled through the eastern foundation of the 148 Maple Avenue residence with a rotary hammer. The penetration point is located 9.5' south of the northeast corner of the house. Ludlow is preparing to place non-shrink grout where the 1" copper pipe passes through the east side of the home's foundation.

1141: Ludlow is working on replacing the meter pit they damaged yesterday at 22 Wallingford Road, Durham, property.

1221: Ludlow has finished installing a new meter pit at the 22 Wallingford Road property. Ludlow is currently backfilling around the meter pit with native fill and compacting it with a jumping jack.

1239: Ludlow is backfilling over the 1" copper water service line they installed at the 148 Maple Avenue property.

1305: Ludlow continues to backfill over the 1" copper water service line they installed at the 148 Maple Avenue property.

1326: Ludlow has almost finished restoring those portions of the lawn at the 22 Wallingford Road property that were disturbed during the installation of a 1.5" copper water service line.

1341: Ludlow is spreading grass seed on the loam they just placed on those areas of the lawn at the 22 Wallingford Road property that were disturbed during the installation of a 1.5" copper water service line.

1354: Ludlow continues to place and grade loam on those portions of the 148 Maple Avenue property that were disturbed during the installation of a 1" copper water service line.

Daily Activities - Installation of final water service components, Durham

Fazzino Plumbing installed final water service components at residences located at 133, 146, and 148 Maple Avenue in Durham.

1058: Fazzino Plumbing is installing final water service components at the 133 Maple Avenue residence in Durham.

1139: Fazzino Plumbing is finishing up with the installation of final water service components at the 133 Maple Avenue residence.

Res. Representative:

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	September 14, 2021
Location:	Wallingford Road and Maple Avenue, Durham	Day of Week:	Tuesday
Project #:	AECOM: 6061487	Report No:	322
Contractor:	Ludlow Construction	Page:	3 of 16

1157: Fazzino Plumbing finishes with the installation of final water service components at the 133 Maple Avenue residence.

1229: Fazzino Plumbing has mobilized to the 146 Maple Avenue residence for the installation of final water service components.

1516: Fazzino Plumbing has mobilized to the 148 Maple Avenue residence for the installation of final water service components.

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	September 14, 2021
Location:	Wallingford Road and Maple Avenue, Durham	Day of Week:	Tuesday
Project #:	AECOM: 6061487	Report No:	322
Contractor:	Ludlow Construction	Page:	4 of 16



Picture 1: Ludlow excavating a trench at the 148 Maple Avenue property for the installation of a 1" copper water service line. View to the east.

Daily Report

	· · · ·		
Project:	Durham Meadows Pipeline Installation	Date:	September 14, 2021
Location:	Wallingford Road and Maple Avenue, Durham	Day of Week:	Tuesday
Project #:	AECOM: 6061487	Report No:	322
Contractor:	Ludlow Construction	Page:	5 of 16



Picture 2: Ludlow jackhammering rock they encountered while excavating a trench at the 148 Maple Avenue property in Durham. View to the west.

Daily Report

	7 1		
Project:	Durham Meadows Pipeline Installation	Date:	September 14, 2021
Location:	Wallingford Road and Maple Avenue, Durham	Day of Week:	Tuesday
Project #:	AECOM: 6061487	Report No:	322
Contractor:	Ludlow Construction	Page:	6 of 16



Picture 3: Ludlow placing 1" copper water service line in the trench they excavated at the 148 Maple Avenue property in Durham. View to the west.

Daily Report

	<i>1</i> 1		
Project:	Durham Meadows Pipeline Installation	Date:	September 14, 2021
Location:	Wallingford Road and Maple Avenue, Durham	Day of Week:	Tuesday
Project #:	AECOM: 6061487	Report No:	322
Contractor:	Ludlow Construction	Page:	7 of 16



Picture 4: Ludlow connecting 1" copper water service line to the curb stop for the 148 Maple Avenue to property in Durham. View to the south.

Daily Report

	<i>7</i> 1		
Project:	Durham Meadows Pipeline Installation	Date:	September 14, 2021
Location:	Wallingford Road and Maple Avenue, Durham	Day of Week:	Tuesday
Project #:	AECOM: 6061487	Report No:	322
Contractor:	Ludlow Construction	Page:	8 of 16



Picture 5: 1" copper water service line that Ludlow has inserted through the foundation for the 148 Maple Avenue residence, prior to securing it in place with non-shrink grout. View to the west.

Daily Report

Durham Meadows Pipeline Installation	Date:	September 14, 2021
Wallingford Road and Maple Avenue, Durham	Day of Week:	Tuesday
AECOM: 6061487	Report No:	322
Ludlow Construction	Page:	9 of 16
	Wallingford Road and Maple Avenue, Durham AECOM: 6061487	Wallingford Road and Maple Avenue, DurhamDay of Week:AECOM: 6061487Report No: Page:



Picture 6: Ludlow removing the meter pit they damaged yesterday at 22 Wallingford Road in Durham as they prepare to replace it. View to the north.

Daily Report

	7 1		
Project:	Durham Meadows Pipeline Installation	Date:	September 14, 2021
Location:	Wallingford Road and Maple Avenue, Durham	Day of Week:	Tuesday
Project #:	AECOM: 6061487	Report No:	322
Contractor:	Ludlow Construction	Page:	10 of 16



Picture 7: Ludlow compacting native fill that they backfilled into the trench at the 148 Maple Avenue residence in 1' lifts. View to the north.

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	September 14, 2021
Location:	Wallingford Road and Maple Avenue, Durham	Day of Week:	Tuesday
Project #:	AECOM: 6061487	Report No:	322
Contractor:	Ludlow Construction	Page:	11 of 16



Picture 8: Ludlow grading loam they placed on the 22 Wallingford Road property to restore those areas of the lawn that were disturbed during the installation of a 1.5" copper water service line. View to the east.

Daily Report			
Project:	Durham Meadows Pipeline Installation	Date:	September 14, 2021
Location:	Wallingford Road and Maple Avenue, Durham	Day of Week:	Tuesday
Project #:	AECOM: 6061487	Report No:	322
Contractor:	Ludlow Construction	Page:	12 of 16



Picture 9: Ludlow compacting fill against the eastern foundation of the 148 Maple Avenue residence after installing a 1" copper water service line at the residence. View to the northwest.

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	September 14, 2021
Location:	Wallingford Road and Maple Avenue, Durham	Day of Week:	Tuesday
Project #:	AECOM: 6061487	Report No:	322
Contractor:	Ludlow Construction	Page:	13 of 16



Picture 10: Ludlow placing loam on the areas of the 148 Maple Avenue property that were disturbed during the installation of a 1" copper water service line. View to the north.

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	September 14, 2021
Location:	Wallingford Road and Maple Avenue, Durham	Day of Week:	Tuesday
Project #:	AECOM: 6061487	Report No:	322
Contractor:	Ludlow Construction	Page:	14 of 16



Picture 11: Final water service components that Fazzino Plumbing installed today at the residence located at 133 Maple Avenue, Durham.


Res. Representative:

J. Meunier

Date: 09/14/21

Daily Report

Project:	Durham Meadows Pipeline Installation	Date:	September 14, 2021
Location:	Wallingford Road and Maple Avenue, Durham	Day of Week:	Tuesday
Project #:	AECOM: 6061487	Report No:	322
Contractor:	Ludlow Construction	Page:	15 of 16



Picture 12: Final water service components that Fazzino Plumbing installed today at the residence located at 148 Maple Avenue, Durham.

Res. Representative:

Daily Report

· · · ·		
Durham Meadows Pipeline Installation	Date:	September 14, 2021
Wallingford Road and Maple Avenue, Durham	Day of Week:	Tuesday
AECOM: 6061487	Report No:	322
Ludlow Construction	Page:	16 of 16
	Wallingford Road and Maple Avenue, Durham AECOM: 6061487	Wallingford Road and Maple Avenue, DurhamDay of Week:AECOM: 6061487Report No: Page:



Picture 13: Final water service components that Fazzino Plumbing installed today at the residence located at 146 Maple Avenue, Durham.

Res. Representative:

J. Meunier

Date: 09/14/21