QUALITY ASSURANCE REPORT (QAR) DAILY LOG OF CONSTRUCTION											REPORT NUMBER 939 DATE			Page 1 of 0		
DRO IECT												14 Jul 2021 - Wednesday CONTRACT NUMBER				
PROJECT Durham Meadows Waterline Remedial Design												W912WJ19C0002				
CONTRACTOR Ludlow Construction Co., Inc.												WEATHER Weather Caused No Delay Temperature Min 65 °F Max 84 °F 0.09 IN Precipitation No Wind				
PORTION OF SCHEDULED DAY SUITABLE FOR OPERATIONS												TEMPERATURE WIND				
STRUCTURAL EXCA- VATION 0 % BORROW EXCA- VATION 0 % EMBANKM					MENT 0 %	CONCRI	ETE 0 %		UCTURE	0 %	MINIMUM 65 °	MAXIMUM F 84	°F		0 MPH	
		1	X	10				24 HOUR PRE	CIPIT	TATION						
HAS ANYTHING DEVELOPED ON THE WORK WHICH MIGHT LEAD TO A CHANGE ORDER OR FINDING OF FACT? YES (Explain)											INCHES ENDING 0.09 M					
NUMBER OF GOVERNMENT											RIVER STAGE					
SUPERVISORY	OFFICE		LAYO	UT	INSPECTION		TOTAL		LABOR		FEET			TIME		
0		0		0		0		0		0		0.0			М	
NUMBER SUPERVISORY	OF CONTRA	ACTO	R'S EM LABOI		TOTAL		NUMBE FROM		SHIFTS TO	Teb	1	<u>x</u> 2 [3 ROM		то	
	SKILLED		LABOI		TOTAL		FROW		10				KOW			
0	oh a liet of the	0 follow	uina (c	0	ma of oqui	0	or idlo or u	orkina	and (h) N	M	M nd algorification	of contractor per	aannal	M	M	
Attach a list of the following. (a) Major items of equipment either idle or working, and (b) Number and classification of contractor personnel onsite. NOTE: if the contractor's Quality Control Report (QCR) contains the information it need not be repeated.																
QA NARRATIVES Work Performed Today: Unresolved Issue: No Shift: 1																
Kurt Mintell Exterior water connections: Church on Main - connect at curb stop to existing well line 233 main Street = 16 LF of 1" copper United Concrete - electrician onsite at AV Ct Flagger - 1 onsite for exterior connections - Howard Safety: Unresolved Issue: No Shift: 1 Joseph Currier Safety Inspections litems: 1, PPE - good 2, Traffic pattern/control - Traffic control for the Perm Pavement work on 17 - 1 flagger 3. Working in excavation - Trenching for exterior 1" pipe from curb stop to house - trench box utilized if deeper the 5 feet. NONE TODAY 4. Muddy & trip hazards - while trenching and working around tight quarters 4. Situational awareness while working around heavy equipment. Excavating for trench/ mini excavator 5. Proper lifting techniques - lift with knees not low back 6. COVID - no discussion today 7. Concrete placement today - NONE 8. Caps on REBAR at booster station - on the rebar for the generator. 9. Ladders in the trench - as needed 10. Safety Meeting to review bad weather protocols while working 11. DN - NONE TODAY																
QA REPRESENTA	TIVE'S SIGN	ATURI	E		IDA	TE			l RF	/PROJEC	T ENGR'S INITI	ALS	ı	DATE		
J	2331010	ن	_													