QUALITY ASSURANCE REPORT (QAR) DAILY LOG OF CONSTRUCTION										REPORT NUMBER 925				Page 1 of 0		
										DATE 30 Jun 2021 - Wednesday						
PROJECT										CONTRACT NUMBER						
Durham Meadows Waterline Remedial Design										W912WJ19C0002						
CONTRACTOR Ludlow Construction Co., Inc.										WEATHER Weather Caused No Delay Temperature Min 81 °F Max 92 °F No Precipitation No Wind						
PORTION OF SCHEDULED DAY SUITABLE FOR OPERATIONS											TEMPERATURE WIND					
STRUCTURAL EX	CA- BORROV VATION	N EXCA-	EMBANK	MENT	CONCR	ETE	STR	UCTURE		MINIMUM	1	MAXIMUM				
	0 %	0 %		0 %		0 %	6		0 %		81 °F	92	°F		0 MPH	
HAS ANYTHING DEVELOPED ON THE WORK WHICH MIGHT										24 HOUR PRECIPITATION						
LEAD TO A CHANGE ORDER OR FINDING OF FACT? YES (Explain)										INCHES ENDING 0.00					М	
			OF GOVERNMENT EMPLOYEES YOUT INSPECTION			TOTAL LABOR				RIVER ST.				AGE TTIME		
	OFFICE			INSPECT						FEET				IIVIE		
0 NUMBER	 R OF CONTRAC	0 CTOR'S EM	0 IPLOYEES	<u> </u>	2		2 SER OF	SHIFTS	0	<u> </u> □ 1	X	0.0	3		M	
SUPERVISORY	SKILLED		RERS	TOTAL		FROM		TO	FR	ROM	TO		ROM		ТО	
0		0	0		0		0700	1500	м		М	м		м	М	
Atta	ach a list of the	following. (a	a) Major ite	ems of equi	pment eitl	her idle or	working	g, and (b) Nu	mber a	nd classific	ation of	contractor per	sonnel	l onsite.		
QA NARRA		actor's Quar	iity Control	Report (Q	JR) COIIIA	iiis iie iiii	omalio	ii ii need not	be rep	ealeu.						
	rmed Today:							Un	resolv	ed Issue:	No	Shift:	1			
Kurt Minte		rious loss	tiono:													
SAWCUT	nt Paving at va at:	irious ioca	ilioris.													
1. Pickett	& Maiden															
2. Winsom	ne & 17															
3. 68 & 17 4. Talcott																
5. Maiden & 17																
6. Pickett 7.Old Cen	& 17 netery & 17															
	of 208 Main															
Noted KTF 3" + 3" + 3	R sawcut and B" = 9"	excavated	d 9", place	ed steel p	lates ov	er the blo	w off v	/alve locati	ons an	id paved t	he loca	tion				
Results of 0	QA Inspection	ns and Te	sts, Defi	ciencies (Observe	d, Actio	ns Tak	en: Un	resolv	ed Issue:	No	Shift:	2			
Kurt Minte		4														
Noted:	of the tank in	terior														
	ntractor has sk d additional sk				entified in	n the orig	inal ins	spection. N	oted th	ne skim w	as not	all the way to	the b	oottom.		
	touch up pain				ne pipes	inside th	e wate	er tank. KTF	R will d	lo this whe	en they	return				
Safety:								Un	resolv	ed Issue:	No	Shift:	1			
Kurt Minte	ell pections items															
	good at 2 sepa		sites.													
	oattern/control															
	g in excavatior & trip hazards							ouse - trend	n box	utilizea ii	deeper	the 5 leet.				
Situatio	nal awareness	s while wo	orking aro	und heav	equipm			g for trench	n/ mini	excavato	r					
	lifting techniqu - no discussio		itii knees	HOLIOW D	ack											
	te placement t			tha rabar:	for the a	anaratar										
	n REBAR at be s in the trench			lile rebai	ioi ille g	епегают.										
	Meeting for porting in the f					entranc	e to th	e tank -								
11. DN - W	TOTALING III UIC	ann - not	ou log III I	og out sill	ocat un	o chilant		o tank -								
QA REPRESENTA	ATIVE'S SIGNA	TURE		DA	TE			RE/P	ROJEC	T ENGR'S	INITIAL	S		DATE		