PROJECT Durham Meadows Waterline Remedial Design  CONTRACTOR Ludlow Construction Co., Inc.  WEATHER Weather Caused No Delay Temperature Min 50 °F Max 62 °F No Precipitation 5 MPH Wind  PORTION OF SCHEDULED DAY SUITABLE FOR OPERATIONS  STRUCTURAL EXCA- VATION  O %  O %  O %  O %  TEMPERATURE  WIND  MINIMUM  MAXIMUM  M	QUALITY ASSURANCE REPORT (QAR) DAILY LOG OF CONSTRUCTION											REPORT NUMBER 1022			Page 1 of 0			
Durism Maadows Waterline Remedial Design CORTINACTOR Luddow Construction Co., Inc.  WATHER Water Caused No Delay Temperature Info 107 F, Max 62 °F Water Caused No Delay Temperature Info 107 F, Max 62 °F Water Caused No Delay Temperature Info 107 F, Max 62 °F Water Caused No Delay Temperature Info 107 F, Max 62 °F Water Caused No Delay Temperature Info 107 F, Max 62 °F Water Caused No Delay Temperature Info 107 F, Max 62 °F Water Caused No Delay Water Caused																		
CONTRACTOR Ladiow Construction Co., Inc.    WAFTHER   Weather Cassed No Delay   Weather Cassed No Delay   Transportants bits 00° F May 60° F		adow	s Waterline	Reme	dial Desig	an												
Temperature Min 50 F Max 82 F No Previous State Min	CONTRACTOR	2			<u> </u>	·												
PORTION OF SCHEDULED DAY SUITABLE FOR OPERATIONS  TEMPERATURE WIND  WHICH WAITON WHICH W	Ludion Const.	Edulow Constitution Co., inc.												Max 62 °	°F			
WATION  ON O		PORTION OF SCHEDULED DAY SUITABLE FOR OPERATIONS												TEMPERATURE WIND				
HAS ANYTHING DEVELOPED ON THE WORK WHICH MIGHT  HAS ANYTHING DEVELOPED ON THE WORK WHICH MIGHT  LEAD TO A CHANGE ORDER OF FINDING OF FAIR  NUMBER OF COVERNMENT EMPLOYEES  SUPERVISORY  OFFICE  LAYOUT  INSPECTION  NUMBER OF COVERNMENT EMPLOYEES  SUPERVISORY  OFFICE  LAYOUT  INSPECTION  NUMBER OF CONTRACTORS EMPLOYEES  NUMBER OF SHIFTS  I I I I I I I I I I I I I I I I I I I		CA-		XCA-	EMBANK	(MENT	CONCR	ETE.	STRUCTURE			MINIMUM	MAXIMU	М				
HAS ANYTHING DEVELOPED ON THE WORK WHICH MIGHT LEAD TO A CHANGE ORDER OF RINDING OF FART?    NUMBER OF GOVERNMENT EMPLOYEES	W.(110.1	0 %	VALION	0 %	0 %		<u> </u>	0 %	C		0 %	<u> </u>						
NUMBER OF CONTRACTORS EMPLOYEES  SUPERVISORY  OFFICE  LAYOUT  INSPECTION  O  O  O  O  O  O  O  O  O  O  O  O							IIGHT	X N	10			INCHES	24 HOUR I					
SUPERVISORY OFFICE LAYOUT INSPECTION TOTAL LABOR FEET 0.0 TIME  NUMBER OF CONTRACTORS EMPLOYEES NUMBER OF SHIFTS 1 1 2 3 3  SUPERVISORY SKILLED LABORERS TOTAL FROM TO FROM TO FROM TO FROM TO FROM M M M M M S M M M M M S M M M M M M S M M M M M M M M M M M M M M M M M M M M							? YES (Explain)									М		
NUMBER OF CONTRACTORS EMPLOYEES  NUMBER OF CONTRACTORS EMPLOYEES  NUMBER OF SHIFTS    1     2   3																		
NUMBER OF CONTRACTOR'S EMPLOYEES  SUPERVISORY  SKILLED  LABORERS  TOTAL  TOTAL  TOTAL  TROM  N  M  M  M  M  M  M  M  M  M  M  M  M		OFF		LAYO		INSPECT	TON	TOTAL		LABOR		FEET			TIME			
SUPERVISORY SKILLED LABORERS TOTAL 1 FROM TO FROM TO FROM TO FROM TO FROM TO A MACHINE STATES AND THE STATES AN				DIS EN			1			NULTO	0	<u> </u>			2	M		
Attach a list of the following. (a) Major items of equipment either idle or working, and (b) Number and classification of contractor personnel onsite.  NOTE: if the contractor's Quality Control Report (QCR) contains the information it need not be repeated.  Work Performed Today:  Joseph Currier  Ludlow crew:  Working at 24 and 36 Maiden Lane installing the external water service. A small crew broke off later in the day to continue grading and site restoration at the metering vault.  1. Rock encountered - NA 2. Cut parking lot - NA 3. Remove bushes/trees - NA 4. Flagger being utilized - Yes  AR Electric - Not onsite today.  DN Tank - Not onsite today.  Fazzino Plumbing - At 308, 316 and 321 Main Street. Two plumbers are completing the final water tie in and removal of filter systems.  Apuzzo Electrical - Not on site today.  Safety:  Joseph Currier Safety Inspections items:  1. PPE - Good -  2. Traffic pattern/control - flagger on site at Maiden Lane 3. Working in excavation - yes short run of excavation at 24 and 36 Maiden Lane 4. Muddy & trip hazards: while trenching and working around tight quarters - none today 4. Situational awareness while working around heavy equipment. Excavating for trench' mini excavator 5. Proper lifting techniques: while trenching and working around tight quarters - none today 4. Situational awareness while work day - Agreed that workers will wear a mask when entering someone's home 7. Ladders in the trench - as needed. 8. Equipment being driven on roads - have a truck behind with flashing lights. 9. Safety mask / full cover while cutting rebar. 10. Hearing protection used during ledge removal operations - NO ledge removal today. 11. Sika requirements - NA today.  NO new safety issues to review today.											FR					ТО		
Attach a list of the following. (a) Major items of equipment either idle or working, and (b) Number and classification of contractor personnel onsite.  NOTE: if the contractor's Quality Control Report (QCR) contains the information it need not be repeated.  Work Performed Today:  Joseph Currier  Luddow crexi:  Working at 24 and 36 Maiden Lane installing the external water service. A small crew broke off later in the day to continue grading and site restoration at the metering vault.  1. Rock encountered - NA 2. Cut parking lof - NA 3. Remove bushes/trees - NA 4. Flagger being utilized - Yes  AR Electric - Not onsite today.  DN Tank - Not onsite today.  Fazzino Plumbing - At 308, 316 and 321 Main Street. Two plumbers are completing the final water tie in and removal of filter systems.  Apuzzo Electrical - Not on site today.  Safety:  Joseph Currier  Safety Inspections items:  1. PPE - Good -  2. Traffic pattern/control - flagger on site at Maiden Lane 3. Working in excavation - yes short run of excavation at 24 and 36 Maiden Lane 4. Muddy & trip hazards: while trenching and working around tight quarters - none today 4. Situational awareness while working around heavy equipment. Excavating for trench' mini excavator 5. Proper lifting techniques: while trenching and working around tight quarters - none today 4. Situational awareness while working around with flashing lights. 9. Safety mask / full cover while cutting rebar. 10. Hearing protection used during ledge removal operations - NO ledge removal today. 11. Sika requirements - Na today  REVIEW WITH SSHO: NO new safety issues to review today.	2		4		4		10			N	1	М	N	<u>,                                    </u>	М	М		
Work Performed Today: Joseph Currier Ludlow crew: Working at 24 and 36 Maiden Lane installing the external water service. A small crew broke off later in the day to continue grading and site restoration at the metering vault.  1. Rock encountered - NA 2. Cut parking lot - NA 3. Remove bushes/frees - NA 4. Flagger being utilized - Yes AR Electric - Not onsite today. DN Tank - Not onsite today. Fazzino Plumbing - At 308, 316 and 321 Main Street. Two plumbers are completing the final water tie in and removal of filter systems. Apuzzo Electrical - Not on site today. Safety: Joseph Currier Safety Inspections items:  1. PPE - Good - 2. Traffic pattern/control - flagger on site at Maiden Lane 3. Working in excavation - yes short run of excavation at 24 and 36 Maiden Lane 4. Muddy & trip hazards - while trenching and working around tight quarters - none today 4. Situational awareness while working around heavy equipment. Excavating for trench/ mini excavator 5. Proper filting techniques - lift with knees not low back 6. COVID - Discussion prior the work day - Agreed that workers will wear a mask when entering someone's home 7. Ladders in the trench - as needed. 8. Equipment being driven on roads - have a truck behind with flashing lights. 9. Safety wask / full cover while cutting rebar. 10. Heaning protection used during ledge removal operations - NO ledge removal today. 11. Sika requirements - NA today REVIEW WITH SSHO. NO new safety issues to review today.	Atta		list of the follo		a) Major ite		ipment eith	her idle or w		and (b) Numb	ber ar	nd classification o						
Work Performed Today:  Joseph Currier  Ludlow crew:  Working at 24 and 36 Maiden Lane installing the external water service. A small crew broke off later in the day to continue grading and site restoration at the metering vault.  1. Rock encountered - NA 2. Cut parking lot - NA 3. Remove bushes/trees - NA 4. Flagger being utilized - Yes  AR Electric - Not onsite today.  DN Tank - Not onsite today.  Fazzino Plumbing - AI 308, 316 and 321 Main Street. Two plumbers are completing the final water tie in and removal of filter systems.  Apuzzo Electrical - Not on site today.  Safety:  Unresolved Issue: No Shift: 1  Joseph Currier  Safety Inspections items:  1. PPE - Good - 2. Traffic pattern/control - flagger on site at Maiden Lane 3. Working in excavation - yes short run of excavation at 24 and 36 Maiden Lane 4. Muddy & trip hazards - while trenching and working around tight quarters - none today 4. Situational awareness while working around heavy equipment. Excavating for trench/mini excavator 5. Proper lifting techniques - lift with knees not low back 6. C.OVID - Discussion prior the work day - Agreed that workers will wear a mask when entering someone's home 7. Ladders in the trench - as needed. 8. Equipment being driven on roads - have a truck behind with flashing lights. 9. Safety mask full cover while cutting rebar. 10. Hearing protection used during ledge removal operations - NO ledge removal today. 11. Sika requirements - NA today.  NO new safety issues to review today.																		
Joseph Currier Ludlow crew: Working at 24 and 36 Maiden Lane installing the external water service. A small crew broke off later in the day to continue grading and site restoration at the metering vault.  1. Rock encountered - NA 2. Cut parking lot - NA 3. Remove bushes/frees - NA 4. Flagger being utilized - Yes AR Electric - Not onsite today. DN Tank - Not onsite today. DN Tank - Not onsite today. Fazzino Plumbing - At 308, 316 and 321 Main Street. Two plumbers are completing the final water tie in and removal of filter systems. Apuzzo Electrical - Not on site today. Safety: Unresolved Issue: No Shift: 1 Joseph Currier Safety Inspections items:  1. PPE - Good - 2. Traffic pattern/control - flagger on site at Maiden Lane 3. Working in excavation - yes short run of excavation at 24 and 36 Maiden Lane 4. Muddy & trip hazards - while trenching and working around heavy equipment. Excavating for trench/ mini excavator 5. Proper lifting techniques - lift with knees not low back 6. COVID - Discussion prior the work day - Agreed that workers will wear a mask when entering someone's home 7. Ladders in the trench - as needed. 8. Equipment being driven on roads - have a truck behind with flashing lights. 9. Safety mask / full cover while cutting rebar. 10. Hearing protection used during ledge removal operations - NO ledge removal today. 11. Sika requirements - NA today REVIEW WITH SSHO. NO new safety issues to review today.										Unre	solve	ed Issue: No	Sh	ift: 1				
<ol> <li>Traffic pattern/control - flagger on site at Maiden Lane</li> <li>Working in excavation - yes short run of excavation at 24 and 36 Maiden Lane</li> <li>Muddy &amp; trip hazards - while trenching and working around tight quarters - none today</li> <li>Situational awareness while working around heavy equipment. Excavating for trench/ mini excavator</li> <li>Proper lifting techniques - lift with knees not low back</li> <li>COVID - Discussion prior the work day - Agreed that workers will wear a mask when entering someone's home</li> <li>Ladders in the trench - as needed.</li> <li>Equipment being driven on roads - have a truck behind with flashing lights.</li> <li>Safety mask / full cover while cutting rebar.</li> <li>Hearing protection used during ledge removal operations - NO ledge removal today.</li> <li>Sika requirements - NA today</li> <li>REVIEW WITH SSHO:</li> <li>NO new safety issues to review today.</li> </ol>	site restora  1. Rock er 2. Cut parl 3. Remove 4. Flagger  AR Electri  DN Tank -  Fazzino Pl  Apuzzo El  Safety:	ation ncour king I e bus bein c - Not lumb	at the meter  Intered - NA Iot - NA Iot - NA Shes/trees - N g utilized - Y ot onsite today onsite today ing - At 308, cal - Not on s	NA Yes lay 316 ar	ult. nd 321 M day.	<i>l</i> lain Street				pleting the fi	inal v	water tie in and	removal of	f filter s				