QUALITY ASSURANCE REPORT (QAR)								REPORT NUMBER 491				Page 1 of 0				
DAILY LOG OF CONSTRUCTION										DATE 22 Apr 2020 - Wednesday						
PROJECT										CONTRA			шу			
Durham Meadows Waterline Remedial Design								W912WJ19C0002								
CONTRACTOR Ludlow Constr	ruction Co., Inc.									Tempe	er Cause erature N	ed No Delay Min 37 °F Mi Ditation 25 M				
	PORTION C	F SCHEDU	ILED DAY	SUITABLE	FOR OP	ERATIONS						RATURE			WIND	-
				EMBANKMENT CONCRETE STR			STRI	RUCTURE		MINIMUM		MAXIMUM				
VATION	0 %	0 %		0 %		0 %			0 %		37 °F	04 HOUD D	0 °F	NITATION!	25	MPH
	HING DEVELO				GHT	X N	0			INCHES		24 HOUR P		ENDING		
LEAD TO A CHANGE ORDER OR FINDING FO FACT?					YES (Explain)				0.43				LINDING		М	
CLIDED///CODY			GOVERNMENT EMPL					LADOD		RIVER S			R STA	GE TIME		
SUPERVISORY	OFFICE	LAYO	UI	INSPECT	ION	TOTAL		LABOR		FEE1				TIME		
0	05.000,504	0	0		2		2	01,115	0			0.0				М
NUMBER SUPERVISORY	SKILLED		RERS	TOTAL		NUMBE FROM		TO	TFR	1 .OM	ТО		FRON	3 1	TO	
0 Δ#s	ch a list of the	following (a	0 Major ite	me of equi	0 oment eith	•	00 orking	1700 M		nd classific	M of	M contractor n	oreonr	M onsite		M
	TE: if the contra										allon or	contractor p	CISOIII	iei orisite.		
QA NARRAT																
	Subcontract	or & Area	of Respo	onsibility	for Worl	C:		Unre	solve	ed Issue:	No	Shift	t: 1			
Robert Chi Project inv	ristie olves installin	ıg water m	ain from	a new Mid	ldletown	Water Tar	nk into	o Durham an	nd tyi	ng into h	omes &	businesse	s:			
Subcontra Subcontra Subcontra Subcontra	tractor: Ludlo ctor: ACE Co ctor: Connect ctor: John Tu ctor Vellieux n Police - 0	nsulting - S icut Traffic rner Consu	SSHO Ro Control	b Peddico - 0	ord & CC	componei C Jerry Br	nts. rando	n								
	med Today:							Unre	solve	ed Issue:	No	Shift	t: 1			
Installed 1 [°] Installed 2 [°]	ristie k Site and Ac 7.4 feet of 18 7 feet of 24" f new catch ba	" Reinforce Reinforced	ed concre													
Continued Installed 3	n Roads: 3 S installing the - 1" water co ucted compac	16" Restra	ained pip	e from sta).5								
1- Ludlow	employee wo	rked on pr	essurizin	g and test	ting the v	vater main										
2. Fire Hyd 3. Police - 4. Illuminar 5. Sawcut 6. Sawcut 7. 16" Res 8. 20 inch 10. Ledge 11. Trailer 12. 8 inch 13. Bank F 14. Manua 15. 16x16 16. 16" Bu 17. 1" Corl	rained Pipe - drant Assemb 3 State Police ted Signs - y Town Roads State Roads trained Pipe - pipe at acces pipe Restrain Removal - No cleaned - no Gate Valve - 1 I Drain Asser 16 TEE - 0 tterfly valve - poration - 3 p stop - 0	ly - 0 ees - 0 Feet - 294 Fee - 147 s road - 0 ed - NA one encou today 0 11.7 nbly - 0		day												
19. 1" Coo	per pipe - 0															

Results of QA Inspections and Tests, Deficiencies Observed, Actions Taken: Unresolved Issue: No Shift: 1

Robert Christie

Observed the installation of the 16" Restrained pipe. At approximately 0730 they began excavating. Fabric was placed in the bottom of the excavation followed by 6" of 3/4" stone. Then the stone was covered with fabric. They then placed 3" of sand, installed the pipe and placed 12"of sand over the pipe followed by 3 - 12" lifts of native material and compacted each lift. Placed 2 - 8" lifts of processed gravel and compacted each lift. Finally placed 4" of HMA in two 2" compacted lifts.

Compaction Tests today - Yes, Observed Steve from John Turner Consulting performing the compaction tests. All of the tests were above the required 95%.

Contractor encountered ground water during the excavation. The water was pumped out into the woods and into a storm drain. The storm drain had a sediment control fabric.

Drove by the storage yard twice during my shift. Observation made both times was no material was spilled on the ground and no damage to asphalt. The catch basin did have sediment control fabric in it and did not appear to be clogged.

Observed the installation of the new catch basin basin being installed on the tank access road.

Performed a SWPP post rain inspection of the worksite with SSHO Rob Peddicord & CQC Jerry Brandon at 0850. Found one small area of silt fence that was laying over a little from a part of a stump on it. Jerry stated he would pull it back up and secure it.

Verbal Instructions Given to Contractor: Unresolved Issue: No Shift: 1

Robert Christie

Spoke with Jon and Jerry asking them to ensure storm drains are covered & protected per the SWPP.

Miscellaneous Remarks and Visitors to Project: Unresolved Issue: No Shift: 1

Robert Christie
Jerry - QC
Rob P - SSHO
John Pio - Superintendent
Mike Pio - onsite
USACE - KM

AECOM - Joel was onsite providing extra oversight of the contractor.

Mike Cunningham Steve - JTC Consulting

Miscellaneous Remarks and Visitors to Project: Unresolved Issue: No Shift: 1

Robert Christie

Water encountered while excavating:

Water was encountered on 17 while excavating. Contractor installed a sump pump and was able to pump water from the trench while excavating.

Water was encountered while excavating the tank access road to install a new catch basin. Contractor installed a sump pump and was able to pump water from the trench while excavating.

PR Comments, encounters or issues:

Contractor hit a fiber optic line at approximately station 165+76. 2 representatives from Keystone communications came out determined there wasn't any damage to the line. They performed a temporary repair for the night and will be back tomorrow to do a permanent fix. Steve from CT DOT was onsite and is aware of it. ** (See the two attached pictures labeled Fiber Optic line) ** Crew was onsite till 1700 due to this.

CT DOT onsite or communication: Steve, Dale and Chris were onsite, They had no issues.

Steve did mention that he thinks the asphalt plant is going to be open nights starting next week since Eversource is starting work this Sunday. If that occurs they said he will be having us switch over to nights.

Safety: Unresolved Issue: No Shift: 1

Robert Christie

Noted portable hand wash station on back of tool truck, cleaning supplies nitrile gloves, face masks.

Workers fill out daily forms indicating they are not demonstrating any symptoms of COVID 19 and turning into SSHO.

Daily Safety Inspections:

- 1. Noted proper PPE while cutting Steel pipe with cut off saw.
- 2. Traffic Control: 3 State Police and cones on 17 while installing the new water line
- 3. Discussed situational awareness while working around heavy equipment, and while allowing residents to use the shared driveway while under construction
- 4. Situational awareness not to work in close proximity to each other (COVID PREVENTION)
- 5. Trench box being used for all excavations while working in trench.

QA REPRESENTATIVE'S SIGNATURE	DATE	RE/PROJECT ENGR'S INITIALS	DATE	
W	5,=	1.2,1.1.00201 2.1.01.0 11.11.1.120	15, 2	
	I			