	QUALITY A DAILY I					AR)				REPORT N 500 DATE		ER) - Friday		Pa(ge 1 of 1	
PROJECT										CONTRAC		MBER				
	adows Waterline	Remed	lial Desig	n						W912W		0002				
CONTRACTOR Ludlow Constr	ruction Co., Inc.									Tempera	Cause ature N	ed Critical E Min 54 °F M pitation 22 M	Max 64 °			
	PORTION OF S	SCHEDU	LED DAY	SUITABLE	FOR OP	ERATIONS	3			TE	EMPER	RATURE			WIND	
STRUCTURAL EX		EXCA-	EMBANK	MENT	CONCR	ETE	STRU	CTURE		MINIMUM		MAXIMUN	N			
VATION	VATION 0 %	0 %		0 %		0 %			0 %		54 °F		64 °F		22 MP	н
	HING DEVELOPE				юцт	XN	NO					24 HOUR F	PRECIP			
	A CHANGE ORDE				IGITI		YES (Ex	plain)		INCHES				ENDING		
	N II 18 45						,	,				0.81				N
SUPERVISORY				INSPECT		ITOTAL		LABOR		FEET		RIVE	ER STA			
								2,12011								
	0 R OF CONTRACTO			<u> </u>	1		1 ER OF S		0		X	0.0		3		N
SUPERVISORY	SKILLED		-	, TOTAL		FROM			FF						ТО	
0	0		0		0	0	700	1530	м	N	л	М	1	М		Ν
	ach a list of the foll			ms of equi												
NO	TE: if the contracto	or's Quali	ity Control	Report (Q	CR) conta	ins the info	rmation	it need not	be rep	eated.						
Contractor/	Subcontractor	& Area	of Respo	onsibility	for Wor	k:		Ur	resolv	ed Issue: N	lo	Shi	ift: 1			
Robert Ch Project inv	ristie volves installing v	vater m	ain from	a new Mie	dletown	Water Ta	ink into	Durham	and ty	ing into hon	nes &	business	es:			
Subcontra Subcontra Middletow State Polic	ctor: Connecticu ctor: John Turne ctor Vellieux - 0 n Police - 0 ce -0 rmed Today:	er Consu						Lin	vresolv	ed Issue: N	10	Shi	ift: 1			
1	-							U	liesolv	ed issue. N	10	511	IL. I			
Billy's crev of the wate Received a 10+96. Installed a Worked or	ristie ik Site and Acce v dumped grave er tank site. a load of RCP pi catch basin at s n extending the s and repaired any	on the pe mid- tation 1 slope on	access r day and 0+40. i the left s	continued	to insta	ll the 12" F				,		,	0 1			
***(Due to	n Roads: 0 Stat the rain Steve \ the office/yard p	Nright fi	rom CT D	OT made	e the call	to not allo	ow the o	contracto	r to wo	rk on the st	tate ro	oad today)) *** Th	iis crew		
	om Ludlow press ressure tested Ta								ater lin	e held the ²	150lb:	s for the e	ntire te	∍st.		
Pickett lan No other w No deliver	vork was perforn	ned toda	ay.													
2. Fire Hyd 3. Police - 4. Illumina 5. Sawcut 6. Sawcut 7. 16" Res 8. 16" Non 9. 20 inch 10. 20 inch	trained Pipe - 0 drant Assembly 2 State Police ted Signs - yes Town Roads - (State Roads - 0 trained Pipe - 0 n-Restrained Pip pipe at access r n pipe Restraine Removal - No 0) Feet) Feet Feet e - 0 Fe oad - 0 d - NA														

12. Trailer cleaned - Not today								
13. 8 inch Gate Valve - 0								
14. Bank Run Gravel- 0 CY								
15. Manual Drain Assembly - 0								
16. 16x16x8 TEE - 0								
17. 16x16x16 TEE - 0								
18. 16" Butterfly valve - 0								
19. 1" Corporation - 0								
20. 1" Curb stop - 0								
21. 1" Cooper pipe - 0								
Results of QA Inspections and Tests, Deficiencie	es Observed, Actions Taken:	Unresolved Issue: No	Shift: 1					
Robert Christie								
Observed the water pressure test that was perform	med in Durham from station 132	+32 to 142+27. The test began at	0900. At 0910 I took					
a picture of the pressure gauge which read 150lb								
held the 150lbs of pressure at 1100 with a second								
	1 5 5							
Compaction Tests today - Not required today due	to only installing 20 feet of pipe.							
No water was encountered today.								
Drove by the storage yard twice during my shift. C			round and no					
damage to asphalt. The catch basin did have sed	iment control fabric in it and did	not appear to be clogged.						
Observations made at the tank site location were								
tank site. The dump truck would back up the hill, o		the bulldozer would spread the g	ravel out.					
Observed the crew installing the new catch basin	and the 12" RCP pipe.							
Verbal Instructions Given to Contractor:		Unresolved Issue: No	Shift: 1					
Robert Christie								
Jon Pio told me this morning that since they could	In't work on the state read today	that he was planning on porforming	a a pressure test in					
Durham today. I verbally instructed him to let me								
onsite Bill know and we both could verify it held th			representative					
	le required pressure.	Uprocedured leaves No	Chiffe 1					
Miscellaneous Remarks and Visitors to Project:		Unresolved Issue: No	Shift: 1					
Robert Christie								
Water encountered while excavating:								
N/A								
PR Comments, encounters or issues:								
No issues today.								
CT DOT onsite or communication: No								
Miscellaneous Remarks and Visitors to Project:		Unresolved Issue: No	Shift: 1					
Robert Christie								
Jerry - QC								
Rob P - SSHO								
John Pio - Superintendent								
Mike Pio - onsite								
AECOM - Bill was onsite covering for Joel								
Mike Cunningham								
JTC Consulting - No representative was onsite to	day							
Democranic Address for the Middle Address of the	- 44							
Representative from Middletown to verify pressure	e test							
Safety:		Unresolved Issue: No	Shift: 1					
Robert Christie								
Noted portable hand wash station on back of tool	truck cleaning supplies nitrile a	oves face masks						
Workers fill out daily forms indicating they are not)					
workers in our daily forms indicating they are not	any symptoms of		<i>.</i> .					
Daily Safety Inspections:								
1. Noted proper PPE while cutting Steel pipe with	cut off saw							
2. Traffic Control: 2 State Police and cones on 17		ine						
3. Discussed situational awareness while working			shared driveway					
while under construction			charod antoway					
	imity to each other (COVID PRE							
	 Situational awareness not to work in close proximity to each other (COVID PREVENTION) Trench box being used for all excavations while working in trench. 							
QA REPRESENTATIVE'S SIGNATURE	DATE	RE/PROJECT ENGR'S INITIALS	DATE					