

<b>QUALITY ASSURANCE REPORT (QAR) DAILY LOG OF CONSTRUCTION</b>					REPORT NUMBER 573		Page 1 of 0		
					DATE 13 Jul 2020 - Monday				
PROJECT Durham Meadows Waterline Remedial Design					CONTRACT NUMBER W912WJ19C0002				
CONTRACTOR Ludlow Construction Co., Inc.					WEATHER Weather Caused No Delay Temperature Min 72 °F Max 85 °F No Precipitation No Wind				
PORTION OF SCHEDULED DAY SUITABLE FOR OPERATIONS					TEMPERATURE		WIND		
STRUCTURAL EXCA- VATION	BORROW EXCA- VATION	EMBANKMENT	CONCRETE	STRUCTURE	MINIMUM	MAXIMUM			
0 %	0 %	0 %	0 %	0 %	72 °F	85 °F	0 MPH		
HAS ANYTHING DEVELOPED ON THE WORK WHICH MIGHT LEAD TO A CHANGE ORDER OR FINDING FO FACT?					24 HOUR PRECIPITATION				
					INCHES		ENDING		
					0.00		M		
NUMBER OF GOVERNMENT EMPLOYEES					RIVER STAGE				
SUPERVISORY	OFFICE	LAYOUT	INSPECTION	TOTAL	LABOR	FEET	TIME		
0	0	0	1	1	0	0.0	M		
NUMBER OF CONTRACTOR'S EMPLOYEES				NUMBER OF SHIFTS					
				<input type="checkbox"/> 1 <input checked="" type="checkbox"/> 2 <input type="checkbox"/> 3					
SUPERVISORY	SKILLED	LABORERS	TOTAL	FROM	TO	FROM	TO	FROM	TO
0	0	0	0	0700	1530 M	M	M	M	M
Attach a list of the following. (a) Major items of equipment either idle or working, and (b) Number and classification of contractor personnel onsite. NOTE: if the contractor's Quality Control Report (QCR) contains the information it need not be repeated.									
<b>QA NARRATIVES</b>									
<b>Work Performed Today:</b>					Unresolved Issue: No		Shift: 1		
Kurt Mintell KTR installed 12" pipe on the east bank of Allyn Brook. See note below									
Installed curb stops at: 391,395,385 - note additional water corp needed for 385 Main Street.									
Chlorination of main at Marina Place Road. - Adding 12.5% chlorine product - see photo									
Scott from DN Tank onsite accepting delivery of lumber for forming and a rental boom fork lift									
ITEMS: 0028: New tap for STA 163+01 for 385 Main Street , this will be a change since the curb stop location for this address was changed. 0031: 1" Curb Stops at 391,395,385 Main Street 0034: 1" copper pipe -119.5 0061: Sawcut State Road =168LF 47: FINISHED CONNECTING 12 INCH PIPE ON LOWER SIDE OF THE STREAM. STA 511+16 TO 512+11. WE WILL HAVE TO APPLY A STA CORRECTION SINCE BENDS CHANGE STA FOOTAGE SO THE GATE VALVE INSTALLED AT STA 512+00 WILL ALSO BE STA 512+11. CLEANED UP AND MOVED EVERYTHING OUT DOWN THE STREET TO BEGIN OTHER STREAM CROSSING. FINAL RESTORATION WILL BE COMPLETED ONCE WATER MAIN HAS PASSED A PRESSURE TEST.									
<b>Verbal Instructions Given to Contractor:</b>					Unresolved Issue: No		Shift: 2		
Kurt Mintell Silt fence on Maiden is leaning in some spots and need repair - notified CQC Jerry - he agreed to have the fence repaired- KEEP OPEN Since there is Thursday night free concerts at Pickett Lane to ensure the work area is left in a clean safe orderly fashion - ROB PEDDICORD									
<b>Miscellaneous Remarks and Visitors to Project:</b>					Unresolved Issue: No		Shift: 1		
Kurt Mintell Spoke with Armand LaPonte - 147 Main St about getting his water service done next week - Also spoke with Mike Pio. Both are in agreement - will attempt to schedule this for late next week to avoid interfering with scheduled roofer.									
Left VM for Steve Wright to meet and walk 17 to ID the sliver slabs for permanent pavement. KEEP OPEN									
<b>Miscellaneous Remarks and Visitors to Project:</b>					Unresolved Issue: No		Shift: 2		
Kurt Mintell Noted damaged curb on Pickett under guardrail from stream crossing - see photo									
QA REPRESENTATIVE'S SIGNATURE				DATE		RE/PROJECT ENGR'S INITIALS		DATE	