QUALITY ASSURANCE REPORT (QAR) DAILY LOG OF CONSTRUCTION									REPORT 631	REPORT NUMBER 631				Page 1 of 0		
DAILT LOG OF CONSTRUCTION											DATE 09 Sep 2020 - Wednesday					
PROJECT Durham Meadows Waterline Remedial Design								CONTRACT NUMBER W912WJ19C0002								
CONTRACTOR Ludlow Constr	ruction Co., Inc.									Temp	er Cause erature N	ed No Delay Min 82 °F M on No Wind		°F		
	PORTION OF	SCHEDL	JLED DAY	SUITABLE	FOR OP	ERATION	NS				TEMPER	RATURE			WIND	
STRUCTURAL EXCA- VATION BORROW EXCA- VATION 100 %		EMBANKMENT CONCRI		ETE 100		STRUCTURE 100 %		MINIMUM MAXIMUM 82 °F 68 °			0 MPH					
100 %			100 %			ı		100 %	 		24 HOUR PRECIP				IVIPH	
HAS ANYTHING DEVELOPED ON THE WORK WHICH MIGHT LEAD TO A CHANGE ORDER OR FINDING FO FACT? YES (Explain)								INCHES ENDING						М		
	NUI	MBER OF	GOVERNI	MENT EMP	ENT EMPLOYEES					RIVER STAGE				GE		
SUPERVISORY	OFFICE	LAYO	UT	INSPECT				LABOR					TIME			
0		0	0		2		2		0			0.0				М
	R OF CONTRAC	TOR'S EM	1PLOYEES	3		NUM	BER OF	SHIFTS		1	X] 2		3		
SUPERVISORY	SKILLED	LABO	RERS	TOTAL		FROM		TO	FF	ROM	ТО		FRON	Л	ТО	
0		0	0		0		0700	1530	М		М	М		М		М
Atta	ach a list of the for	ollowing. (a	a) Major ite	ems of equi	pment eith	ner idle or	working	g, and (b) Nu	mber a	nd classific	cation of	contractor p	ersonr	nel onsite.		
QA NARRAT		ctor's Quai	illy Control	Report (Q	JR) conta	ins the in	iormatio	n it need not	ре гер	ealed.						
	rmed Today:							Un	resolv	ed Issue:	No	Shif	t: 1			
ITEMS: 26: FIRE F 31: 4 1 IN AND #206 34: 73.5 FI MAPLE AV 62: 60 FE Billys Crev ITEMS: 0031: 1" C 11 Maiden 17 Maiden 18 Maiden 19 Maiden 24 Maiden 24 Maiden 25 Maiden 0034: 1" C 0065: Roc 0062: 262. DN Tank - DN Tanks Crane is se	Maple Ave - ins HYDRANT ASS CH CURB STO MAPLE AVE: EET OF 1 1NC VE: 17 FEET ET OF TOWN V installing curl Curb stops = 7 a Lane STA 400 Lane STA 400 Lane STA 400 Lane A05+70 Lane 405+70 Lane 407+03 Copper Pipe = 6 K and Boulder L23 LF = prepping the is not setting the is not steel of	SEMBLY: OPS: #18 STA 931 H COPP SAW CL b stops o at: 2+30 3+02 3+44 03+70 2 8 165 LF excavation ex	s STA 930 8 MAPLI +24 ER PIPE JT n Maider	E AVE: ST : #188 MA Lane: 1 CY crane. rigging is eights are	PLE: 16	.5 FEET	. They	MAPLE AV	E: 24	FEET, #2	200 MAF	PLE AVE: 1	16 FE			
	utting on 17 fo water main on			_							e Police	e & 1 Flagg	jer.			
CQC Inspec	tion Phases A	Attended	and Inst	tructions	Given:			Un		ed Issue:	No	Shif	t: 1			
Kurt Minte	II Noted con	npaction (on Maple	Ave. Pro	oer lifts a	ind com	pacted	layers.								
	uctions Giver	to Cont	ractor:					Un	resolv	ed Issue:	No	Shif	t: 1			
clarify whe	n with Jerry (Qere the deliverie	es go.	_		eliveries	being de	elivered	to J. Baror	es ho	use. Jerr	y will ins	stall additio	nal si	gns to		
Miscellaneo	ous Remarks a	and Visit	ors to Pr	oject:				Un	resolv	ed Issue:	No	Shif	t: 1			
	ll orrespondence nas an issue a			n Lane - bi	ought up	o at wee	kly mee	eting OPE	N ITE	ΞM						

				1					
A REPRESENTAT	IVE'S SIGNATURE	DATE	RE/PROJECT ENGR'S INITIALS	DATE					
no issues w	ith the crane at this time.								
Discussion	with Rob Peddicord to review the crar	e set up & placement The crane	is set up where it was drawn in t	he plan and there are					
Kurt Mintell									
Safety:			Unresolved Issue: No	Shift: 1					
Paul Paris	No safety issues noted today.								
Safety:			Unresolved Issue: No	Shift: 2					
open from 9	0/2/2020 - will follow up Closed toda	y - no further issues.							
Discussion with Jerry CQM & Jon Pio concerning storm drains on Maple Ave - need to be covered with silt socks while working. Left									

C