QUALITY ASSURANCE REPORT (QAR)								REPORT NUMBER 660 DATE				Page 1 of 0				
PROJECT										08 Oct		Thursday BER	,			
Durham Meadows Waterline Remedial Design									W912WJ19C0002							
CONTRACTOR Ludlow Construc	ction Co., Inc.									Temper	[.] Cause ature M	d No Delay in 45 °F M า No Wind		ŕF		
	PORTION OF	SCHEDU	JLED DAY	SUITABLE	FOR OPI	ERATION	S			TI	EMPER	ATURE			WIND	
STRUCTURAL EXC/ VATION 100	VATION	EXCA-	EMBANK	MENT 100 %	CONCRI	ETE 100 %		ICTURE	00 %	MINIMUM	45 °F	MAXIMUM	l 68 °F		0	MPH
100	70	100 /0		100 78					00 70			4 HOUR P			0	
					GHT	Х	NO			INCHES				ENDING		
LEAD TO A	CHANGE ORDE	RURFI	NDING FC	FACT			YES (E)	(plain)				0.00	М			
	NUM	BER OF	GOVERN	IENT EMP	LOYEES							RIVE	R STA	GE		
SUPERVISORY	OFFICE	LAYO	UT	INSPECT	ION	TOTAL		LABOR		FEET				TIME		
2	0		0		1		3		0			0.0				N
-	OF CONTRACT	-	-				ER OF			1	X	2		3		
SUPERVISORY	SKILLED	LABO	RERS	TOTAL		FROM	ר	0	FR	OM	то		FROM	1	то	
0	0		0		0		0700	1530	м	1	N	М		М		N
	h a list of the foll E: if the contract										tion of c	contractor p	ersonn	el onsite.		
			ity Control	Report (Q	Contai		Jination	It need not i	Je Tepe	ealeu.						
Work Perform	-							Unr	esolve	ed Issue: N	lo	Shif	t·1			
of the acces SEE SAFET Permanent ITEMS: 114: 650 FE 116: 223.45 117: 223.45 119: 154.42 JTC onsite f One Ludlow Sawcut on 1 Results of QA Kurt Mintell OPEN ITEM CTDOT has have voids i resolved.	A Inspections	E SAW (STA 157 TA 157 F SLIVI tests noving t and Te the tree pots an	CUT 7+25 TO +25 TO 1 ER SLAB the silt fer sts, Defic nch on th ad should re the cu	160+25 60+25 nce along ciencies (e south e be invest	the tank Dbserver nd of the gated wh rere place	access i d, Action water m hen the F	road. (T ns Take ain by (² erman	om) • n: Unr Did Cemete ent Paving	esolvo ery Rc	ed Issue: N pad. Steve n is done.	lo Wright This ite	Shif feels the em will rei	t: 1 trench main c	n may open unt		
Review the tank contract methods to a it did not nee lack of cyline requirement JTC was on Keep open - Miscellaneou Kurt Mintell Weekly Prog LB & CN on Safety: Kurt Mintell	prestressed wi ctor installed sh save time. The ed to be tested ders. I will clos	re on the notcrete ere was I due to e the de he sam ODAY, nd Visite	ne tank & on the to no cylind it being t eficiency ples per t will conti	the placed op section ers taken he same i once satis he spec - nue to tra	ment and of the ta from the nix that v fied the also tool	nk (over one con was used proper m k air & S	the pre crete tr the oth tix was	stressed w uck that sh ner day. I a placed and st Unr	ire ins owed m issu woul esolve	talled)- thi up. I discu uing a defi	s is the ssed th ciency concre	e contracto nis with Q for this pla	ors me CM - I aceme test t: 1	eans and ne told m	ne	

2. Noted wall brace being lifted by boom lift not in a choker sling. RESOLVED CLOSE3. Noted rebar on ground potential tripping hazard. RESOLVED CLOSE

- Non Permit Confined Space for work inside the Tank:1. Supervisor overseeing the workers inside the tank.2. Workers check box on clipboard hanging outside the entrance when in and out for accountability.3. Four monitors to verify safe breathing atmosphere inside the tank.

QA REPRESENTATIVE'S SIGNATURE	DATE	RE/PROJECT ENGR'S INITIALS	DATE