

Laurel, MD 20707 Phone: 301-361-0620 www.ERTCorp.com

LETTER REPORT

TO: Carol Charette, USACE-CENAE, Todd Beckwith, USACE-CENAB

FROM: Thomas Bachovchin, ERT

DATE: May 07, 2020

SUBJECT: Letter Report, Sign Inspection and UXO Awareness Training, Martha's Vineyard

MMRP Sites

ERT, under contract with the U.S. Army Corps of Engineers (USACE), New England District, is implementing land use controls (LUCs) at three Military Munitions Response Program (MMRP) sites on Martha's Vineyard:

- Cape Poge Bombing Target Site Munitions Response Site (MRS) FUDS Property No. D01MA0595
- Former South Beach Moving Target Machine Gun and Katama Rocket Range MRS FUDS Property No. D01MA0486
- Tisbury Great Pond MRS FUDS Property No. D01MA0453

This annual Long Term Monitoring report documents activities carried out on Martha's Vineyard in accordance with the LUC Implementation Plan (LUCIP) and Performance Work Statement for contract W912DR-15-D-0015-0003.

ERT staff arrived on Martha's Vineyard on June 25, 2019. The objectives of the visit were to:

- Conduct a public presentation to the Edgartown Life Guards for South Beach, the TTOR Rangers at Norton Point, Cape Poge and TGP, and first responders including local police and fire department personnel and other interested parties on Unexploded Ordnance (UXO) Awareness with regard to the three Martha's Vineyard MMRP sites.
- Perform evaluation of current site conditions and inspection and maintenance of signage associated with the MRSs.
- Review and document ordnance responses from the State Bomb Squad or Explosive Ordnance Detachment since the last inspection.

UXO Awareness Training

The presentation was conducted on June 26, 2019, at the Edgartown Library, Edgartown, Massachusetts, by Mr. Michael Watson, ERT MMRP Health and Safety Officer. The PowerPoint presentation, approved by USACE, was presented by Mr. Watson to 31 attendees. None of the interested parties requested a copy of the DVD of the presentation.



The sign-in sheet is included in Attachment A.

Sign Inspection and Maintenance

Mr. Watson and David Cote, ERT, inspected the signs associated with all three sites on June 26 and 27. The weather conditions were slightly overcast the first day, but were sunny on the second day with a temperature ranging from 70-80 degrees F. Each sign, its location and general vicinity were evaluated in terms of site conditions.

In summary, as shown in Attachment B, most of the signs were in very good to good condition with no need for repair, replacement, or relocation. Formal recommendations for each sign are included in Attachment B.

ERT confirmed that five signs were completely missing (four within the South Beach MRS and one within the Tisbury MRS). These five had been reported missing in the previous sign inspection reports. As discussed in Attachment C, one of the five is likely the result of vandalism while the remainder are likely due to erosion of the area.

Site Conditions

Current site conditions were evaluated as part of this report. As indicated in Attachment C, the locations of the four missing signs are in areas where erosion has affected the proper function of the LUCs in terms of the signs remaining in place. No other severe or notable erosion conditions associated with any of the MRSs were noted. These signs will be replaced if appropriate locations can be identified in the field.

Post Inspection Interviews

Part of the scope of the LUCIP is to conduct interviews with community members about the site conditions. ERT conducted interviews via phone which are presented in Attachment D.

EOD Activity

Local Police/Fire Departments as well as the MA State police Bomb Squad and Navy EOD, were contacted regarding incidents since the June 2018 inspection. Attachment E contains a State bomb squad report concerning an August 2018 munitions-related find. However, after several attempts, no additional reports were obtained; these will be included as received.



This letter report is organized as follows:

Attachment A – UXO Awareness Training Sign-in Sheet

Attachment B – Site Figures, Sign Inspection Forms, and Photo Documentation Log

Attachment C – Site Conditions Forms

Attachment D – Interview Forms

Attachment E – Explosive Ordnance Detail (EOD) or MA State Bomb Squad Activity Form



Attachment A

UXO Awareness Training Sign-in Sheet

Attachment A A-1





Unexploded Ordnance Awareness Training

Martha's Vineyard's Military Munitions Related Sites

Edgartown Library, Edgartown, Massachusetts June 26th, 2019, 10:00 AM



Contact information is requested so that USACE may provide notice of future presentations and to notify you of updates on the site.

	Name	Title/Organization	Phone	Email	Address
1	Bryce, Newson	Lifeguard	971-807-2010	Mbryaneison®	25 Village of Hower
2	Suzanne Moné-Stratan	lifeguard	774-563-9109	suzannevns Dymail.com	42 Circular Street, Saratega Springs NY
3	Flyn Loftey	Lifeguard	203-914-135	flynnm Lofter Osmal	52 Nursery Street
4	Flym Loftey Griffin Coffey	Lifeguard	203-919-13	griffncottey78763gm	Worwalk, ET
5	Bestrice Motor	Lifeguard	67-893-1531	bestrice Planegralla	14 Toring Pave One Buttoms 14 Cow Bay Road
	Carriag Cork	Lifeword	617-841-2351	coolsowesleson.edu	14 COW Bay Road
	Lizzie Williamon	Lifeguard	617-833-1371	littiem voidouton	10 Dark Hollow Lane
8	Chloe Blanc	Lifeguard		Chloeblane 12@aol.com	200
	Brais Joden	Lifeyuard		brooks jurden men generillen	7 Hidden Cove, OB,
	PAULO PEREIRA	Lifeguard	The Control of the Co	ppereinajr4@gmail.com	
	Alana Morris	Lifeguard	508-627-2262	alanamerris54@mail.	
12	Jack Holmes	Lifeguard	508-560-4580	Jackon 1213@good.	loo Highland Avenue
	BRIAN USHA	Lifeguard	860 208-5628	bjusreyaho.	the wast named a
14	CENE TOWNES	Sr. Lifeguard	508.621.	GENETOWNS 49 C GMAIL COM	12 CHAPMAN LAVE EAGLEDOW MY 0250
15	Den Townes 9	Sr. Lifeguard	508-221-	DLTownes Oconcest,	13 Chapman Lane Edgartown, mA
	Bund Joseph d		908-403 5057	briagiondanmile 8mail.com	30 HERCIER WAY

Attachment A A-2





Unexploded Ordnance Awareness Training

Martha's Vineyard's Military Munitions Related Sites

Edgartown Library, Edgartown, Massachusetts June 26th, 2019, 10:00 AM



Contact information is requested so that USACE may provide notice of future presentations and to notify you of updates on the site.

	Name	Title/Organization	Phone	Email	Address
17	Jessia Sonia	Sr. Lifequard	508-5100 355 Z	Jess.m.30nia@adicon	141 Great Plans 14 West Tiskury Ma
	Hamison Rodrigues	Sr. Lifeguard	808-727 0382	Harrison Kradrigues Ogmail.com	60 Gods Way Vineyard Hoven IMA
	Nevin Wallis	Lifeword	508-560- 4544	nwalls oreganican	5 Strawberry Un. Oak Bluffs. M.A.
	Maghan Sonia	Lifeguard	508.560. 4414	Meghan. Sonia 12@gmail Com	141 Glad Plains Rd West Tisbury MA
	John Hong O'Sharper	the state of the s	774-563- 9484	oshoughnessymu73@aul.	'S Muriorit Ave. OB,
		Lifeguard	114-663 -9717	24548 Cothaughnessygnal	- u u
23	Donald ashoressy 312 Note Noncore	Lifeguard	203-216-1212	nakawa 158gmail.com	28 Trinity Park, OB
M	John Knight	Lifeguard	617-921 - 5717	Jack 44 kmyhr@gmad.com	57 Eric Avanue, Newton A
	S. BLAKE ACTELL	Lifeguard	802-274-459	BLAKE. AFFELL &	35 CANTERLY LA VINEYARD HAVEN TOOK 58:
	CHRIS Kennedy	Island Superintendent Trustees of Escenation		1 1 4 4 4	23 Bara 100 8ch
27	Antum 4 Cimens	Lifeguard	508677 0559	Antrony Cimer.	13 Lori LN COIM blupps
28	Diller	Lifeguard	774-621-	di Hormcondrewsized Smil.	179 Skiff Ave Vineyard Huven
29	Mex Vasiliadis	Lifeguard	508-627	@ gmail.com	30 Slungh Con
10	Dunald	Lifeguard)	774-563	humanne	10 BUL 7442
31	Jespica Ay *	Edgartaun Vol Dept.	588-787 5864	Parks & net Edgarbun -MA.US	To Main 57, MAY Edgartun, MAY
2					



Attachment B

Tisbury Great Pond MRS:

Site Figure Sign Inspection Forms Photo Documentation Log

South Beach MRS:

Site Figure Sign Inspection Forms Photo Documentation Log

Cape Poge MRS:

Site Figure Sign Inspection Forms Photo Documentation Log





Document Path: N:\GIS\Northeast\Massachusetts\MarthasVineyard\MXD\Tisbury\SignInspection\2019\SignLocations.mxd



	I. Site Information					
Site Name: Martha's Vineyard MRSs		Date(s) of Inspection: June 26 and 27, 2019				
Location and Re	gion: Martha's V	Vineyard, MA				
		II.	Sign Inspectio	n		
Sign Location	Condition (poor, fair, good, excellent)	Maintenance Required (cleaning, repair, replacement)	Maintenance Performed (type and date)	Notes: (include photograph documentation before and after maintenance)		
Tisbury Great	Pond (photos 1	1-6)				
Beach Entrance at Summer Beach	Very Good	Cleaning, wiped down with Windex	Cleaning, June 26, 2019	Sign is located at south of parking area, south of wood chip trail, facing east. Overall very good condition. No erosion issues. RECOMMEND: no action		
Entrance to Winter beach	Very Good	Cleaning, wiped down with Windex	Cleaning, June 26, 2019	Sign is located at beach trail head and corner of roads, facing north. Overall very good condition. No erosion issues. RECOMMEND: no action		
Western Beach	N/A	N/A	N/A	Sign is missing (likely due to erosion). Confirmed situation from last inspection. RECOMMEND: replace sign if appropriate location identified (photo 5)		
Main Entrance from parking lot	N/A	N/A	N/A	Sign is located near parking lot. Overall very good condition. No erosion issues. RECOMMEND: no action		



Tisbury Great Pond

Inspection June 26, 2019





1. Summer Beach entrance.

2. Summer Beach, sign facing east.



3. Winter Beach entrance.



4. Winter Beach approach, sign facing north.



Tisbury Great Pond Inspection June 26, 2019





5. Western Beach sign missing.

6. Main Entrance from parking lot sign.



7. General area of Main Entrance sign.












Figure 2 Sign Locations

Sign Inspection Report Former South Beach Munitions Response Area Martha's Vineyard, Massachusetts

N:\GIS\Northeast\Massachusetts\MarthasVineyard\MXD\SouthBeach\SignInspection\SignLocations.mxd



II. Sign Inspection				
Sign Location	Condition (poor, fair, good, excellent)	Maintenance Required (cleaning, repair, replacement)	Maintenance Performed (type and date)	Notes: (include photograph documentation before and after maintenance)
South Beach (p	hotos 7-25)			
South Beach Entrance 1	Very Good	Cleaning, wiped down with Windex	Cleaning, June 26, 2019	Sign is located south of Atlantic drive and beach trail, at beach entrance #5, facing east. Overall very good condition. No erosion issues. RECOMMEND: no action
South Beach Entrance 2	N/A	N/A	N/A	Sign is missing (likely due to vandalism). Confirmed situation from last inspection. RECOMMEND: : replace if appropriate location identified (photo 9)
South Beach Entrance 3	Very Good	Cleaning, wiped down with Windex	Cleaning, June 26, 2019	Sign is located south of Atlantic drive and beach trail, at beach entrance #3, facing east. Overall very good condition. No erosion issues. RECOMMEND: no action
South Beach Left Fork	Very Good	Cleaning, wiped down with Windex	Cleaning, June 26, 2019	Sign is located south of Atlantic drive and beach trail, at beach entrance #4, facing north. Overall very good condition. No erosion issues. RECOMMEND: no action
South Beach Right Fork	Very Good	Cleaning, wiped down with Windex	Cleaning, June 26, 2019	Sign is located adjacent to road and beach trail, facing north. Overall very good condition. No erosion issues. RECOMMEND: no action
Left Fork Deflation	Very Good	Cleaning, wiped down with Windex	Cleaning, June 26, 2019	Sign is located west of Katama Rd, facing east, across from the tire pumping station. Overall very good condition. No erosion issues. RECOMMEND: no action
Norton Point Trail Entrance Sign 2	N/A	N/A	N/A	Sign is missing (likely due to erosion). Confirmed situation from last inspection. RECOMMEND: replace if appropriate location identified (photo 19)



Sign Location	Condition (poor, fair, good, excellent)	Maintenance Required (cleaning, repair, replacement)	Maintenance Performed (type and date)	Notes: (include photograph documentation before and after maintenance)
Chappaquiddick Wasque Tire Inflate Area	N/A	N/A	N/A	Sign is missing (likely due to erosion). Confirmed situation from last inspection. RECOMMEND: replace if appropriate location identified (photo 20)
Chappaquiddick Wasque Gate House	Very Good	Cleaning, wiped down with Windex	Cleaning, June 26, 2019	Sign is located just pass the gate house, facing south. Overall very good condition. No erosion issues. RECOMMEND: no action
Chappaquiddick Wasque Swimming Trail	N/A	N/A	N/A	Sign is missing (likely due to erosion). Confirmed situation from last inspection. RECOMMEND: replace if appropriate location identified (photo 23)
Chappaquiddick Wasque Fishing Trail	Very Good	Cleaning, wiped down with Windex	Cleaning, June 26, 2019	Sign is located south of parking area, facing north. Overall very good condition. No erosion issues. RECOMMEND: no action



South Beach

Inspection June 26, 2019



7. Entrance 1, Sign facing east.

8. Entrance 1, opposite view.



9. Entrance 2, sign missing.



10. Entrance 3, sign facing east.





11. Entrance 3, side view.



12. Left Fork, sign facing east.



13. Left Fork approach.



14. Right Fork, sign facing north.





15. Right Fork, showing underside.



16. Right Fork, approach view.



17. Left Fork Deflation, sign facing east.



18. Left Fork Deflation, looking south.





19. Norton Point Entrance 2, sign missing.



20. Wasque Tire Inflation Area, blocked off approach to missing sign.



21. Wasque Gate House, sign facing south.



22. Wasque Gate House, side view.








23. Wasque Swimming Trail, sign missing.

24. Wasque Fishing Trail, sign facing north.



25. Wasque Fishing Trail approach.







	II. Sign Inspection				
Sign Location	Condition (poor, fair, good, excellent)	Maintenance Required (cleaning, repair, replacement)	Maintenance Performed (type and date)	Notes: (include photograph documentation before and after maintenance)	
Cape Poge Sign	as (photos 26-28)				
Dyke Bridge	Very Good	Cleaning, wiped down with Windex	Cleaning, June 27, 2019	Sign location is east of Dyke Bridge (foot bridge and bicycle bridge), facing south. Overall very good condition. No erosion issues. RECOMMEND: no action	
Little Neck	Very Good	Cleaning, wiped down with Windex	Cleaning, June 27, 2019	Sign visible from Cape Poge Bay, about 10 feet from shoreline. Sign facing south. Overall very good condition. No erosion issues. RECOMMEND: no action Note, needed escort by Trustee personnel due to nesting piping plover.	



Cape Poge Inspection June 27, 2019



Cape Pope Little Neck
Robb Target Site

Francisco Copy

Franci

26. Dyke Bridge, sign facing south.

27. Little Neck, sign facing south.



28. Little Neck, sign approach.



Attachment C

Site Conditions Forms

Attachment C C-1



	I. Site Information						
Site Name: Martha's Vineyard MRSs	Date(s) of Inspection: June 26 and 27, 2019						
Location and Region: Ma	Location and Region: Martha's Vineyard, MA						
	II. Site Conditions						
Location (vicinity of sign)	Site Conditions of Note (e.g., significant erosion since last site inspection, observations of munitions, or other observations that impact LUC implementation) Notes: (include photograph documentation)						
Tisbury Great Pond							
Area of Western Beach Sign	Area of sign has undergone severe erosion (sign was washed away prior to April 2018).	See photos 5&6.					
Area of Entrance to Winter Beach Sign	Area showed no sign of erosion.	No findings that impact LUC implementation. See photos 3&4.					
Area of Summer Beach Entrance Sign	Area showed no sign of erosion.	No findings that impact LUC implementation. See photos 1&2.					
South Beach							
Area of Beach Entrance 1 & 2, and Right Fork Signs	Area showed no sign of erosion. Beach Entrance 2 sign missing but likely due to vandalism, not erosion.	No findings that impact LUC implementation. See photos 7-8, 9, 14-16.					
Area of Left Fork, Left Fork Deflation, and Beach Entrance 3 Signs	Area showed no sign of erosion.	No findings that impact LUC implementation. See photos 10-11, 12-13, 17-18.					
Area of Norton Point Trail Entrance Sign	Sign missing apparently due to erosion.	See photo 19.					
Area of Wasque Tire Inflate and Swimming Trail Signs	Area of signs has undergone severe erosion. Both signs had been washed away prior to 2018.	See photos 20&23.					
Area of Wasque Gate house and Fishing Trail Signs	Minimal to no signs of erosion.	No findings that impact LUC implementation. See photos 21, 22, 24, 25.					
Cape Poge							
Area of Dyke Bridge Sign	Minimal to no signs of erosion.	No findings that impact LUC implementation. See photo 26.					
Area of Little Neck Sign	Minimal to no signs of erosion.	No findings that impact LUC implementation. See photos 27&28.					

Attachment C C-2



Attachment D

Interview Forms

Attachment C C-3



I. Site Information			
Site Name:		Date(s) of Inspection:	
Martha's Vineyard MRSs			
Location and Region: Martha	's Vineyard, MA		
	II. Inte	rview Activity	
Individual Interviewed	Date of Interview	Brief Description of Discussion (include reports of onsite intrusive activities, EOD response action, etc.)	
Jennifer Rand	8/09/19	Phone interview, see questionnaire	



Community Interview Questionnaire Sheets (8-9-19 interview by ERT)

N:	ame: Jennifer Rand (West Tisbury Town Administrator)
Te	elephone (H): Work (W):508-696-0102
1.	A FUDS Long Term Management (LTM) is being conducted at the Former Nantucket Ordnance Site in Nantucket, MA. Have you heard about this project? If so, do you remember when and how you learned of it?
	Ms. Rand was aware of the project and in general the past military history of the area. She fel it was fairly common knowledge as a historical matter but also knew about it from her position as Town Administrator.
2.	Have you talked with any Army Corps of Engineers, state, or environmental officials about the ongoing FUDS LTM at the Nantucket Ordnance Site?
	Yes, through her role as Town Administrator, but Ms. Rand did not provide a specific name.
3.	If you have, were they responsive to your concerns or questions?
	Ms. Rand indicated that yes, they have always been responsive. She personally did not have specific questions for anyone in an official capacity, but felt the information was readily available to her if any issues should arise.
4.	Do you know how the community receives information about local events and news (i.e., radio, television, online news sources or newspapers)?
	Ms. Rand noted articles in local newspapers, but felt in general that the information is out there and people know about it.
5.	Is there anything else you would like to mention that we have not talked about? If in answering this question you provide "historical" information, please identify the source of this information.
	Ms. Rand had no further questions or issues.



Attachment E

Explosive Ordnance Detail (EOD) or MA State Bomb Squad Activity



NOTE:

Local Police/Fire Departments as well as the MA State police Bomb Squad and Navy EOD, were contacted regarding incidents in the past year. However, after several attempts, no additional reports in addition to the one described below were obtained; these will be included as received.

The photo below indicates an MK 23 practice bomb (shown with primer cap), one of three found August 15, 2018, at the Cape Poge Bombing Target Site MRS. The next picture is the investigation report from the Massachusetts State Police Bomb Squad.





