

**REPORT OF CHANNEL CONDITIONS
100 TO 400 FEET WIDE
(ER 1130-2-316)**

PAGE 1 OF 1 PAGE

DATE: **October 22, 2013**

TO:	FROM:
-----	-------

RIVER/HARBOR NAME AND STATE: Stony Creek, Branford, CT Dwg. No. SCB-19, Sheet 1 of 1, Dated 23 September 2013	MINIMUM DEPTHS IN CHANNEL ENTERING FROM SEAWARD
--	--

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH Nautical (miles)	MLLW DEPTH (feet)			
<u>CONDITION SURVEY</u>							
<u>6-Foot Channel</u>							
From about 60' upstream of Buoy GC-1 upstream 1,300' to about 260' upstream of Buoy GC-3	7/13	100	.21	6.0	5.8	5.1	4.8
Thence upstream about 1,063' to upstream end of Federal Navigation Project	7/13	100	.17	6.0	2.0	2.0	2.0
<u>6-Foot Maneuvering Basin</u>							
Area adjoining East Channel Limit between Town Wharf and upstream end of Federal Navigation Project	7/13		3.3 acres	6.0		1.8	

GENERAL NOTE: The information shown on this sheet(s) represents the results of surveys made on the dates indicated and can only be considered as indicating the general conditions existing at that time.

FOOT NOTES: