

**REPORT OF CHANNEL CONDITIONS
100 TO 400 FEET WIDE
(ER 1130-2-520)**

PAGE 1 OF 1 PAGES

DATE: **September 30, 2015**

TO: NAVIGATION INTEREST	FROM:
--------------------------------	-------

RIVER/HARBOR NAME AND STATE: Westcott Cove, Stamford, Connecticut
Dwg. No. WEC-727, Sheet(s) 1-2 of 2, Dated 30 September 2015

MINIMUM DEPTHS IN
CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (nautical miles)	MLLW DEPTH (feet)			
<u>CONDITION SURVEY</u> <u>8-Foot Channel</u> From about 305' seaward of Buoy FI R-4 upstream 2,500' to 70' seaward of Buoy GC-7 Thence upstream 2,070' to termination of Federal Channel	8/15	100	0.41	8.0	(1) 6.8	7.0	(2) 7.1
	8/15	300 to 200	0.34	8.0	(3) 4.2	4.7	0.6

GENERAL NOTE: The information shown on this sheet(s) represents the results of surveys made on the dates indicated and can only be considered as indicating the general conditions existing at that time.

FOOT NOTES:

- (1). Except for shoaling to 6.1' within 5' of west limit.
- (2). Except for shoaling to 6.3' within 5' of east limit.
- (3). Except for shoaling to +0.2' within 5' of west limit.