

**REPORT OF CHANNEL CONDITIONS
400 FEET WIDE OR GREATER
(ER 1130-2-520)**

DATE: **June 09, 2016**

TO: NAVIGATION INTEREST	FROM:
--------------------------------	-------

RIVER/HARBOR NAME AND STATE: Boston Harbor, South Boston, Massachusetts Dwg. No. BOS-1924, Sheets 1-2 of 2, Dated 09 June 2016	MINIMUM DEPTHS IN CHANNEL ENTERING FROM SEAWARD
---	--

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MID-CHANNEL		RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (nautical miles)	MLLW DEPTH (feet)		LEFT INSIDE QUARTER (feet)	RIGHT INSIDE QUARTER (feet)	
<u>CONDITION SURVEY</u> <u>40-Foot Reserved Turning Area</u> Maneuvering area located opposite former South Boston Army Base	8/15		5.17 acres	40.0	(1) 40.0 Available			
<u>40-Foot Reserved Channel</u> From about 1,840' seaward of former South Boston Army Base upstream 4,080' to upstream limit of 40-Foot Reserved Channel	8/15	Varies; 346 to 400	.67	40.0	38.7	38.7	39.9	40.0
<u>35-Foot Reserved Channel</u> From about 2,240' upstream of former South Boston Army Base upstream 1,340' to upstream limit of channel	8/15	430	.22	35.0	(2) 35.0	35.0	34.8	35.0

GENERAL NOTE: The information shown on this sheet(s) represents the results of surveys made on the dates indicated and can only be considered as indicating the general conditions existing at that time.

FOOT NOTES:

- (1). Except for shoaling to 39.8' within 5' of west limit.
- (2). Except for shoaling to 33.9' within 50' of upstream end of channel limit.