

**REPORT OF CHANNEL CONDITIONS
400 FEET WIDE OR GREATER
(ER 1130-2-520)**

DATE: **June 10, 2016**

TO: NAVIGATION INTEREST	FROM:
--------------------------------	-------

RIVER/HARBOR NAME AND STATE: Boston Harbor, Boston, MA Dwg. No. BOS-1925, Sheet 1 of 1, Dated 10 June 2016	MINIMUM DEPTHS IN CHANNEL ENTERING FROM SEAWARD
---	--

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MID-CHANNEL		RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (Nautical miles)	MLLW DEPTH (feet)		LEFT INSIDE QUARTER (feet)	RIGHT INSIDE QUARTER (feet)	
<p><u>CONDITION SURVEY</u></p> <p><u>40-Foot President Roads Anchorage</u></p> <p>Opposite Northern side of 40-Foot Main Ship Channel</p>	7/15	3110	437.83 acres	40.0		37.1'	Available	

GENERAL NOTE: The information shown on this sheet(s) represents the results of surveys made on the dates indicated and can only be considered as indicating the general conditions existing at that time.

FOOT NOTES:

NOAA Chart 13272