

**REPORT OF CHANNEL CONDITIONS
FOR CHANNELS LESS THAN 100 FEET WIDE
(ER 1130-2-520)**

PAGE 1 OF 1 PAGE

DATE: **June 28, 2016**

<p>T0: NAVIGATION INTEREST</p>	<p>FROM:</p>
---------------------------------------	--------------

<p>RIVER/HARBOR NAME AND STATE: Cohasset Harbor, Cohasset, Massachusetts Dwg. No. COH-130, Sheet 1 of 2, Dated 28 June 2016</p>	<p>MINIMUM DEPTHS IN CHANNEL ENTERING FROM SEAWARD</p>
---	--

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			DEPTH AVAILABLE
		WIDTH (feet)	LENGTH (Nautical miles)	MLLW DEPTH (feet)	
<p><u>GOVERNMENT AFTER DREDGE SURVEY</u></p> <p><u>8-Foot Entrance Channel</u></p> <p>From about 380' seaward of Sutton Hole Light upstream about 2,000' (250' seaward of Long Basin Light)</p> <p>Thence upstream 1,420' to 20' seaward of Buoy GC-13</p>	05/16	90	.33	8.0	<p>(1) 5.0</p>
	05/16	90	.23	8.0	6.0

GENERAL NOTE: The information shown on this sheet(s) represents the results of surveys made on the dates indicated and can only be considered as indicating the general conditions existing at that time.

FOOT NOTES:

(1). Except for shoaling to 3.0' within 10' of western limit.