

**REPORT OF CHANNEL CONDITIONS
100 TO 400 FEET WIDE
(ER 1130-2-520)**

DATE: **March 4, 2015**

TO: NAVIGATION INTEREST	FROM:
--	--------------

RIVER/HARBOR NAME AND STATE: Scarborough River, Scarborough, ME Dwg. No. 2761, Sheets 1-3 of 3, Dated 4 March 2015	MINIMUM DEPTHS IN CHANNEL ENTERING FROM SEAWARD
---	--

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (nautical miles)	MLLW DEPTH (feet)			
<u>AFTER DREDGE SURVEY</u>							
<u>8-Foot Entrance Channel</u>							
From about 460' seaward of Prouts Neck Yacht Club upstream 3,815' opposite Seaward end of West Jetty	12/14 - 1/15	200	.63	8.0	7.7	8.0	(1) 8.0
<u>6-Foot Channel</u>							
Thence upstream 2,817' to 6-Foot Anchorage (about 460' seaward of Pine Point Fisherman's Co-op)	12/14 - 1/15	200 to 100 to 200 to 275	.46	6.0	(2) 5.8	4.7	(3) 5.8
<u>6-Foot Anchorage</u>							
Thence upstream 1,495' to end of Federal Navigation Project	12/14 - 1/15	275 to 330	12.2 acres	6.0		(4) 6.0 available	

GENERAL NOTE: The information shown on this sheet(s) represents the results of surveys made on the dates indicated and can only be considered as indicating the general conditions existing at that time.

FOOT NOTES:

- (1). Except for shoaling to 6.6' within 20' of limit.
- (2). Except for shoaling to 5.4' within 5' of limit.
- (3). Except for shoaling to 4.4' within 5' of limit.
- (4). Except for shoaling to 4.8' within 20' of north limit; docks and floats encroaching on south limit in the vicinity of Pine Point Town Pier.