

**REPORT OF CHANNEL CONDITIONS
400 FEET WIDE OR GREATER
(ER 1130-2-316)**

DATE: **November 20, 2015**

TO: NAVIGATION INTEREST	FROM:
--	--------------

RIVER/HARBOR NAME AND STATE: Portsmouth Hbr. & Piscataqua River, ME & NH Dwg. No. PIS-2788, Sheet 1 of 1, Dated 20 November 2015	MINIMUM DEPTHS IN CHANNEL ENTERING FROM SEAWARD
---	--

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MID-CHANNEL		RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (Nautical miles)	MLLW DEPTH (feet)		LEFT INSIDE QUARTER (feet)	RIGHT INSIDE QUARTER (feet)	
<u>CONDITION SURVEY</u> <u>35-Foot Channel</u> From about 1,320' seaward of Buoy FI R-10 upstream 2,650' to the 35-Foot Turning Basin (about 150' upstream Buoy FI G-11)	10/15	400	.44	35.0	(1) 34.3	34.4	35.0	(2) 33.0
	10/15		23.5 acres	35.0	(3) 34.0			
<u>35-Foot Turning Basin</u>								

GENERAL NOTE: The information shown on this sheet(s) represents the results of surveys made on the dates indicated and can only be considered as indicating the general conditions existing at that time.

FOOT NOTES:

- (1). Except for shoaling to 30.3' within 20' of limit.
- (2). Except for shoaling to 32.2' within 25' of limit.
- (3). Except for shoaling to 33.3' within 20' of northeast limit.