

**REPORT OF CHANNEL CONDITIONS
100 TO 400 FEET WIDE
(ER 1130-2-520)**

DATE: **July 28, 2016**

TO: **NAVIGATION INTEREST**

FROM:

RIVER/HARBOR NAME AND STATE: Great Salt Pond, Block Island, Rhode Island
Dwg. No. GSP-181, Sheet 1 of 1, Dated 28 July 2016

MINIMUM DEPTHS IN
CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (nautical miles)	MLLW DEPTH (feet)			
<p align="center"><u>GOVERNMENT AFTER DREDGE SURVEY</u></p> <p align="center"><u>18-Foot Channel</u></p> <p>From about 10' upstream of Buoy RN-2 Bell upstream about 1,790' to Buoy FL G-7</p> <p>Thence upstream about 1,190' to upstream end of Federal Navigation Project</p>	6/16	150	.29	18.0	14.8	14.6	15.2 ⁽¹⁾
	6/16	150	.20	18.0	15.6	14.0	6.5 ⁽²⁾

GENERAL NOTE: The information shown on this sheet(s) represents the results of surveys made on the dates indicated and can only be considered as indicating the general conditions existing at that time.

FOOT NOTES:

- (1). Except for shoaling to 7.7' within 10' of limit.
- (2). Except for shoaling to +0.1' within 10' of limit.

