

**REPORT OF CHANNEL CONDITIONS
100 TO 400 FEET WIDE
(ER 1130-2-520)**

PAGE 1 OF 1 PAGES

DATE: **June 10, 2016**

T0: **NAVIGATION INTEREST**

FROM:

RIVER/HARBOR NAME AND STATE: Boston Harbor, Nubble Channel, Boston, MA
Dwg. No. BOS-1919, Sheet 1 of 1, Dated 10 June 2016

MINIMUM DEPTHS IN
CHANNEL ENTERING FROM SEAWARD

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (nautical miles)	MLLW DEPTH (feet)			
<p><u>CONDITION SURVEY</u></p> <p><u>15-Foot Channel</u></p> <p>From about 200' seaward of Buoy GC-3 upstream 588' to upstream end of channel</p>	12/14	300	.10	15.0	(1) 14.3	14.9	(2) 13.9

GENERAL NOTE: The information shown on this sheet(s) represents the results of surveys made on the dates indicated and can only be considered as indicating the general conditions existing at that time.

FOOT NOTES:

- (1). Except for shoaling to 13.4' within 10' of limit.
- (2). Except for shoaling to 11.2' within 20' of limit.