

**REPORT OF CHANNEL CONDITIONS
100 TO 400 FEET WIDE
(ER 1130-2-316)**

DATE: **December 7, 2015**

TO: <p align="center">NAVIGATION INTEREST</p>	FROM:
---	-------

RIVER/HARBOR NAME AND STATE: Searsport Harbor, Searsport, Maine Dwg. No. SEA-2716, Sheets 1-2 of 2, Dated 7 December 2015	MINIMUM DEPTHS IN CHANNEL ENTERING FROM SEAWARD
--	--

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (Nautical miles)	MLLW DEPTH (feet)			
<p><u>CONDITION SURVEY</u></p> <p><u>35-Foot Access Channel and Turning Basin</u></p> <p>From about 1,100' upstream of Buoy RN-4 upstream 3,660' (about 200' seaward of Maine Port Authority Pier)</p>	10/15	Varies	78 acres	35.0	.	(1) 32.0 available	

GENERAL NOTE: The information shown on this sheet(s) represents the results of surveys made on the dates indicated and can only be considered as indicating the general conditions existing at that time.

FOOT NOTES:

(1). Except for shoaling to 30.8' within a 300' radius of the northwest corner of Federal Navigation Project.