

**REPORT OF CHANNEL CONDITIONS
100 TO 400 FEET WIDE
(ER 1130-2-520)**

PAGE 1 OF 1 PAGE

DATE: **October 21, 2014**

TO: NAVIGATION INTEREST	FROM:
--------------------------------	-------

RIVER/HARBOR NAME AND STATE: Stonington Harbor, Stonington, Maine Dwg. No. SHM-2751, Sheet 1 of 1, Dated 21 October 2014	MINIMUM DEPTHS IN CHANNEL ENTERING FROM SEAWARD
---	--

NAME OF CHANNEL	DATE OF SURVEY	AUTHORIZED PROJECT			LEFT OUTSIDE QUARTER (feet)	MIDDLE HALF (feet)	RIGHT OUTSIDE QUARTER (feet)
		WIDTH (feet)	LENGTH (nautical miles)	MLLW DEPTH (feet)			
<u>CONDITION SURVEY</u>							
<u>10-Foot Channel</u>							
From about 110' seaward of adjacent prominent southern point upstream 630'	9/14	100 to 110	0.10	10.0	(1) 8.7	9.2	9.3
Thence upstream 285' to upstream limit of Federal Navigation Project	9/14	60	0.05	10.0	(2) 8.1		
<u>8-Foot Anchorage</u>	9/14		3.6 acres	8.0		8.0	
<u>6-Foot Anchorage</u>	9/14		5.8 acres	6.0		5.7	

GENERAL NOTE: The information shown on this sheet(s) represents the results of surveys made on the dates indicated and can only be considered as indicating the general conditions existing at that time.

FOOT NOTES:

- (1). Except for shoaling to 7.9' within 5' of limit. Encroachment by float along limit.
- (2). Except for shoaling to 7.0' within 5' of north channel limit. Encroachment by a float in the vicinity of Stonington Town Dock.