		REPORT NUMBER	0			
CONTRACTORS QUALITY CONTROL REPORT	(QCR)	587 Page 1 of 3	5			
DAILY LOG OF CONSTRUCTION	(401)	DATE				
		27 Jul 2020 - Monday				
PROJECT		CONTRACT NUMBER				
Durham Meadows Waterline Remedial Design		W912WJ19C0002				
CONTRACTOR	WEATHER					
Ludlow Construction Co., Inc.		sed No Delay 9 Min 73 °F Max 97 °F				
		ion 8 MPH Wind				
QC NARRATIVES						
JOB SAFETY						
SAFETY: Crews arrived at 7:00am, Departed at 3:00-3:30pm						
*SSHO Rob Peddicord:						
*Monitored 2 main crews production activities; Foremen Jonathon *Monitored DN Tanks activities at the Water Tank; Foreman AI Ke		Ruz,				
*Jonathon Pio's crew: Began Streamcrossing #3 at Maple Ave *Work off the road, no traffic control needed						
*Billy DaCruz crew at Rt 17, Installing Water Services *1 CTC flagger, 1 Labor flagger for traffic control (Certs on record)					
*Borrow/Dump Yard: 1 Operator loading dumps with trench backfi	ill material; mainta	ining waste piles				
*DN Tanks poured 4 cy concrete for Pipe Pit; all safety precaution	ns followed.					
*Performed daily checklist inspections on Daily Report; Crews surroundings. Safety in compliance with EM 385-1-1. COVID- PDF						
Report, with attached pic)						
*Checked dumptruck haul roads for debris. *Checked silt fencing for SWPP; no ruptures.						
*Weekly Toolbox Meeting: Hot Works Procedures						
*Office work: The SSHO continued collecting and filing crew pa Lift Plan PDFs attached to RMS).	aperwork for Lift F	Plans, AHAs, and Daily Equipment Inspection	s (See			
*Received daily reports from DN Tanks; COVID self cert, SSHO I	Daily Report.					
TESTS REQUIRED BY SPECIFICATIONS, PERFORMED, AND T	HE RESULTS					
Concrete Pour Testing: Slump, = 8.5 , Air = 1.5 , Temp = 86						
WORK PERFORMED TODAY						
WORK PERFORMED TODAY Onsite 7:00 AM ; Offsite 3:00 PM						
PERSONAL;						
Project Manager 1 Superintendent 5						
Operators 5						
Labors 8						
Truck Drivers 3						
VISITERS:						
SUBCONTRACTORS ON SITE: Turner = 1						
Cert Flaggers = 3						
WORK COMPLETED:						
JON'S Crew:	<i>(</i> –					
46: BEGAN WORKING ON STREAM CROSSING ON MAPLE AV 75: 280 FEET OF SILT FENCE INSTALLED ON MAPLE AVE Placed Stream Diversion Pipe	/E					

		REPORT NUMBER		
		587	Page 2 of 3	
CONTRACTORS QUALITY CONTROL REPORT (QCF DAILY LOG OF CONSTRUCTION		DATE		
			ndav	
PROJECT		27 Jul 2020 - Mo CONTRACT NUMBER	nuay	
Durham Meadows Waterlin	e Remedial Design	W912WJ19C000	12	
	eet of Piercing Under Sidewalk and Bushes.		2	
Water Tank Installation: Forms were set up to cover the Concrete pour began at 9:30 AM 8 6x12 cylinders were taken and Concrete was vibrated and rece Pour Concrete. Slump, = 8.5, A	t stored in Cylinder box. ived a Rake finish.	and capped.		
QA/QC: QA Kurt Mintell and QA Joe Cur	rier discussed the concrete pour with QC Jerry I	Brandon before the Pour.		
PROJECT LAISON COORDINA	NTOR:			
PREP/INITIAL DATES	(Preparatory and initial dates held and ad	vance notice)		
Preparatory Inspections held toda	-			
No preparatory inspections	held today			
Initial Inspections held today				
No initial inspections held to	oday			
ACTIVITY START/FINISH				
Activity No Description				
No activities were started or	finished today			
QC REQUIREMENTS				
Requirement No Type	Description		Results	Destille
Requirement No Type CT-00188 QC Test	Concrete was tested for Slump, Air and		Results Awaiting	Results
Requirement No Type CT-00188 QC Test	•			Results
Requirement No Type CT-00188 QC Test	Concrete was tested for Slump, Air and			Results
Requirement No Type CT-00188 QC Test ISSUED QA/QC DEFICIENCY Item No Location	Concrete was tested for Slump, Air and (Describe QA and QC Deficiency item Description			Results
Requirement No Type CT-00188 QC Test ISSUED QA/QC DEFICIENCY Item No Location No QC Deficiency items were	Concrete was tested for Slump, Air and (Describe QA and QC Deficiency item Description e issued today	is issued)		Results
Requirement No Type CT-00188 QC Test ISSUED QA/QC DEFICIENCY Item No Location No QC Deficiency items were	Concrete was tested for Slump, Air and (Describe QA and QC Deficiency item Description e issued today	is issued)		Results
Requirement No Type CT-00188 QC Test ISSUED QA/QC DEFICIENCY Item No Location	Concrete was tested for Slump, Air and (Describe QA and QC Deficiency item Description e issued today	is issued)		Results
Requirement No Type CT-00188 QC Test ISSUED QA/QC DEFICIENCY Item No Location No QC Deficiency items wer CORRECTED QA/QC DEFICIE	Concrete was tested for Slump, Air and (Describe QA and QC Deficiency item Description e issued today NCY (Report QC and QA Deficiency items	is issued)		Results
Requirement No Type CT-00188 QC Test ISSUED QA/QC DEFICIENCY Item No Location No QC Deficiency items wer CORRECTED QA/QC DEFICIE Item No Location	Concrete was tested for Slump, Air and (Describe QA and QC Deficiency item Description e issued today NCY (Report QC and QA Deficiency items Description	is issued)		Results
Requirement No Type CT-00188 QC Test ISSUED QA/QC DEFICIENCY Item No Location No QC Deficiency items were CORRECTED QA/QC DEFICIE Item No Location No QC Deficiency items were ORRECTED QA/QC DEFICIE Item No Location	Concrete was tested for Slump, Air and (Describe QA and QC Deficiency item Description e issued today NCY (Report QC and QA Deficiency items Description	corrected)		Results
Requirement No Type CT-00188 QC Test ISSUED QA/QC DEFICIENCY Item No Location No QC Deficiency items were CORRECTED QA/QC DEFICIE Item No Location No QC Deficiency items were CORRECTED QA/QC DEFICIE Item No Location No QC Deficiency items were CONTRACTORS ON SITE	Concrete was tested for Slump, Air and (Describe QA and QC Deficiency item Description e issued today NCY (Report QC and QA Deficiency items Description e corrected today	corrected)	Awaiting	Results
Requirement No Type CT-00188 QC Test ISSUED QA/QC DEFICIENCY Item No Location No QC Deficiency items wer CORRECTED QA/QC DEFICIE Item No Location	Concrete was tested for Slump, Air and (Describe QA and QC Deficiency item Description e issued today NCY (Report QC and QA Deficiency items Description e corrected today	corrected)		Results
Requirement No Type CT-00188 QC Test ISSUED QA/QC DEFICIENCY Item No Location No QC Deficiency items were CORRECTED QA/QC DEFICIE Item No Location No QC Deficiency items were CORRECTED QA/QC DEFICIE Item No Location No QC Deficiency items were CONTRACTORS ON SITE	Concrete was tested for Slump, Air and (Describe QA and QC Deficiency item Description e issued today NCY (Report QC and QA Deficiency items Description e corrected today (Report first and/or last day contractors we	corrected)	Awaiting	Results
Requirement No Type CT-00188 QC Test ISSUED QA/QC DEFICIENCY Item No Location No QC Deficiency items were CORRECTED QA/QC DEFICIE Item No Location No QC Deficiency items were CORRECTED QA/QC DEFICIE Item No Location No QC Deficiency items were CONTRACTORS ON SITE Name	Concrete was tested for Slump, Air and (Describe QA and QC Deficiency item Description e issued today NCY (Report QC and QA Deficiency items Description e corrected today (Report first and/or last day contractors we	corrected)	Awaiting Last Day	
Requirement No Type CT-00188 QC Test SSUED QA/QC DEFICIENCY Item No Location No QC Deficiency items wer CORRECTED QA/QC DEFICIE Item No Location No QC Deficiency items wer CORRECTED QA/QC DEFICIE Item No Location No QC Deficiency items wer CONTRACTORS ON SITE Name No Contractors had their first	Concrete was tested for Slump, Air and (Describe QA and QC Deficiency item Description e issued today NCY (Report QC and QA Deficiency items Description e corrected today (Report first and/or last day contractors we	corrected)	Awaiting	Results
Requirement No Type CT-00188 QC Test ISSUED QA/QC DEFICIENCY Item No Location No QC Deficiency items were CORRECTED QA/QC DEFICIE Item No Location No QC Deficiency items were CORRECTED QA/QC DEFICIE Item No Location No QC Deficiency items were CONTRACTORS ON SITE Name No Contractors had their first LABOR HOURS	Concrete was tested for Slump, Air and (Describe QA and QC Deficiency item Description e issued today NCY (Report QC and QA Deficiency items Description e corrected today (Report first and/or last day contractors we st or last day on the site	corrected)	Awaiting Last Day Number of	Hours
Requirement No Type CT-00188 QC Test SSUED QA/QC DEFICIENCY Item No Location No QC Deficiency items wer CORRECTED QA/QC DEFICIE Item No Location No QC Deficiency items wer CORRECTED QA/QC DEFICIE Item No Location No QC Deficiency items wer CONTRACTORS ON SITE Name No Contractors had their first ABOR HOURS Employer	Concrete was tested for Slump, Air and (Describe QA and QC Deficiency item Description e issued today NCY (Report QC and QA Deficiency items Description e corrected today (Report first and/or last day contractors we st or last day on the site Labor Classification	corrected)	Awaiting Last Day Number of Employees	Hours
Requirement No Type CT-00188 QC Test SSUED QA/QC DEFICIENCY Item No Location No QC Deficiency items were CORRECTED QA/QC DEFICIE Item No Location No QC Deficiency items were CORRECTED QA/QC DEFICIE Item No Location No QC Deficiency items were CONTRACTORS ON SITE Name No Contractors had their first LABOR HOURS Employer Ludlow Construction Co., Inc.	Concrete was tested for Slump, Air and (Describe QA and QC Deficiency item Description e issued today NCY (Report QC and QA Deficiency items Description e corrected today (Report first and/or last day contractors works) st or last day on the site Labor Classification TRUCK DRIVER, GROUP 1	corrected)	Awaiting Last Day Number of Employees 3.0	Hours Worked 24.0
Requirement No Type CT-00188 QC Test ISSUED QA/QC DEFICIENCY Item No Location No QC Deficiency items wer CORRECTED QA/QC DEFICIE Item No Location No QC Deficiency items wer CORRECTED QA/QC DEFICIE Item No Location No QC Deficiency items wer CONTRACTORS ON SITE Name No Contractors had their first LABOR HOURS Employer Ludlow Construction Co., Inc. Ludlow Construction Co., Inc.	Concrete was tested for Slump, Air and (Describe QA and QC Deficiency item Description e issued today NCY (Report QC and QA Deficiency items Description e corrected today (Report first and/or last day contractors we st or last day on the site Labor Classification TRUCK DRIVER, GROUP 1 LABORER, GROUP 1	corrected)	Awaiting Last Day Number of Employees 3.0 8.0	Hours Worked 24.0 56.0
Requirement No Type CT-00188 QC Test ISSUED QA/QC DEFICIENCY Item No Location No QC Deficiency items wer CORRECTED QA/QC DEFICIE Item No Location No QC Deficiency items wer CORRECTED QA/QC DEFICIE Item No Location No QC Deficiency items wer CONTRACTORS ON SITE Name No Contractors had their first LABOR HOURS Employer Ludlow Construction Co., Inc. Ludlow Construction Co., Inc. Ludlow Construction Co., Inc.	Concrete was tested for Slump, Air and (Describe QA and QC Deficiency item Description e issued today NCY (Report QC and QA Deficiency items Description e corrected today (Report first and/or last day contractors wo st or last day on the site Labor Classification TRUCK DRIVER, GROUP 1 LABORER, GROUP 1 CIRCULAR SAW OPERATOR	corrected)	Awaiting Last Day Number of Employees 3.0 8.0 0.0	Hours Worked 24.0 56.0 0.0
Requirement No Type CT-00188 QC Test ISSUED QA/QC DEFICIENCY Item No Location No QC Deficiency items were CORRECTED QA/QC DEFICIE Item No Location No QC Deficiency items were CORRECTED QA/QC DEFICIE Item No Location No QC Deficiency items were CONTRACTORS ON SITE Name No Contractors had their first LABOR HOURS Employer Ludlow Construction Co., Inc.	Concrete was tested for Slump, Air and (Describe QA and QC Deficiency item Description e issued today NCY (Report QC and QA Deficiency items Description e corrected today (Report first and/or last day contractors we st or last day on the site Labor Classification TRUCK DRIVER, GROUP 1 LABORER, GROUP 1 CIRCULAR SAW OPERATOR PROJECT MANAGER	corrected)	Awaiting Last Day Number of Employees 3.0 8.0 0.0 0.0	Hours Worked 24.0 56.0 0.0 0.0
Requirement No Type CT-00188 QC Test ISSUED QA/QC DEFICIENCY Item No Location No QC Deficiency items wer CORRECTED QA/QC DEFICIE Item No Location No QC Deficiency items wer CORRECTED QA/QC DEFICIE Item No Location No QC Deficiency items wer CONTRACTORS ON SITE Name No Contractors had their first LABOR HOURS Employer Ludlow Construction Co., Inc. Ludlow Construction Co., Inc.	Concrete was tested for Slump, Air and (Describe QA and QC Deficiency item Description e issued today NCY (Report QC and QA Deficiency items Description e corrected today (Report first and/or last day contractors we st or last day on the site Labor Classification TRUCK DRIVER, GROUP 1 LABORER, GROUP 1 CIRCULAR SAW OPERATOR PROJECT MANAGER OPERATOR HEAVY EQUIPMENT 1	corrected)	Awaiting Last Day Number of Employees 3.0 8.0 0.0 0.0 5.0	Hours Worked 24.0 56.0 0.0 0.0 40.0

CONTRACTORS QUALITY CONTROL REPORT (QCR)			REPOR	T NUMBER	Page 3 of 3	
DAILY LOG OF CONSTRUCTION						
			DATE 27 Jul 2020 - Monday			
ROJECT				ACT NUMBER	aay	
Durham Meadows Wate	erline Remedial D	esian		12WJ19C0002		
Total hrs worked to date:	23,136.5	Hrs worked MTD:	2,720.0	Total	: 18.0	136.0
QUIPMENT HOURS Serial Number	Description				Idle Hours	Operating Hours
L-20	L-20 Kumatsu Fr	ont End Loader Billy	,		4.0	4.0
TE-6 Ex	TE-6 Volvo	Jon			6.0	2.0
E-4 0336FCRAB	E-4 Cat 336 Tra	ck Hoe Jon			0.0	8.0
T-36	Dump Truck T-36				8.0	0.0
B-5	Sweeper B-5	Billy			6.0	2.0
E-20 ECR145DL,	E-20 Volvo Excav	-			0.0	8.0
T-41	Ludlow Pressure				8.0	0.0
T-50	T-50 PU	Jon			4.0	4.0
T-77 PU	T-77 PU	Billy			4.0	4.0
E-9 Track Hoe	E-9 336 Track H	2			8.0	4.0 0.0
T-64	Dump Truck T-64	,			8.0	0.0
B-5 Sweeper	B-5 Sweeper	Jon			4.0	4.0
R-4 Roller Billy	Roller Compacter				4.0	4.0
TE 15 Excavator	TE-15 Track Hoe	-			6.0	4.0 2.0
T-84 PU	T-84 PU	Billy			0.0	8.0
T-78 PU	T-78 PU	Jon			6.0	2.0
L-18 950	L-18 Loader	Jon			4.0	4.0
R-18 Roller	R-18 Compactor				4.0	4.0
D1 Cat	D-1 Cat D-5 Doz				8.0	4.0 0.0
T-86	T-86 Dump Truc	,			0.0	8.0
T-21 Dump	T-21 Dump	Jon			8.0	0.0
R-17 Roller	R-17 Roller	Billy			8.0	0.0
T-59 Dump	T-59 Dump	Billy			8.0	0.0
TE-13 Excavator	TE-13 EX	Billy			8.0	0.0
Total operating hrs to date:			Opr hrs MTD:	1,396.0		68.0
				1,550.0	10tal. 124.0	00.0
IISHAP REPORTING	(Describe r	nishaps)				