REPORT NUMBER Page 1 of 3 596 CONTRACTORS QUALITY CONTROL REPORT (QCR) DAILY LOG OF CONSTRUCTION DATE 05 Aug 2020 - Wednesday PROJECT CONTRACT NUMBER W912WJ19C0002 Durham Meadows Waterline Remedial Design CONTRACTOR WEATHER Ludlow Construction Co., Inc. Weather Caused Non-Critical Delay Temperature Min 66 °F Max 89 °F 0.15 IN Precipitation 18 MPH Wind **QC NARRATIVES** JOB SAFETY SAFETY: Crews arrived at 7:00am, Departed at 3:00-3:30pm \*SSHO Rob Peddicord: \*Monitored 2 main crews production activities; Foremen Jonathon Pio and Billy DaCRuz, \*Monitored DN Tanks activities at the Water Tank; Foreman Al Kendall. \*Jonathon Pio's crew: No Production work. Site shut down do to power outages from storm damage \*Billy DaCruz crew: No Production. Site shut down due to power outages from storm damage. Partial crew assisted DN Tanks with prepping for and performing pressure test on inlet pipe. \*Also some equipment removed from site \*DN Tanks performed site maintenance while Ludlow did pressure test on tank inlet pipes \*Performed daily checklist inspections on Daily Report; DN Tanks Crew wearing all required PPE, Crew alert of surroundings. Safety in compliance with EM 385-1-1. COVID-19 precautions being followed. (SEE Attached Ludlow SSHO Daily PDF Report.) \*Checked silt fencing for SWPP: no ruptures. \*Office work: The SSHO continued collecting and filing crew paperwork for Lift Plans, AHAs, and Daily Equipment Inspections (See Lift Plan PDFs attached to RMS). \*Received daily reports from DN Tanks; COVID self cert, SSHO Daily Report, TESTS REQUIRED BY SPECIFICATIONS, PERFORMED, AND THE RESULTS Pressure Tests of the Pipes encased in the concrete: Tests were good. Test at 100 PSI for 1 hour. SWPP was Performed Today: Results Good. WORK PERFORMED TODAY WORK PERFORMED TODAY Onsite 7:00 AM ; Offsite 3:00 PM PERSONAL; **Project Manager** Superintendent 3 **Operators 1** Labors 3 Truck Drivers 1 0 VISITERS: SUBCONTRACTORS ON SITE: Tropical Storm Isaias hit the area Tuesday around 3:00 PM in the afternoon with 60 MPH winds and Heavy rainfall resulting in minor flooding and heavy storm damage with leaving wires down and trees across many roads throughout the State of Connecticut Due to damage, Concrete Plants have been shut down due to downed trees and Power issues. Durham shut down working today because of the power being off and trees across the power lines. This shutdown affects critical path activity, A7250 Form, Reinforce & Place Floor Slab - Storage Tank. SWPP was performed today because of Storm;

WORK COMPLETED; JON'S Crew: Shutdown> No work today. Crew,s were sent back home due to Storm Damage in Durham.

BILLY's Crew: Shut down. Billy's Crew's were sent back home due to Storm Damage in Durham. Billy and Helper went to AI's Crew at the water tank to set up the pipe pits for pressure test.

			REPORT NUMBER				
CONTRACTORS QUALITY CONTROL REPORT (QCR DAILY LOG OF CONSTRUCTION			596	Page 2 of 3			
			DATE				
				ednesdav			
PROJECT			05 Aug 2020 - Wednesday CONTRACT NUMBER				
	dows Waterline	e Remedial Design	W912WJ19C0002				
		ed the pipes at 100 PSI for 1 hour. Tests Passe					
Water Tank Ins	tallation						
DN Tanks;							
AL's Crew:	n placing sand be	ds in the forms for preparation of pouring concr	ete				
QA/QC: QA Kurt Mintel QA Curt was p	I Discussed with ( resent during the t	QC Jerry Brandon and HSSO Rob Peddicord, esting of the pipes.	the storm damage and the P	Pressure Test of the F	Pipe's.		
PROJECT LAI	SON COORDINAT	TOR:					
PREP/INITIAL D		(Preparatory and initial dates held and ad	vance notice)				
	ections held today						
No preparator	y inspections h	eld today					
Initial Inspections							
-	ections held to	day					
ACTIVITY STAR	T/FINISH						
Activity No	Description						
	vere started or	finished today					
QC REQUIREM	ENTS						
Requirement No	Type	Description					
·		Description	tested as required in the Original	Results	Populto		
CT-00192	QC Test	The Pipes in the concrete were pressure and Drawings. Tests were Good.	e tested as required in the Spe		Results		
·		The Pipes in the concrete were pressure					
CT-00192	QC Test QC Test	The Pipes in the concrete were pressure and Drawings. Tests were Good.	f Storm;	ecs Awaiting			
CT-00192 CT-00193	QC Test QC Test	The Pipes in the concrete were pressure and Drawings. Tests were Good. SWPP was Performed today Because c	f Storm;	ecs Awaiting			
CT-00192 CT-00193 SSUED QA/QC	QC Test QC Test DEFICIENCY	The Pipes in the concrete were pressure and Drawings. Tests were Good. SWPP was Performed today Because of (Describe QA and QC Deficiency item)	f Storm;	ecs Awaiting			
CT-00192 CT-00193 SSUED QA/QC Item No	QC Test QC Test DEFICIENCY	The Pipes in the concrete were pressur and Drawings. Tests were Good. SWPP was Performed today Because of (Describe QA and QC Deficiency item Description	f Storm;	ecs Awaiting			
CT-00192 CT-00193 SSUED QA/QC Item No No QC Deficie	QC Test QC Test DEFICIENCY Location	The Pipes in the concrete were pressur and Drawings. Tests were Good. SWPP was Performed today Because of (Describe QA and QC Deficiency item Description	f Storm; s issued)	ecs Awaiting			
CT-00192 CT-00193 SSUED QA/QC Item No No QC Deficie	QC Test QC Test DEFICIENCY Location ncy items were	The Pipes in the concrete were pressur and Drawings. Tests were Good. SWPP was Performed today Because of (Describe QA and QC Deficiency item Description	f Storm; s issued)	ecs Awaiting			
CT-00192 CT-00193 SSUED QA/QC Item No No QC Deficie CORRECTED Q	QC Test QC Test DEFICIENCY Location ncy items were A/QC DEFICIEN	The Pipes in the concrete were pressur and Drawings. Tests were Good. SWPP was Performed today Because of (Describe QA and QC Deficiency item Description issued today ICY (Report QC and QA Deficiency items	f Storm; s issued)	ecs Awaiting			
CT-00192 CT-00193 SSUED QA/QC Item No No QC Deficie CORRECTED Q Item No	QC Test QC Test DEFICIENCY Location ncy items were A/QC DEFICIEN Location	The Pipes in the concrete were pressure and Drawings. Tests were Good. SWPP was Performed today Because of (Describe QA and QC Deficiency item Description <b>issued today</b> ICY (Report QC and QA Deficiency items Description	f Storm; s issued)	ecs Awaiting			
CT-00192 CT-00193 SSUED QA/QC Item No No QC Deficie CORRECTED Q Item No No QC Deficie	QC Test QC Test DEFICIENCY Location ncy items were A/QC DEFICIEN Location	The Pipes in the concrete were pressur and Drawings. Tests were Good. SWPP was Performed today Because of (Describe QA and QC Deficiency item Description issued today ICY (Report QC and QA Deficiency items Description	f Storm; s issued) corrected)	ecs Awaiting			
CT-00192 CT-00193 SSUED QA/QC Item No No QC Deficie CORRECTED Q Item No No QC Deficie CONTRACTORS	QC Test QC Test DEFICIENCY Location ncy items were A/QC DEFICIEN Location	The Pipes in the concrete were pressure and Drawings. Tests were Good. SWPP was Performed today Because of (Describe QA and QC Deficiency item Description <b>issued today</b> ICY (Report QC and QA Deficiency items Description	f Storm; s issued) corrected) ere on site)	ecs Awaiting Awaiting			
CT-00192 CT-00193 SSUED QA/QC Item No No QC Deficie CORRECTED Q Item No No QC Deficie	QC Test QC Test DEFICIENCY Location ncy items were A/QC DEFICIEN Location	The Pipes in the concrete were pressur and Drawings. Tests were Good. SWPP was Performed today Because of (Describe QA and QC Deficiency item Description issued today ICY (Report QC and QA Deficiency items Description	f Storm; s issued) corrected)	ecs Awaiting			
CT-00192 CT-00193 SSUED QA/QC Item No No QC Deficie CORRECTED Q Item No No QC Deficie CONTRACTORS Name	QC Test QC Test DEFICIENCY Location ncy items were A/QC DEFICIEN Location ncy items were S ON SITE	The Pipes in the concrete were pressur and Drawings. Tests were Good. SWPP was Performed today Because of (Describe QA and QC Deficiency item Description issued today ICY (Report QC and QA Deficiency items Description corrected today (Report first and/or last day contractors we	f Storm; s issued) corrected) ere on site)	ecs Awaiting Awaiting			
CT-00192 CT-00193 SSUED QA/QC Item No No QC Deficie CORRECTED Q Item No No QC Deficie CONTRACTORS Name	QC Test QC Test DEFICIENCY Location ncy items were A/QC DEFICIEN Location ncy items were S ON SITE	The Pipes in the concrete were pressur and Drawings. Tests were Good. SWPP was Performed today Because of (Describe QA and QC Deficiency item Description issued today ICY (Report QC and QA Deficiency items Description	f Storm; s issued) corrected) ere on site)	ecs Awaiting Awaiting Last Day	Results		
CT-00192 CT-00193 SSUED QA/QC Item No No QC Deficie CORRECTED Q Item No No QC Deficie CONTRACTORS Name No Contractor	QC Test QC Test DEFICIENCY Location ncy items were A/QC DEFICIEN Location ncy items were S ON SITE	The Pipes in the concrete were pressur and Drawings. Tests were Good. SWPP was Performed today Because of (Describe QA and QC Deficiency item Description issued today ICY (Report QC and QA Deficiency items Description corrected today (Report first and/or last day contractors we	f Storm; s issued) corrected) ere on site)	ecs Awaiting Awaiting			
CT-00192 CT-00193 SSUED QA/QC Item No No QC Deficie CORRECTED Q Item No No QC Deficie CONTRACTORS Name No Contractor ABOR HOURS	QC Test QC Test DEFICIENCY Location ncy items were A/QC DEFICIEN Location ncy items were S ON SITE	The Pipes in the concrete were pressur and Drawings. Tests were Good. SWPP was Performed today Because of (Describe QA and QC Deficiency item Description issued today ICY (Report QC and QA Deficiency items Description corrected today (Report first and/or last day contractors we t or last day on the site	f Storm; s issued) corrected) ere on site)	ecs Awaiting Awaiting Last Day Number of	Results		
CT-00192 CT-00193 SSUED QA/QC Item No No QC Deficie CORRECTED Q Item No No QC Deficie CONTRACTORS Name No Contractor ABOR HOURS Employer	QC Test QC Test DEFICIENCY Location ncy items were A/QC DEFICIEN Location ncy items were S ON SITE	The Pipes in the concrete were pressur and Drawings. Tests were Good. SWPP was Performed today Because of (Describe QA and QC Deficiency item Description ICY (Report QC and QA Deficiency items Description corrected today (Report first and/or last day contractors we t or last day on the site Labor Classification	f Storm; s issued) corrected) ere on site)	ecs Awaiting Awaiting Last Day Number of Employees	Results		
CT-00192 CT-00193 SSUED QA/QC Item No No QC Deficie CORRECTED Q Item No No QC Deficie CONTRACTORS Name No Contractor ABOR HOURS Employer Ludlow Construc	QC Test QC Test DEFICIENCY Location ncy items were A/QC DEFICIEN Location ncy items were S ON SITE	The Pipes in the concrete were pressur and Drawings. Tests were Good. SWPP was Performed today Because of (Describe QA and QC Deficiency item Description ICY (Report QC and QA Deficiency items Description corrected today (Report first and/or last day contractors we t or last day on the site Labor Classification TRUCK DRIVER, GROUP 1	f Storm; s issued) corrected) ere on site)	Awaiting Awaiting Last Day Number of Employees 1.0	Results Hours Worked 8.0		
CT-00192 CT-00193 SSUED QA/QC Item No No QC Deficie CORRECTED Q Item No No QC Deficie CONTRACTORS Name No Contractor ABOR HOURS Employer Ludlow Construc Ludlow Construc	QC Test QC Test DEFICIENCY Location ncy items were A/QC DEFICIEN Location ncy items were S ON SITE s had their first tion Co., Inc. tion Co., Inc.	The Pipes in the concrete were pressur and Drawings. Tests were Good. SWPP was Performed today Because of (Describe QA and QC Deficiency item Description issued today ICY (Report QC and QA Deficiency items Description corrected today (Report first and/or last day contractors we t or last day on the site Labor Classification TRUCK DRIVER, GROUP 1 LABORER, GROUP 1	f Storm; s issued) corrected) ere on site)	Awaiting Awaiting Last Day Number of Employees 1.0 3.0	Results		
CT-00192 CT-00193 SSUED QA/QC Item No No QC Deficie CORRECTED Q Item No No QC Deficie CONTRACTORS Name No Contractor ABOR HOURS Employer Ludlow Construc Ludlow Construc	QC Test QC Test DEFICIENCY Location ncy items were A/QC DEFICIEN Location ncy items were S ON SITE tion Co., Inc. tion Co., Inc. tion Co., Inc. tion Co., Inc.	The Pipes in the concrete were pressur and Drawings. Tests were Good. SWPP was Performed today Because of (Describe QA and QC Deficiency item Description ICY (Report QC and QA Deficiency items Description corrected today (Report first and/or last day contractors we t or last day on the site Labor Classification TRUCK DRIVER, GROUP 1 LABORER, GROUP 1 CIRCULAR SAW OPERATOR	f Storm; s issued) corrected) ere on site)	Awaiting Awaiting Awaiting Last Day Number of Employees 1.0 3.0 0.0	Results Hours Worked 8.0 24.0 0.0		
CT-00192 CT-00193 SSUED QA/QC Item No No QC Deficie CORRECTED Q Item No No QC Deficie CONTRACTORS Name No Contractor ABOR HOURS Employer Ludlow Construc Ludlow Construc Ludlow Construc	QC Test QC Test DEFICIENCY Location A/QC DEFICIEN Location ncy items were S ON SITE TS had their first tion Co., Inc. tion Co., Inc. tion Co., Inc. tion Co., Inc.	The Pipes in the concrete were pressur and Drawings. Tests were Good. SWPP was Performed today Because of (Describe QA and QC Deficiency item Description issued today ICY (Report QC and QA Deficiency items Description corrected today (Report first and/or last day contractors we t or last day on the site Labor Classification TRUCK DRIVER, GROUP 1 LABORER, GROUP 1 CIRCULAR SAW OPERATOR PROJECT MANAGER	f Storm; s issued) corrected) ere on site)	Awaiting Awaiting Awaiting Last Day Number of Employees 1.0 3.0 0.0 0.0	Results Hours Worked 8.0 24.0 0.0 0.0		
CT-00192 CT-00193 SSUED QA/QC Item No No QC Deficie CORRECTED Q Item No No QC Deficie CONTRACTORS Name No Contractor ABOR HOURS Employer Ludlow Construc Ludlow Construc Ludlow Construc Ludlow Construc	QC Test QC Test DEFICIENCY Location ncy items were A/QC DEFICIEN Location ncy items were 5 ON SITE tion Co., Inc. tion Co., Inc. tion Co., Inc. tion Co., Inc. tion Co., Inc. tion Co., Inc.	The Pipes in the concrete were pressur and Drawings. Tests were Good. SWPP was Performed today Because of (Describe QA and QC Deficiency item Description issued today ICY (Report QC and QA Deficiency items Description corrected today (Report first and/or last day contractors we (Report first and/or last day contractors we t or last day on the site Labor Classification TRUCK DRIVER, GROUP 1 LABORER, GROUP 1 CIRCULAR SAW OPERATOR PROJECT MANAGER OPERATOR HEAVY EQUIPMENT 1	f Storm; s issued) corrected) ere on site)	Awaiting Awaiting Awaiting Last Day  Number of Employees  1.0 3.0 0.0 0.0 1.0	Results  Hours Worked  8.0  24.0  0.0  0.0  8.0		

PROJECT	OF CONSTRUCTION				e 3 of 3				
DAILY LOO ROJECT Durham Meadows Waterlin	OF CONSTRUCTION	CONTRACTORS QUALITY CONTROL REPORT (QCR)							
Durham Meadows Waterli		(4)	DATE						
Durham Meadows Waterli			05 Aug 2020	- Wednesday					
	PROJECT					CONTRACT NUMBER			
Total hrs worked to date:	Durham Meadows Waterline Remedial Design					W912WJ19C0002			
	24,120.5 Hrs wor	rked MTD:	376.0	Total:	7.0	56.0			
QUIPMENT HOURS									
Serial Number	Description				Idle Hours	Operating Hours			
L-20	L-20 Kumatsu Front End Load	der Billy			8.0	0.0			
TE-6 Ex	TE-6 Volvo Jon				8.0	0.0			
E-4 0336FCRAB	E-4 Cat 336 Track Hoe	Jon			8.0	0.0			
T-36		Jon			8.0	0.0			
E-20 ECR145DL,	E-20 Volvo Excavator E-20	Jon			8.0	0.0			
T-41	Ludlow Pressure Test Truck 1				8.0	0.0			
T-50	T-50 PU Jon	Entry			0.0	8.0			
T-77 PU		Billy			0.0	8.0			
E-9 Track Hoe		Billy			8.0	0.0			
T-64	Dump Truck T-64	Dilly			8.0	0.0			
B-5 Sweeper	B-5 Sweeper Bill	M			8.0	0.0			
R-4 Roller Billy	Roller Compacter	Billy			8.0	0.0			
TE 15 Excavator		illy			0.0	0.0			
T-84 PU	T-84 PU Billy	-			8.0	0.0			
T-78 PU	· · · · · · · · · · · · · · · · · · ·				8.0 8.0				
L-18 950					8.0 8.0	0.0			
R-18 Roller		on			8.0 8.0	0.0			
	· ·	Dilly				0.0			
D1 Cat		Billy			8.0	0.0			
T-86	T-86 Dump Truck	Billy			8.0	0.0			
T-21 Dump	T-21 Dump Jon				8.0	0.0			
R-17 Roller	R-17 Roller Billy				8.0	0.0			
T-59 Dump	T-59 Dump Billy				8.0	0.0			
TE-13 Excavator	TE-13 EX Billy				8.0	0.0			
Total operating hrs to date: 1	19,687.5 Idle hrs MTD:	420.0 Op	r hrs MTD: 140.0	Total:	160.0	16.0			
ISHAP REPORTING	(Describe mishaps)								
No mishaps reported today	,								