QUALITY ASSURANCE REPORT (QAR) DAILY LOG OF CONSTRUCTION											REPORT NUMBER 951				Page 1 of 0		
											DATE 26 Jul 2021 - Monday						
PROJECT											CONTRACT NUMBER						
Durham Meadows Waterline Remedial Design											W912WJ19C0002						
CONTRACTOR Ludlow Construction Co., Inc.											WEATHER Weather Caused No Delay Temperature Min 0 °F Max 0 °F No Precipitation No Wind						
PORTION OF SCHEDULED DAY SUITABLE FOR OPERATIONS											MPEF	RATURE			WIND		
STRUCTURAL EXCA- BORROW VATION		EXCA- EMBAI		KMENT	CONCRI	ETE STF		RUCTURE		MINIMUM		MAXIMUM					
	VATION 0 %	0 %		0 %	5	0 %		0 %			0 °F		0 °F		0 MPH		
		X NO					24 HOUR PRECIPITAT										
HAS ANYTH LEAD TO A		WHICH MIGHT					INCHES ENDING										
				YES (Explain)					0.00						М		
CLIDED///CODY			ER OF GOVERN			TOTAL	LABOR	DOD			RIVER STA						
SUPERVISORY	PERVISORY OFFICE		LAYOUT		INSPECTION			LABOR		FEET				TIME			
0	0		0		2		2		0	<u> </u>		0.0				M	
NUMBER SUPERVISORY	OF CONTRACTO	R'S EM LABOI		TOTAL		NUMBE FROM	R OF S		TER	1 ROM	X TO	2	FROM	3	то		
		LADO		1017.2					' ''				' ' ' '		'		
0	0 ch a list of the follo	wing (a	0	mo of ogu	0	<u> </u>	700	1530 M	or o	M nd alassificati	<u> </u>	M oontrooter r	oraani	M		М	
	E: if the contractor										OII OI	contractor p	ersoni	iei orisite.			
QA NARRAT	IVES																
Work Perforr	med Today:							Unres	olv	ed Issue: No)	Shif	t: 1				
Billys Crew 253 Main S 257 Main S VFDs are pi with the roo Results of Q Kurt Mintell Main Stree 1. Compone 2. Proper s 3. Well pum 4. PRV set s 5. Debris cl CTWATER issues. WILL FOLL Result of th meeting)	et interior plumbinents meet the Bo pacing of plumbing removed with at 60 PSI	urb stop of 1" co f 1' co g Hill F ing the und Tes ung Initia uy in Ai ing har electric c along an R. t dddletov	p to found opper pip pper piper Pump State compon sts, Defical al complete merica Angers - 27 cal wiring	dation co e, Encou e ution Build eents arou ciencies eted: .ct - YES 7 inches o g wire nut eentify iten s meet at	onnections ntered thing. A&F and inside Observer reviewed due to joist & tape -	ck foundar R Electric verthe pump d, Actions requirements spacing breaker tanch list The ay. bw to repair	vill be of station stations. Takent with good of eitems.	onsite to begin. n: Unresin Fazzino Plu, hangers had labeled appear appear the items or	umb bldin d.	ed Issue: No bing. g the coppe	obse Obseeplace	Shif 7" ervations th	nan ad	ctual			
1. PPE - go 2. Traffic pa 3. Working 4. Muddy & 4. Situation 5. Proper lif 6. COVID - 7. Concrete 8. Ladders 9. Safety M 10. DN - No	ections items: ood attern/control - 7 in excavation - 7 trip hazards - w al awareness wl fting techniques no discussion to a placement toda in the trench - a: eeting to review oted fencing surr r onsite - workin	Frenchi rhile tre rile wo - lift wit oday ay - NO s need bad w roundin g at 20	ing for exenching a rking aro th knees NE ed - note eather program the tar	etterior 1" and working and heave not low be ad lack of rotocols v nk, section 216 Main	pipe from ng around yy equipm pack ladders w while work ns have fa n Street - I	curb stop I tight qual lent. Exca while trencl king allen down	to hourters vating ning ar	for trench before trench for tren	nini 1.5" uest	excavator copper pipe ed SSHO &	e at 1	196 Main e Pio repai		P	Y		
QA REPRESENTAT	ΓΙVE'S SIGNATŪR	E		D	ATE			RE/PRO	JEC	t engr's in	ITIĀĒ	.S		DATE			