QUALITY ASSURANCE REPORT (QAR)							REPORT NUMBER 583				Page 1 of 0							
DAILY LOG OF CONSTRUCTION								DATE 23 Jul 2020 - Thursday										
PROJECT Durham Mea	adows	Waterline	Reme	dial Desig	n							CONTRAC W912V		IBER				
Durham Meadows Waterline Remedial Design CONTRACTOR						WEATHER												
Ludlow Const	ruction	Co., Inc.										Tempe	rature N	ed No Delay ⁄lin 78 °F M n No Wind		Ϋ́F		
	PO	RTION OF S	CHEDU	ILED DAY	SUITABLE	FOR OP	ERATIO	NS				Т	EMPEF	RATURE			WIND	
STRUCTURAL EX		BORROW EX VATION		EMBANK		CONCR			RUC	TURE		MINIMUM		MAXIMUM				
	0 %		0 %		0 %		0	%			0 %		78 °F		92 °F		0 N	1PH
		DEVELOPED				IGHT	Х	NO				INCHES		24 HOUR P		ENDING		
LEAD TO A	A CHAI	NGE ORDER	R OR FI	NDING FC	FACT?			YES (Exp	lain)				0.00		2.12.10		М
		NUMB	ER OF	GOVERN	IENT EMP	LOYEES								RIVE	R STA	GE		
SUPERVISORY	OFF	ICE	LAYO	UT	INSPECT	ION	TOTAL		L	ABOR		FEET				TIME		
1		0		0		1		:	2		0			0.0				М
		CONTRACTO					-	BER O			155	1	X	2		3	-	
SUPERVISORY	SKIL	LED	LABO	RERS	TOTAL		FROM		ТО)	FR	OM	то		FROM	1	то	
0		0		0		0		0700		1530			М	М		М		М
Att. NC	ach a li)TE: if t	ist of the follo the contractor	wing. (a r's Qual	a) Major ite ity Control	ms of equi Report (Q	pment eitl CR) conta	her idle o ins the ir	r workin nformatio	ng, a on it	nd (b) Num need not b	iber ai ie repe	nd classifica eated.	ation of	contractor p	ersonn	iel onsite.		
QA NARRA	TIVES	S																
Work Perfo	rmed	Today:								Unre	esolve	ed Issue: I	No	Shif	t: 1			
Kurt Minte On 17:	ell																	
Install curl	b stop	s to busines	sses:															
Tank Site:																		
Crew onsi	te forn	ning up the	footing	g - installi	ng plywoo	od forms	and bra	acing, #	‡4 re	ebar bend	s aro	und the pe	erimete	er				
Maiden La	ane:																	
		at the intersonent over to						for the	e Ma	aiden Lane	e Stre	am crossi	ing.					
QTYS:																		
MAIDEN L	ANE																	
		OF 12 INCH 8 INCH TR					TA 410	+47										
15: 1 12X	12X8 ⁻	TEE: STA 4	10+47															
		GATE VALV ATE VALVE			0.5 AND 4	410+43												
26: I FIRE	E HYD	RANT ASS	EMBL	Y: BRICK					•									
		C YARDS C			GRAVEL (174.5X3	6.5X2) (3	38X3X2	2)									
17: 0030: 1" C	Corps =	= 2 @177+^	11 (31:	3 Main) &	178+56 (307 Mai	n)											
0031: 1" 0	Curb S	tops = 2		, .			,											
		r Pipe = 134 Piercing = 1																
0054 Roc	k & bo	oulder excav	ation =	= 14.89														
0061: Sav		tate =104.0		and loot	ruotiono	Civen				Llor		ed Issue: I	No	Shif	+· 1			
										Unite	esolve	ed issue. I	NO	Shii	ι. Ι			
meet the s	e testi spec o	reparatory I ing lab for concrete	oncrete	e - this m	ay not be	USACE	Certifie	d- QCN ave Ai	/I wa iudi	as notified that IMTL	l that is no	if not certi t USACE	ified the	e testing la ved THIS I	ab wou TEM I	uld not S		
CLOSED. Verbal Instr		ns Given to	o Cont	ractor:						Unre	esolve	ed Issue: I	No	Shif	t: 1			
Kurt Minte	ell																	
Notified Jo	on Pio	ional tank d of the prop n prior to wo	erty pi	n located	at the Ma	ple Stre	et strea		sing	and to be	e cau	tions while	e worki	ng around	. He w	vill take		
Miscellaneo			-		-	- Criteriuy	moved			Unre	esolve	ed Issue: I	No	Shif	t: 2			

Kurt Mintell Noted damaged curb on Pickett under guardrail from stream c	rossing - KEEP OPEN	
Miscellaneous Remarks and Visitors to Project:	Unresolved Issue: No	Shift: 1
Kurt Mintell Left a paint mark for Armand to see (proposed water into basement) (147 Ma conversation- the CBYD the utilities are actually on the lot next door not on h OPEN		
DOT Correspondence - SW on meeting - shimming on 17 brought up		
Miscellaneous Remarks and Visitors to Project:	Unresolved Issue: No	Shift: 1
Kurt Mintell Joel - AECOM onsite		
Safety:	Unresolved Issue: No	Shift: 1
Kurt Mintell Email to SSHO (Rob P.) to ensure proper COVID 19 steps are being taken - town- cc ed Mike Pio on the email.	especially with the Tank Crew since	e they are form out of
Noted Traffic Control:		
1. on 17 1 certified flagger & 1 CSP. 2. Pickett Lane - 1 Certified flagger by Maiden Lane.		
PPE & Trench Box:		

- trench boxes being used on 17 & the stream crossing
 PPE noted
 Hot temperature discussion staying hydrated reviewed.

Tank Site:

- Electrical cords inspected GOOD
 PPE GOOD
 COVID Awareness GOOD
 Safety Board GOOD

QA REPRESENTATIVE'S SIGNATURE	DATE	RE/PROJECT ENGR'S INITIALS	DATE