QUALITY ASSURANCE REPORT (QAR) DAILY LOG OF CONSTRUCTION											REPORT 596 DATE			Pag	Page 1 of 0	
PROJECT												05 Aug 2020 - Wednesday CONTRACT NUMBER				
Durham Meadows Waterline Remedial Design												W912WJ19C0002				
CONTRACTOR Ludlow Construction Co., Inc.												WEATHER Weather Caused Non-Critical Delay Temperature Min 0 °F Max 0 °F No Precipitation No Wind				
PORTION OF SCHEDULED DAY SUITABLE FOR OPERATIONS												TEMPERATURE WIND				
STRUCTURAL EXCA- VATION BORROW EXCA- VATION 0 % 0 %				EMBANKMENT CONCR			ETE STRUCTURE			0 %	MINIMUM MAXIMUM 0 °F 0 °F			0 MPH		
1							[X]	NO					24 HOUR PREC	PITATION		
HAS ANYTI LEAD TO A		IGHT		YES (E	xplain)		INCHES		0.00	ENDING	М					
		UMBI			IENT EMPLOYEES						RIVER STAGE					
SUPERVISORY	OFFICE	FICE LAYO		UT INSPECT		TOTAL			LABOR		FEET			TIME		
0		0		0		1		1		0	<u></u>		0.0		М	
NUMBER SUPERVISORY	OF CONTRA	ACTO	R'S EM LABOI		TOTAL		NUMBI FROM		SHIFTS TO	TER	1 ROM	ТО] 2 FRC	3	ТО	
	SKILLLD		LADOI		TOTAL						COIVI					
0	ch a list of the	0 follo	wing (s	0 Major ita	ms of oqui	0 nmont oith	<u>'</u>	700		Number a	nd classific	M of	M	M nol onsito	M	
Attach a list of the following. (a) Major items of equipment either idle or working, and (b) Number and classification of contractor personnel onsite. NOTE: if the contractor's Quality Control Report (QCR) contains the information it need not be repeated.																
1	QA NARRATIVES Work Performed Today: Unresolved Issue: No Shift: 1															
Kurt Mintell Only work at the tank site today due to Durham directing the contractor not to work on Durham because of power outages and wires down.																
2 Ludlow workers prep the pipe stubs (3) in the bottom of the tank and conducted pressure testing. Middletown water onsite to over see the testing - all 3 pipes passed - 1hour @ 100 PSI																
DN Tank is working on the forms for the pre- cast panels of the tank - noted brown sand spread inside the forms and tamped uniformly in place Results of QA Inspections and Tests. Deficiencies Observed. Actions Taken: Unresolved Issue: No. Shift: 1																
Results of QA Inspections and Tests, Deficiencies Observed, Actions Taken: Unresolved Issue: No Shift: 1 Kurt Mintell Pressure test of the 3 pipe stubs in the bottom of the tank 100 PSI for 1 hour - Joe form Middletown, Jerry Ludlow QCM and myself witnessed the testing																
QA REPRESENTA	TIVE'S SIGNA	ATUR	E		DA	TE			RE	/PROJEC	T ENGR'S	INITIAL	S	DATE		