

PLAN
SCALE: 1" = 50'

GENERAL NOTES:

1. Soundings are in feet and tenths and refer to the plane of Mean Lower Low Water (MLLW) 1983-2001 Tidal Epoch.
2. Topography shown is from previous surveys and/or NOAA Chart No. 13286. All topography, including shoreline, bridges, piers, etc., is located approximate unless otherwise noted and should be used as a general reference only.
3. Bench Mark Data: TBM PERK (2005) is a chiseled square with a 1/4" drill hole in corner of the concrete wall with metal rail located at the northwest side of The Harbormaster's Shed on the north side of Perkins Cove.
Elevation is 15.46 feet above MLLW.
4. Coordinates shown are based on the Transverse Mercator Grid System for the State of Maine (West Zone 1802) & NAD 1983.
5. Survey was performed using an Odom MK2 echotrac echosounder. Vessel positioning was obtained utilizing a trimble 4000 SSE GPS Receiver with the U.S.Coast Guard Beacon System.
6. The sounding information shown on this map represents the SHOALEST soundings of those obtained from hydrographic surveys conducted during July 2006.
7. The sounding information depicted on this map should NOT be used to determine volumes. Volumes are determined from more sounding information than shown. Additional sounding information is available upon request.
8. The information depicted on this map represents the results of surveys made on the dates indicated, and can only be considered as indicating the general conditions existing at that time.
9. Field Book: R&H 4474
Depthsounder Roll: 06-833/01
Surveyed by: P.K.O'Brien and Crew

US Army Corps of Engineers® New England District

MARK	DESCRIPTION	DATE	APPR.

MARK	DESCRIPTION	DATE	APPR.

REVIEWED BY: Asst. Chief, Survey Section
SUBMITTED BY: Chief, Survey Section
DATE: 5/15/2008
DWN BY: VJG
CKD BY: SWK
DESIGNED BY: VJG
CONTROL FILE: JOSIASPS.DGN
PLOT SCALE: 1" = 50'
PLOT DATE: 4/25/2008
DRAWING CODE: 2848
DIST: FILE CODE: ANSI F
FILE NAME: JOSIASMAY101.S01

U.S. ARMY CORPS OF ENGINEERS
NEW ENGLAND DISTRICT
CONCORD, MASSACHUSETTS
www.nae.usace.army.mil

JOSIAS RIVER
OGUNQUIT, MAINE
CONDITION SURVEY
7-FOOT CHANNEL
5 AND 7-FOOT ANCHORAGES

SHEET IDENTIFICATION
V-101
SHEET 1 OF 1

SCANNED RECORD
APR-2008